



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Make	Model	Total Meter	Color Meter	DF	Fax	Prt	Scan	Fin	PFU	LCT	EC	IC	Notes	SN	Loc
Brother	HLL6400DW	7605	0	X	X	PCL/PS			PFU1		2	2		U64185K8N319330	TX
Brother	HLL6400DW	23514	0	X	X	PCL/PS			PFU1		2	2		U64185K8N319366	TX
Brother	HLL6400DW	34059	0	X		PCL/PS			PFU1		2	2		U64186A1N284459	TX
Brother	HLL6400DW	36149	0	X		PCL/PS			PFU1		2	2		U64186A1N284450	TX
Brother	HL-L6400DW	23007	0			PCL/PS			PFU1		2	2		U64185K9N687004	TX
Brother	HL-L6400DW	148613	0			PCL/PS			PFU1		2	2		U64185K9N687015	TX
Brother	HL-L6400DW	165165	0			PCL/PS			PFU1		2	2		U64185K9N687018	TX
Brother	HLL9310CDW	21957	19954	X	X	PCL/PS	X		PFU1		2	2		U64644E8J198054	TX
Brother	HL-L9310CDW	15437	0			PCL/PS			PFU2		2	2		U64644A0F320485	TX
Brother	MFC-L9570CDW	70943	8458	X	X	PCL/PS	X		PFU1		2	2		U64647L9J466809	MN
Canon	ImagePres s C700	2274233	1512343	X		Canon VHE- CTRL- MB950	X	AM2	PFU3	B1	2	2		UME03177	MN
Canon	IRA DX-4735i	258413	0	X	X	PCL/PS	X		PFU4		2	2	Main unit needs to be updated	4AQ02807	TX
Canon	IRA DX-4745i	101842	0	X	X	UFR II/PCL/ PS	X	Internal	PFU4		2	2		25J06426	MN
Canon	IRA DX-C257if	1238	66	X	X	PCL/PS	X		Cab2		2	2		3CE14416	TX
Canon	IRA DX-C257if	44708	35339	X	X	UFR ii/PCL/PS	X		Cab2		2	2		3CE02279	MN
Canon	IRA DX-C357IF	76722	44737	X	X	PCL/PS	X		Cab2		2	2		2UL01743	MN
Canon	IRA DX-C3725i	64079	31371	X	X	UFR II/PCL/ PS	X		Cab2		2	2	Missing Finisher	2UA12036	MN
Canon	IRA DX-C5735i	186101	80222	X		UFR ii/PCL/PS	X	Internal	PFU4		2	2		3BN01515	MN
Canon	IRA DX-C5735i	223499	167471	X		UFR ii/PCL/PS	X	Internal	PFU4		2	2		3BN01744	MN
Canon	IRA DX-C5740i	153545	114714	X		UFR ii/PCL/PS	X	Internal	PFU4		2	2		3BB04588	MN
Canon	IRA DX-C5740i	196755	88448	X		UFR ii/PCL/PS	X	Internal	PFU4		2	2		3BB04456	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Canon	IRA DX-C5740i	460791	357742	X		UFR ii/PCL/PS	X	Internal	PFU4		2	2		3BB04371	MN
Canon	IRA DX-C5750i	234501	183686	X		UFR ii/PCL/PS	X	Internal	PFU4		2	2		3AP02299	MN
Canon	IRA DX-C5750i	340749	269407	X		UFR ii/PCL/PS	X	Internal	PFU4		2	2		3AP02422	MN
Canon	IRA DX-C5750i	446480	187212	X		UFR ii/PCL/PS	X	Y1	PFU4	F1	2	2		3A902212	MN
Canon	IRA-4035	233089	0	X	X	UFR II	X	Internal	PFU4		2	2		HRT00641	MN
Canon	IRA-4535i	952183	0	X	X	UFR II/PCL/PS	X	Internal	Cab2		2	2		UMU08750	MN
Canon	IRA-4535i III	14705	0	X	X	UFR II/PCL/PS	X		PFU4		2	2		2RK07710	TX
Canon	IRA-4551i III	189465	0	X	X	UFR II/CPL/PS	X	Staple Finsih Y1	PFU3		2	2		2ND03860	TX
Canon	IRA-525iF III	12472	0	X	X	UFR II/PCL/PS	X		PFU1		2	2		2WQ04931	TX
Canon	IRA-525iF III	39450	0	X	X	UFR II/PCL/PS	X		PFU1		2	2		2WQ04930	TX
Canon	IRA-525iF III	104663	0	X	X	UFR II/PCL/PS	X		Cab2		2	2		2WQ04936	TX
Canon	IRA-525iF III	122158	0	X	X	UFR II/PCL/PS	X		Cab2		2	2		2WQ05055	TX
Canon	IRA-525iF III	137841	0	X	X	UFR II/PCL/PS	X		PFU1		2	2		2WQ04943	TX
Canon	IRA-525iF III	141231	0	X	X	UFR II/PCL/PS	X		Cab2		2	2		2WQ04971	TX
Canon	IRA-525iF III	166208	0	X	X	PCL/PS	X		Cab2		2	2		2WQ04953	TX
Canon	IRA-525iFII	66162	0	X	X	UFR II/PCL/PS	X		PFU1		2	2		2CK03153	MN
Canon	IRA-6555i III	495095	0	X	X	UFR ii/PCL/PS	X	V1	PFU4		2	2		SKA06952	MN
Canon	IRA-C257if	13486	3499	X	X	PCL/PS	X		Cab2		2	2		3CE05311	TX
Canon	IRA-C257if	87540	44239	X	X	UFR II/PCL/PS	X		PFU1		2	2		3CE05726	TX
Canon	IRA-C3330i	95215	12191	X	X	PCL/PS	X		PFU4		2	2		QTV07118	TX
Canon	IRA-C350iF	527694	52110	X	X	UFR II/PCL/PS	X		PFU4		2	2		QNN11916	MN
Canon	IRA-C3525i II	80416	30277	X	X	UFR II/PCL/PS	X		PFU4		2	2		XTK08804	TX
Canon	IRA-C3525i II	141093	13105	X	X	UFR II/PCL/PS	X		Cab2		2	2		XTK13248	TX
Canon	IRA-C3525i II	306977	168708	X		ufrii/pcl/ps	X	Internal	PFU4		2	2		XTK06635	MN
Canon	IRA-C3525i II	510388	176395	X	X	UFR II/PCL/PS	X	AA1	PFU4		2	2	Missing all toner	XTK13249	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Canon	IRA-C3525i III	29877	10087	X	X	UFR ii/PCL/PS	X		PFU4		2	2		2GH01114	MN
Canon	IRA-C3525i III	226905	173072	X	X	UFRii/PCL/ PS	X		Cab2		2	2		2GH11965	TX
Canon	IRA-C3530i	277437	4133	X		ufrii/pcl/ps	X		Cab2		2	2		WSB02141	MN
Canon	IRA-C3530i III	173113	77613	X	X	UFRii/PCL/ PS	X		Cab2		2	2		2GU03321	MN
Canon	IRA-C356iF III	77717	25618	X	X	UFRii/PCL/ PS	X		Cab2		2	2		2QC04980	TX
Canon	IRA-C356iF III	103548	33865	X	X	UFRii/PCL/ PS	X		Cab2		2	2		2QC04983	TX
Canon	IRA-C356iF III	179223	9702	X	X	UFRii/PCL/ PS	X		Cab2		2	2		2NH01723	TX
Canon	IRA-C475iF III	36360	5865	X	X	ufrii/pcl/ps	X		PFU4		2	2		2HF01274	MN
Canon	IRA-C5250	268083	167223	X	X	UFRii/PCL/ PS	X	Internal	PFU4		2	2		JMQ18293	MN
Canon	IRA-C5250	300861	169784	X	X	UFRii/PCL	X	J1	PFU4		2	2		JMQ27056	MN
Canon	IRA-C5250	369622	121939	X	X	UFRii/PCL	X	J1	PFU4		2	2	B2 Puncher	JMQ27047	MN
Canon	IRA-C5250	747174	230321	X	X	UFRii/PCL	X	J1	PFU4		2	2		JMQ27052	MN
Canon	IRA-C5250	801554	179867	X	X	UFRii/PCL	X	J1	PFU4		2	2	B2 Puncher	JMQ03286	MN
Canon	IRA-C5250	1070104	246260	X	X	UFRii	X	Internal	PFU4		2	2		JMQ23296	MN
Canon	IRA-C5250	1213284	343024	X	X	UFRii	X	Internal	PFU4		2	2		JMQ14082	MN
Canon	IRA-C5535i	33945	31345	X		PCL/PS	X		PFU4		2	2		2KK06826	TX
Canon	IRA-C5535i	539728	260807	X	X	UFR ii/PCL/PS	X	Internal	PFU4		2	2		WXF06754	MN
Canon	IRA-C5535i II	371987	160457	X	X	UFRii/PCL/ PS	X		PFU4		2	2		XUW12896	TX
Canon	IRA-C5535i II	373175	103946	X	X	UFRii/PCL/ PS	X		PFU4		2	2		XUW10697	MN
Canon	IRA-C5535i II	947995	542953	X		ufrii/pcl/ps	X	Internal	PFU4		2	2		XUW06474	MN
Canon	IRA-C5535i III	257430	119533	X		PCL/PS	X		PFU4		2	2		2KK04779	TX
Canon	IRA-C5540i	358406	55248	X	X	UFRii/PCL/ PS	X		PFU4		2	2		XLJ00946	TX
Canon	IRA-C5540i III	84981	20757	X	X	ufrii/pcl/ps	X	Internal	PFU4		2	2		2JU07655	MN
Canon	IRA-C5540i III	203313	58462	X		PCL/PS	X		PFU3		2	2		2JU07715	TX
Canon	IRA-C5550i	162217	329	X		PCL/PS	X		PFU4		2	2		XLG06329	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Canon	IRA-C5550i	476551	101972	X	X	UFRII/PCL/PS	X		PFU4		2	2		WXD08077	MN
Canon	IRA-C5550i III	190567	105336	X	X	UFRII/PCL/PS	X		Cab2		2	2		2JG06458	MN
Canon	IRA-C5560i II	306402	52959	X		UFR ii/PCL/PS	X	Y1	PFU3		2	2		XTZ03283	MN
Canon	IRA-C7565i III	651390	48709	X		UFR ii/PCL/PS	X	V2	PFU4		2	2	Buffer Pass Unit M1	2KT04193	MN
Canon	IRA-C7565i III	662859	47234	X		ufrii/pcl/ps	X	V2	PFU4		2	2	M1	2KT04195	MN
Canon	IRA-C7565i III	717588	66163	X		ufrii/pcl/ps	X	V2	PFU4		2	2	M1	2KT04192	MN
Canon	IRA-DXC257if	31948	16212	X	X	ufrii/pcl/ps	X		PFU2		2	2		3CE02574	MN
Canon	IRA-DXC3730i	377426	64620	X		UFR ii/PCL/PS	X	Internal	PFU4		2	2		2UR05077	MN
Canon	M3250	5460	0			PCL/PS			PFU1		2	2		4600824007CK1	TX
Canon	Pro-4000	248	0			-					2	2	B/W and color counts combined. 248 sqft. 1x 36in roll.	BAGA02795	MN
Copystar	CS-308ci	58994	19189	X		PCL/PS	X		Cab2		2	2		RNH9800003	TX
Copystar	CS-3253ci	299170	112320	X		KPDL/PCL	X		PFU4		2	2		RH49Y01432	TX
Copystar	CS-3253ci	364956	277307	X		KPDL/PCL	X		Cab2		2	2		RH49601072	TX
Copystar	CS-5053ci	170437	26588	X	X	pcl/kpdl	X	Internal	PFU4		2	2		RH19701065	MN
Copystar	CS-5053ci	1372204	447912	X		KPDL/PCL	X		PFU4		2	2		RH10X01904	TX
Heidelberg	Versafire	3764035	3178707			Heidelberg Prinect DFE		SR5110	PFU2	RT5120	2	2	Buffer Pass Unit Type S9, ProC7210X on s/n sticker	Y999LCA0001	MN
HP	4250N	238282	0			pcl/ps			PFU1		2	2		CNGXC48303	MN
HP	E40040	632	0	X		PCL/PS	X		PFU1		2	2		PHBCG51351	TX
HP	E50145	3223	0			PCL/PS			PFU1		2	2		PHBCM9F1R2	MN
HP	E50145	4956	0			PCL/PS			PFU1		2	2		PHBCM9F1NY	MN
HP	E50145	5459	0			PCL/PS			PFU1		2	2		PHBCM9F1PC	MN
HP	E50145	10687	0			PCL/PS			PFU1		2	2		VNCCS3703G	MN
HP	E50145	14003	0			PCL/PS			PFU1		2	2		PHBCM9F1PJ	MN
HP	E50145	14434	0	X		PCL/PS			PFU1		2	2		PHBCN1P5KT	TX
HP	E50145	18919	0			pcl/ps			PFU2		2	2		PHCCNB81K7	MN
HP	E50145	19384	0			pcl/ps			PFU1		2	2		PHCCNB81KX	MN
HP	E50145	23136	0	X		PCL/PS			PFU1		2	2		PHBCN1P5LX	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

HP	E50145	32427	0			pcl/ps			PFU1		2	2		PHCCNB81KK	MN
HP	E50145	33682	0			PCL/PS			PFU2		2	2		PHCCNB81L2	MN
HP	E50145	33724	0			pcl/ps			PFU1		2	2		PHBCM5R12J	MN
HP	E50145	36706	0			PCL/PS			PFU1		2	2		PHBCM9F1QN	MN
HP	E50145	41259	0	X		PCL/PS			PFU2		2	2		PHBCN1P5KZ	TX
HP	E50145	45860	0			PCL/PS			PFU1		2	2		PHBCM9F1R7	MN
HP	E50145	47296	0			PCL/PS			PFU1		2	2		PHBCM9F1RM	MN
HP	E50145	47530	0	X		PCL/PS			PFU2		2	2		PHBCN1P5JQ	TX
HP	E50145	57019	0			PCL/PS			PFU1		2	2		PHCCNB81LV	MN
HP	E50145	58415	0			PCL/PS			PFU1		2	2		PHBCM9F1XB	MN
HP	E50145	71756	0	X		PCL/PS			PFU2		2	2		PHBCN1P5M4	TX
HP	E50145	72938	0			PCL/PS			PFU1		2	2		PHBCM9F1Q0	MN
HP	E50145	89533	0			pcl/ps			PFU2		2	2		PHCCNB81L1	MN
HP	E50145	90617	0	X		PCL/PS			PFU2		2	2		PHBCN1P5HR	TX
HP	E50145	91483	0			pcl/ps			PFU1		2	2		PHBCM5R0ZB	MN
HP	E50145	96274	0	X		pcl/ps	X		PFU1		2	2		PHCCNB81K3	MN
HP	E50145	112682	0			PCL/PS			PFU1		2	2		PHBCM9F1QM	MN
HP	E50145	119963	0			pcl/ps			PFU2		2	2		PHCCNB81KM	MN
HP	E50145	129678	0			PCL/PS			PFU1		2	2		PHBCM9F1RQ	MN
HP	E50145	165595	0			PCL/PS			PFU1		2	2		PHBCM9F1R6	MN
HP	E50145	220125	0			PCL/PS			PFU1		2	2		PHBCM9F1QH	MN
HP	E50145	354113	0			PCL/PS			PFU1		2	2		PHBCM9F1SM	MN
HP	E52645	42434	0	X		PCL/PS	X		PFU1		2	2		MXBCMBR1QJ	TX
HP	E52645	48944	0	X	X	PCL/PS	X		PFU1		2	2		MXBCMBR1QN	TX
HP	E52645	84764	0	X	X	pcl/ps	X		Cab2		2	2		MXBCNCS2FS	MN
HP	E52645	90188	0	X		PCL/PS	X		Cab3		2	2		MXBCNCS24T	MN
HP	E52645	230265	0	X	X	PCL/PS	X		PFU1		2	2		MXBCMBR2NH	TX
HP	E52645	278978	0	X		PCL/PS	X		Cab2		2	2		MXBCMBR1Q8	TX
HP	E55040	883	829	X		PCL/PS	X		PFU2		2	2		JPBCN7Z29C	TX
HP	E55040	240787	215517			PCL/PS			PFU1		2	2		JPBCMBR3MV	TX
HP	E60055	48087	0			PCL/PS			PFU1		2	2		CNMCLBG146	MN
HP	E60055	117511	0			PCL/PS			PFU2		2	2		CNMCL6S1LL	TX
HP	E60055	150848	0			PCL/PS			PFU1		2	2		CNMCLBG15T	MN
HP	E60055	170684	0			PCL/PS			PFU1		2	2		CNMCLBG16T	MN
HP	E60055	303705	0			PCL/PS			PFU1		2	2		CNMCLBG16R	MN
HP	E60055	675656	0			PCL/PS			PFU1		2	2		CNMCLBG16B	MN
HP	E60055	741265	0			PCL/PS			PFU1		2	2		CNMCLBG14D	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

HP	E78325	250881	88077	X		pcl/ps	X		PFU4		2	2		CNB3NCVXCS	MN
HP	E78325	366730	125912	X		pcl/ps	X		Cab2		2	2		CNB3NCVXB	MN
HP	E78330	63305	48892	X		PCL/PS	X		Cab2		2	2		CNB3P1C8GB	TX
HP	E78330	122250	69918	X		PCL/PS	X		PFU4		2	2		CNB1P987G5	TX
HP	E82540	4547	0	X		PCL/PS	X	Internal	PFU4		2	2		CNC1P9604L	MN
HP	E82540	8558	0	X		PCL/PS	X	Internal	PFU3		2	2		CNC1P9605N	MN
HP	E82540	21093	0	X		PCL/PS	X	Internal	PFU3		2	2		CNC1P9603X	MN
HP	E82540	32347	0	X		PCL/PS	X	Internal	PFU3		2	2		CNC1P96055	MN
HP	E82540	41021	0	X		PCL/PS	X	Internal	PFU3		2	2		CNC1P9604M	MN
HP	E82540	52106	0	X		PCL/PS	X	Internal	PFU3		2	2		CNC1P96054	MN
HP	E82540	60695	0	X		pcl/ps	X	Internal	PFU3		2	2		CNC1P8Q045	MN
HP	E82540	63619	0	X		pcl/ps	X	Internal	PFU3		2	2		CNC1P8Q044	MN
HP	E82540	65573	0	X		pcl/ps	X	Internal	PFU3		2	2		CNC1P8Q042	MN
HP	E82540	85705	0	X		pcl/ps	X	Internal	PFU3		2	2		CNC1P7W00W	MN
HP	E82540	135375	0	X		PCL/PS	X	Internal	PFU3		2	2		CNC1P8Q040	MN
HP	E82540	143295	0	X		PCL/PS	X	Internal	PFU3		2	2		CNC1P5T00R	MN
HP	E82540	153808	0	X		pcl/ps	X	Internal	PFU3		2	2		CNC1P96048	MN
HP	E82540	172600	0	X		PCL/PS	X	Internal	PFU3		2	2		CNC1P9604K	MN
HP	E82540	188927	0	X		PCL/PS	X	Internal	PFU3		2	2		CNC1P96045	MN
HP	E87640	56941	39962	X	X	PCL/PS	X		PFU4		2	2		CNC1Q2N056	TX
HP	E87650	162694	102242	X	X	PCL/PS	X		PFU4		2	2		CNC1PB803F	TX
HP	M401dne	29673	0			pcl/ps			PFU1		2	2		PHGFD01528	MN
HP	M401dne	32545	0			pcl/ps			PFU1		2	2		PHGFD01532	MN
HP	M402DN	8093	0			PCL/PS			PFU1		2	2		PHBQF41097	MN
HP	M402DN	46567	0			PCL/PS			PFU1		2	2		PHBQF41093	MN
HP	M402DN	89416	0			PCL/PS			PFU1		2	2		PHBQF41224	MN
HP	M402dne	1584	0			PCL/PS			PFU1		2	2		PHB5C04993	TX
HP	M402dne	46463	0			PCL/PS			PFU1		2	2		PHB5B27398	MN
HP	M404dn	3956	0			PCL/PS			PFU2		2	2		VNG3B29628	TX
HP	M425DN		0	X	X	pcl/ps	X		PFU1		2	2		CND8FCX4SQ	MN
HP	M451DN	75877	53442			PCL/PS			PFU1		2	2	Phantom Jam	CNBH200044	MN
HP	M501	10508	0			PCL/PS			PFU1		2	2		PHBTR93111	TX
HP	M501	29469	0			PCL/PS			PFU1		2	2		PHBTR93112	TX
HP	M501	32738	0			PCL/PS			PFU1		2	2		PHBTR93115	TX
HP	M501	60098	0			PCL/PS			PFU1		2	2		PHBTR99652	TX
HP	M521dn	51691	0	X	X	PCL/PS	X		PFU2		2	2		CNDKMC71BZ	TX
HP	M521dn	107135	0	X		PCL/PS	X		PFU1		2	2		CNDKN4R9FN	TX
HP	M521dn	240363	0	X	X	PCL/PS	X		PFU1		2	2		CNDKMC71Q5	TX
HP	M525	236588	0	X	X	PCL/PS	X		PFU1		2	2	Cannot Confirm COO, Sticker Removed	MXECG4J0D4	MN
HP	M570DN	73714	48090	X		PCL/PS	X		PFU1		2	2		CNCKN7H4WZ	TX
HP	M570DN	86688	55790	X	X	pcl/ps	X		PFU1		2	2		CNCKN3Z5ZK	MN
HP	M605	2670	0	X		PCL/PS			PFU2		2	2		CNDCJB61QN	TX
HP	M605	4845	0	X		PCL/PS			PFU2		2	2		CNDCJB61QG	TX
HP	M605	6227	0	X		PCL/PS			PFU1		2	2		CNDCJB61Q0	TX
HP	M605	7194	0	X		PCL/PS			PFU2		2	2		CNDCJB61Q3	TX
HP	M605	14854	0	X		PCL/PS			PFU2		2	2		CNDCJB61QC	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

HP	M605	17631	0	X		PCL/PS			PFU2		2	2		CNDCJB61Q8	TX
HP	M605	20915	0	X		PCL/PS			PFU2		2	2		CNDCJB61QL	TX
HP	M605	35350	0			PCL/PS			PFU2		2	2		CNDCJB61PP	TX
HP	M605	58996	0	X		PCL/PS			PFU1		2	2		CNDCJB61Q6	TX
HP	P3015	157090	0			PCL/PS			PFU1		2	2		VND3F47700	MN
HP	T2600dr	1049	0	X		PCL/PS	X		PFU1		2	2	meter count is in meters squared.	CN03C5H01B	TX
HP	T830		0			-	X				2	2	No wheels attached. Paper won't cut. 1x 36in roll. Passes paper but can't retrieve count.	CN99H7M02H	MN
HP	X55745	10084	6757			PCL/PS			PFU1		2	2		JPBCR51070	TX
Kon/Min	AccurioPre ss6136P	5283008	0			PCL/PS		FS-532	PFU2	PF-710	2	2	RU-510, SD 506	A9JW011000332	MN
Kon/Min	AccurioPre ssC3080	29671	26158	X		FIERY E400-05	X	FS-532	PFU2	PF-707m	2	2	SD-513 RU-518 SD-513/F	A9VE011001381	TX
Kon/Min	AccurioPre ssC3080	913384	699369	X		FIERY E400-05	X	FS-532	PFU3	PF-709	2	2		A9VE011000624	TX
Kon/Min	AccurioPre ssC6085	2126030	1913935	X		Fiery NX Pro-13		FS-532	PFU3	PF-707m	2	2	IQ-501 RU-518	A92Y011000694	TX
Kon/Min	AccurioPri ntC3070L	666274	504963	X		pcl/ps	X	FS-612	PFU3		2	2	Internal fiery.	AAC4011000908	MN
Kon/Min	AccurioPri ntC3070L	4361160	2859669	X		FIERY E400-05	X	FS-612	PFU2	LU-202m	2	2		AAC4011001200	TX
Kon/Min	BZ-227	20511	0	X	X	PCL/PS	X	FS-534	PFU3		2	2		A7AK019002441	MN
Kon/Min	BZ-308	100474	0	X		PCL/PS	X		Cab3		2	2		A9HK011006089	TX
Kon/Min	BZ-308	177322	0	X		PCL/PS	X		Cab2		2	2		A9HK011000398	TX
Kon/Min	BZ-308	183387	0	X	X	PCL/PS	X		PFU3		2	2		A9HK011006084	TX
Kon/Min	BZ-308e	7395	0	X		PCL/PS	X		PFU3		2	2		AA6W017003409	MN
Kon/Min	BZ-308e	23417	0	X	X	PCL/PS	X	Internal	Cab2		2	2		AA6W017006014	MN
Kon/Min	BZ-308e	82647	0	X	X	PCL/PS	X		PFU4		2	2		AA6W017005241	MN
Kon/Min	BZ-308e	100680	0	X		PCL/PS	X	Internal	PFU4		2	2		AA6W017005330	MN
Kon/Min	BZ-308e	139059	0	X		PCL/PS	X		Cab2		2	2		AA6W017004129	MN
Kon/Min	BZ-308e	191991	0	X	X	PCL/PS	X		Cab2		2	2		AA6W017005215	TX
Kon/Min	BZ-308e	280286	0	X		PCL/PS	X		PFU4		2	2		AA6W017004250	TX
Kon/Min	BZ-308e	341283	0	X		PCL/PS	X		Cab2		2	2		AA6W017005689	TX
Kon/Min	BZ-360i	92843	0	X		PCL/PS	X		PFU3		2	2		AC77013002851	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kon/Min	BZ-360i	183438	0	X		PCL/PS	X		PFU3		2	2	Missing toner, tested with spare.	AC77013001001	MN
Kon/Min	BZ-360i	202826	0	X		PCL/PS	X		PFU3		2	2		AC77013002847	TX
Kon/Min	BZ-360i	283035	0	X		PCL/PS	X		PFU3		2	2		AC77013001016	MN
Kon/Min	BZ-368e	6621	0	X		PCL/PS	X		PFU4		2	2		AA6V017009808	MN
Kon/Min	BZ-368e	7147	0	X		PCL/PS	X		PFU4		2	2		AA6V017009454	MN
Kon/Min	BZ-368e	10004	0	X		PCL/PS	X	FS-536	PFU4		2	2		AA6V017010010	MN
Kon/Min	BZ-368e	24179	0	X		PCL/PS	X		Cab3		2	2		AA6V017007025	TX
Kon/Min	BZ-368e	105711	0	X		PCL/PS	X		Cab2		2	2		AA6V017008303	TX
Kon/Min	BZ-368e	438338	0	X		PCL/PS	X		Cab2		2	2		AA6V017008298	TX
Kon/Min	BZ-368e	540871	0	X	X	pcl/ps	X	FS-536	PFU4		2	2		AA6V017000835	MN
Kon/Min	BZ-4050i	24760	0	X	X	PCL/PS	X		PFU1		2	2	dirty	ACT9011000694	TX
Kon/Min	BZ-4050i	32188	0	X	X	PCL/PS	X		PFU1		2	2		ACT9011000716	TX
Kon/Min	BZ-4050i	37962	0	X	X	PCL/PS	X		Cab2		2	2		ACT9011001355	TX
Kon/Min	BZ-4050i	195423	0	X	X	PCL/PS	X		PFU1		2	2		ACT9011000653	TX
Kon/Min	BZ-4050i		0	X	X	PCL/PS	X		PFU1		2	2	waste toner box full, dirty	ACT9011010465	TX
Kon/Min	BZ-4052	58860	0	X		PCL/PS	X		PFU1		2	2		AA1R011014912	TX
Kon/Min	BZ-4052	61350	0	X	X	pcl/ps	X		PFU1		2	2		AA1R011007444	MN
Kon/Min	BZ-4052	376529	0	X	X	pcl/ps	X		PFU1		2	2	Poor image quality	AA1R011010159	MN
Kon/Min	BZ-450i	36040	0	X	X	pcl/ps	X	Internal	Cab2		2	2		AC76011005650	MN
Kon/Min	BZ-450i	51097	0	X	X	PCL/PS	X		PFU3		2	2		AC76011003957	TX
Kon/Min	BZ-450i	100621	0	X		PCL/PS	X		PFU3		2	2		AC76011004105	TX
Kon/Min	BZ-450i	194967	0	X	X	PCL/PS	X		PFU3		2	2		AC76011004219	TX
Kon/Min	BZ-450i	258263	0	X	X	PCL/PS	X	Internal	PFU4		2	2		AC76011000209	MN
Kon/Min	BZ-450i	325095	0	X	X	PCL/PS	X	Internal	Cab2		2	2		AC76011000630	MN
Kon/Min	BZ-450i	555989	0	X		pcl/ps	X	FS-539	PFU3		2	2		AC76011003305	MN
Kon/Min	BZ-458	224543	0	X	X	PCL/PS	X		Cab2		2	2		A9HH011007403	TX
Kon/Min	BZ-458e	8826	0	X		pcl/ps	X	FS-536	Cab2		2	2		AA6U011022736	MN
Kon/Min	BZ-458e	517129	0	X		pcl/ps	X	Internal	PFU4		2	2		AA6U011018207	MN
Kon/Min	BZ-458e	631968	0	X		pcl/ps	X		PFU4		2	2		AA6U011015410	MN
Kon/Min	BZ-458e	998758	0	X	X	pcl/ps	X	Internal	Cab2		2	2		AA6U011001790	MN
Kon/Min	BZ-4750i	94580	0	X	X	PCL/PS	X		PFU1		2	2		ACT8011001880	MN
Kon/Min	BZ-5000i	24232	0			PCL/PS			PFU1		2	2		ACF1011000786	MN
Kon/Min	BZ-550i	293485	0	X	X	PCL/PS	X	Missing	PFU4		2	2	Bypass tray missing.	AC75011002830	MN
Kon/Min	BZ-554e	391345	0	X		pcl/ps	X		PFU3		2	2	Arrived without finisher	A61D011002781	MN
Kon/Min	BZ-558e	137574	0	X		pcl/ps	X	Internal	PFU4		2	2		AA6T011009517	MN
Kon/Min	BZ-650i	630823	0	X		PCL/PS	X		PFU3		2	2		AC74011002352	TX
Kon/Min	BZ-650i	854076	0	X	X	PCL/PS	X	FS-536	PFU3		2	2		AC74011002363	TX
Kon/Min	BZ-658e	1025248	0	X		PCL/PS	X	FS-536	PFU3		2	2		AA6R011006196	TX
Kon/Min	BZ-808	604857	0	X		PCL/PS	X	FS-536	PFU4		2	2	SD-511	A8KN011001343	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kon/Min	BZ-958	1345123	0	X	X	PCL/PS	X	FS-536	PFU4		2	2	Error Code: C8103	A796011003570	MN
Kon/Min	BZ-C227	18717	8100	X		PCL/PS	X		PFU4		2	2		A798019501308	TX
Kon/Min	BZ-C227	82950	17181	X		PCL/PS	X		Cab2		2	2		A798011501584	MN
Kon/Min	BZ-C227	88284	40098	X	X	PCL/PS	X		Cab2		2	2	dirty	A798019500581	TX
Kon/Min	BZ-C227	111028	59387	X		PCL/PS	X		Cab2		2	2		A798011502670	TX
Kon/Min	BZ-C227	164093	71564	X		PCL/PS	X	Internal	Cab2		2	2		A798011503320	MN
Kon/Min	BZ-C250i	84316	45826	X		pcl/ps	X	FS-536	PFU4		2	2		AA2M011008125	MN
Kon/Min	BZ-C250i	88015	61970	X		PCL/PS	X		Cab2		2	2		AA2M011000344	MN
Kon/Min	BZ-C250i	120274	78683	X	X	PCL/PS	X		Cab2		2	2		AA2M011007084	TX
Kon/Min	BZ-C250i	153269	101584	X		pcl/ps	X		PFU4		2	2	Arrived without finisher.	AA2M013001246	MN
Kon/Min	BZ-C250i	199229	30554	X	X	PCL/PS	X		Cab2		2	2		AA2M011009891	MN
Kon/Min	BZ-C250i	208996	30123	X	X	PCL/PS	X		Cab2		2	2		AA2M011002202	MN
Kon/Min	BZ-C250i	272559	69688	X		PCL/PS	X	FS-536	Cab2		2	2		AA2M013000830	MN
Kon/Min	BZ-C250i	295836	150476	X	X	PCL/PS	X	FS-536	PFU4		2	2	SD-511	AA2M011008482	MN
Kon/Min	BZ-C258	76107	58238	X		PCL/PS	X		Cab2		2	2	Missing Finisher	A7R0011001596	MN
Kon/Min	BZ-C258	226196	95843	X	X	PCL/PS	X		PFU4		2	2		A7R0011008644	TX
Kon/Min	BZ-C258	438896	7001	X		PCL/PS	X	FS-534	Cab2		2	2		A7R0011016524	MN
Kon/Min	BZ-C300i	63930	45599	X	X	pcl/ps	X		Cab2		2	2		AA2K013000608	MN
Kon/Min	BZ-C300i	64814	33556	X		PCL/PS	X		Cab2		2	2		AA2K011006714	MN
Kon/Min	BZ-C300i	101809	44695	X	X	PCL/PS	X	FS-536	PFU4		2	2		AA2K011008507	TX
Kon/Min	BZ-C300i	107897	80472	X		PCL/PS	X		PFU3		2	2		AA2K013004570	TX
Kon/Min	BZ-C300i	116920	49511	X		PCL/PS	X		Cab2		2	2		AA2K011004696	TX
Kon/Min	BZ-C300i	117819	17985	X		PCL/PS	X	Internal	Cab2		2	2		AA2K011007231	MN
Kon/Min	BZ-C300i	126202	91421	X		PCL/PS	X		Cab2		2	2		AA2K011008984	MN
Kon/Min	BZ-C300i	133615	56409	X	X	PCL/PS	X		PFU3		2	2		AA2K013006613	MN
Kon/Min	BZ-C300i	163490	69209	X	X	PCL/PS	X	Internal	Cab2		2	2		AA2K011007675	MN
Kon/Min	BZ-C300i	164762	47464	X	X	PCL/PS	X		Cab2		2	2		AA2K011009024	MN
Kon/Min	BZ-C300i	206088	107018	X		PCL/PS	X		Cab2		2	2		AA2K011009170	MN
Kon/Min	BZ-C300i	251998	77684	X		PCL/PS	X		Cab2		2	2		AA2K011009127	MN
Kon/Min	BZ-C300i	319605	118296	X	X	PCL/PS	X		Cab2		2	2		AA2K011009075	MN
Kon/Min	BZ-C308	51027	13578	X	X	PCL/PS	X		Cab2		2	2		A7PY011022408	MN
Kon/Min	BZ-C308	77678	44901	X	X	PCL/PS	X	Internal	PFU3		2	2		A7PY017014617	MN
Kon/Min	BZ-C308	95215	52935	X		PCL/PS	X		Cab2		2	2		A7PY017010491	MN
Kon/Min	BZ-C308	99653	32886	X	X	pcl/ps	X		PFU4		2	2		A7PY017002766	MN
Kon/Min	BZ-C308	280087	23410	X		pcl/ps	X	FS-534	PFU4		2	2	Can't bypass user authenticati on. Can only pass B/W copy.	A7PY011008813	MN
Kon/Min	BZ-C3100P	6405	0			pcl/ps			PFU1		2	2		A6DR012107949	MN
Kon/Min	BZ-C3110	31636	2363	X		pcl/ps	X		PFU1		2	2		A6DT011002418	MN
Kon/Min	BZ-C3300i	35157	23089			PCL/PS			PFU1		2	2		AAJT011001924	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kon/Min	BZ-C3320i	87523	43177	X		PCL/PS	X		PFU2		2	2		AAJP011001578	TX
Kon/Min	BZ-C3350i	64337	68	X	X	PCL/PS	X		PFU1		2	2		A93E011203119	MN
Kon/Min	BZ-C3350i	94934	78288	X		PCL/PS	X		PFU1		2	2		A93E011003873	TX
Kon/Min	BZ-C3351	143031	58912	X	X	PCL/PS	X		PFU1		2	2		A92F011004591	TX
Kon/Min	BZ-C360i	30510	10023	X	X	PCL/PS	X	Internal	PFU3		2	2		AA2J011003775	MN
Kon/Min	BZ-C360i	54581	33160	X		PCL/PS	X		Cab2		2	2	Trouble code C-D073	AA2J011010898	TX
Kon/Min	BZ-C360i	117572	50874	X		PCL/PS	X	FS-536	PFU4		2	2	SD-511	AA2J013006904	MN
Kon/Min	BZ-C360i	192573	129568	X	X	pcl/ps	X	FS-536	PFU3		2	2		AA2J011010330	MN
Kon/Min	BZ-C360i	202836	163044	X		PCL/PS	X	Internal	PFU4		2	2		AA2J013006413	MN
Kon/Min	BZ-C360i	204253	26830	X	X	PCL/PS	X	FS-536	Cab3		2	2		AA2J011006194	MN
Kon/Min	BZ-C360i	259716	138791	X		pcl/ps	X		PFU4		2	2		AA2J011008594	MN
Kon/Min	BZ-C360i	262149	82545	X	X	PCL/PS	X	Internal	PFU4		2	2		AA2J013000534	MN
Kon/Min	BZ-C360i	419710	53335	X	X	PCL/PS	X	FS-536	PFU3		2	2		AA2J011000505	TX
Kon/Min	BZ-C360i	444419	286869	X		PCL/PS	X	Internal	PFU4		2	2		AA2J013007627	MN
Kon/Min	BZ-C360i	483060	278424	X		PCL/PS	X	Internal	PFU3		2	2		AA2J011009552	MN
Kon/Min	BZ-C360i	1270007	380050	X	X	PCL/PS	X		PFU3		2	2		AA2J011002367	TX
Kon/Min	BZ-C364e	473655	247573	X		PCL/PS	X		PFU4		2	2	Flat top, odd cable on back, missing fiery?	A5C1011023823	MN
Kon/Min	BZ-C364e	491362	184216	X		PCL/PS	X	FS-534	PFU4		2	2	Yellowed	A5C1011026821	MN
Kon/Min	BZ-C368	69509	49399	X		PCL/PS	X		PFU4		2	2		A7PU017211790	TX
Kon/Min	BZ-C368	78345	35807	X	X	PCL/PS	X		PFU4		2	2		A7PU017204262	TX
Kon/Min	BZ-C368	437172	171223	X		PCL/PS	X	Internal	PFU3		2	2		A7PU017201997	MN
Kon/Min	BZ-C368	548030	162740	X		pcl/ps	X	FS-534	Cab2		2	2		A7PU011023193	MN
Kon/Min	BZ-C4050i	121437	78825	X	X	PCL/PS	X		PFU1		2	2		AAJN011001311	TX
Kon/Min	BZ-C4050i	147252	85045	X	X	PCL/PS	X		PFU1		2	2		AAJN011001308	TX
Kon/Min	BZ-C450i	62182	32517	X	X	PCL/PS	X	FS-539	Cab3		2	2		AA7R011004167	MN
Kon/Min	BZ-C450i	73101	54695	X	X	pcl/ps	X	FS-540	PFU4		2	2		AA7R011002784	MN
Kon/Min	BZ-C450i	78452	48611	X		PCL/PS	X		PFU3		2	2		AA7R011001758	TX
Kon/Min	BZ-C450i	105057	25652	X	X	PCL/PS	X	FS-539	Cab2		2	2		AA7R011010631	TX
Kon/Min	BZ-C450i	132485	60112	X	X	PCL/PS	X	FS-539	PFU4		2	2		AA7R011018022	MN
Kon/Min	BZ-C450i	144513	72509	X		PCL/PS	X		PFU4		2	2	Missing Bridge Unit	AA7R011008201	MN
Kon/Min	BZ-C450i	200832	99251	X		PCL/PS	X		PFU3		2	2		AA7R011000958	TX
Kon/Min	BZ-C450i	255919	141815	X		PCL/PS	X		Cab2		2	2		AA7R011001408	TX
Kon/Min	BZ-C450i	274686	175687	X		PCL/PS	X		Cab2		2	2		AA7R011001460	TX
Kon/Min	BZ-C450i	285291	214841	X		pcl/ps	X	FS-539	PFU4		2	2		AA7R011012708	MN
Kon/Min	BZ-C450i	293824	36663	X	X	PCL/PS	X	FS-539	PFU4		2	2		AA7R011003901	MN
Kon/Min	BZ-C450i	295854	122843	X	X	PCL/PS	X		PFU3		2	2		AA7R011011763	TX

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kon/Min	BZ-C450i	334140	64138	X		pcl/ps	X	Internal	PFU4		2	2	Back left corner panel missing.	AA7R011013323	MN
Kon/Min	BZ-C450i	362885	224434	X	X	Fiery ES IC-420	X	FS-539	Cab3		2	2		AA7R011003708	MN
Kon/Min	BZ-C450i	424600	304018	X		PCL/PS	X		PFU3		2	2		AA7R011001318	TX
Kon/Min	BZ-C450i	432825	291535	X	X	pcl/ps	X	FS-539	PFU4		2	2		AA7R011013502	MN
Kon/Min	BZ-C450i	500493	382766	X	X	pcl/ps	X	FS-540SD	PFU3		2	2		AA7R011007051	MN
Kon/Min	BZ-C450i	548588	505972	X		pcl/ps	X	FS-540SD	PFU3		2	2		AA7R011007030	MN
Kon/Min	BZ-C458	96387	52959	X	X	pcl/ps	X	FS-536	PFU3		2	2		A79M011042993	MN
Kon/Min	BZ-C458	115224	32892	X	X	PCL/PS	X		PFU3		2	2		A79M011052557	TX
Kon/Min	BZ-C458	127669	80860	X		PCL/PS	X		PFU3		2	2	Arrived W/O Finisher	A79M011048687	MN
Kon/Min	BZ-C458	159488	110397	X		PCL/PS	X	FS-536	PFU4		2	2		A79M011019418	MN
Kon/Min	BZ-C458	168712	96817	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79M011046472	MN
Kon/Min	BZ-C458	174189	44458	X	X	PCL/PS	X		PFU4		2	2		A79M011003164	TX
Kon/Min	BZ-C458	185279	61185	X	X	PCL/PS	X		PFU3		2	2		AA7R011001498	TX
Kon/Min	BZ-C458	190726	113040	X	X	PCL/PS	X	FS-536	PFU4		2	2		A79M011020415	TX
Kon/Min	BZ-C458	207997	114883	X		PCL/PS	X		PFU4		2	2		A79M011052236	TX
Kon/Min	BZ-C458	239292	168957	X		PCL/PS	X	Internal	PFU3		2	2		A79M011038754	MN
Kon/Min	BZ-C458	263200	57853	X	X	PCL/PS	X	FS-536	PFU4		2	2		A79M011050967	MN
Kon/Min	BZ-C458	265199	122160	X		PCL/PS	X		PFU3		2	2		A79M011050846	TX
Kon/Min	BZ-C458	315157	65077	X	X	PCL/PS	X		PFU3		2	2		A79M011049224	TX
Kon/Min	BZ-C458	406761	82686	X		PCL/PS	X	FS-536	PFU3		2	2		A79M011004186	MN
Kon/Min	BZ-C458	417000	83174	X	X	PCL/PS	X	Internal	PFU4		2	2	Light salt water damage, no resulting problems noticed.	A79M011016352	MN
Kon/Min	BZ-C458	491582	41659	X	X	pcl/ps	X	FS-536	Cab3		2	2		A79M011007196	MN
Kon/Min	BZ-C458	654042	141729	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79M011010199	MN
Kon/Min	BZ-C458	725262	136638	X	X	PCL/PS	X	Internal	PFU3		2	2		A79M011027860	MN
Kon/Min	BZ-C458	740613	25518	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79M011047753	TX
Kon/Min	BZ-C458	762651	28798	X	X	PCL/PS	X		PFU3		2	2		A79M011049297	TX
Kon/Min	BZ-C458	928227	371726	X		PCL/PS	X	FS-536	PFU4		2	2		A79M011037784	MN
Kon/Min	BZ-C458	1160336	59250	X		E200-09	X		PFU4		2	2	Arrived W/O Finisher	A79M011046294	MN
Kon/Min	BZ-C550i	153767	121015	X		PCL/PS	X	FS-540SD	PFU3		2	2		AA7P011002747	MN
Kon/Min	BZ-C550i	662905	269287	X		PCL/PS	X	FS-539	PFU3		2	2		AA7P011006356	MN
Kon/Min	BZ-C550i	1143951	921287	X		pcl/ps	X	FS-540SD	PFU4		2	2		AA7P011000833	MN
Kon/Min	BZ-C550i	1325909	421771	X	X	PCL/PS	X	FS-540SD	PFU4		2	2		AA7P011003170	MN
Kon/Min	BZ-C558	122787	64623	X		PCL/PS	X		Cab2		2	2		A79K011013660	TX
Kon/Min	BZ-C558	186005	130084	X		PCL/PS	X		Cab2		2	2		A79K011010687	TX
Kon/Min	BZ-C558	196750	127682	X		PCL/PS	X	Internal	PFU3		2	2		A79K011027057	MN
Kon/Min	BZ-C558	238878	173783	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79K011027805	MN
Kon/Min	BZ-C558	569855	76113	X	X	PCL/PS	X	FS-537	PFU3		2	2		A79K011021268	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kon/Min	BZ-C558	745836	461168	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79K011012256	TX
Kon/Min	BZ-C558	852293	568612	X		PCL/PS	X	FS-537	PFU4		2	2	SD-512	A79K011027615	MN
Kon/Min	BZ-C558	970851	246289	X		pcl/ps	X	FS-536	PFU4		2	2		A79K011017850	MN
Kon/Min	BZ-C650i	142964	24957	X		PCL/PS	X	FS-539	PFU3	LU-302	2	2		AA7N017000030	TX
Kon/Min	BZ-C650i	232980	2021	X		PCL/PS	X	FS-539	PFU3	LU-302	2	2		AA7N011008535	TX
Kon/Min	BZ-C650i	291535	156957	X	X	PCL/PS	X	FS-534	PFU4		2	2	Incorrect finisher sent with machine.	AA7N011005020	MN
Kon/Min	BZ-C650i	771249	279506	X	X	PCL/PS	X	FS-540	Cab3		2	2	Tested With Another Toner	AA7N011002804	MN
Kon/Min	BZ-C658	368654	229385	X	X	PCL/PS	X	FS-539	PFU4		2	2		A79J013010187	MN
Kon/Min	BZ-C658	473083	295283	X		PCL/PS	X		PFU3		2	2		A79J013010075	TX
Kon/Min	BZ-C658	1026578	569820	X		PCL/PS	X	FS-536	PFU3		2	2	Incorrect Finisher	A79J013008396	MN
Kon/Min	BZ-C658	1186846	170441	X		PCL/PS	X	FS-536	PFU3		2	2		A79J013009849	TX
Kon/Min	BZ-C659	592316	431240	X	X	PCL/PS	X	FS-540SD	PFU4		2	2		A9K6011007387	TX
Kon/Min	BZ-C659	1396626	198790	X		pcl/ps	X	FS-537	PFU4		2	2	Poor image quality.	A9K6011008069	MN
Kon/Min	BZ-C750i	223505	128369	X	X	PCL/PS	X	FS-536	PFU4		2	2	Incorrect finisher sent with machine.	ACKN011002512	MN
Kon/Min	BZ-C759	344729	205291	X		PCL/PS	X	FS-536	PFU4		2	2		A8JE011001640	MN
Kyocera	FS-4100DN	68543	0			KPDL/PCL			PFU1		2	2		LQP6816214	TX
Kyocera	FS-4100DN	93210	0			KPDL/PCL			PFU1		2	2		LQP6816171	TX
Kyocera	M2540dw	44096	0	X	X	KPDL/PCL	X		PFU1		2	2		VCJ1Y43467	TX
Kyocera	M2640idw	1397	0	X	X	KPDL/PCL	X		PFU1		2	2		VCM8904988	MN
Kyocera	M2640idw	6893	0	X		pcl/kpdl	X		PFU1		2	2	Yellowed and dirty.	VCM9808065	MN
Kyocera	M2640idw	7027	0	X	X	KPDL/PCL6	X		PFU1		2	2		VCM8904989	MN
Kyocera	M2640idw	8353	0	X	X	KPDL/PCL6	X		PFU1		2	2		VCM9808039	MN
Kyocera	M2640idw	26116	0	X	X	KPDL/PCL6	X		PFU1		2	2		VCM8103681	MN
Kyocera	M2640idw	41764	0	X	X	KPDL/PCL6	X		PFU1		2	2		VCM9808056	MN
Kyocera	M2640idw	63535	0	X	X	KPDL/PCL	X		PFU1		2	2		VCM9808068	MN
Kyocera	M2640idw	73527	0	X		KPDL/PCL6	X		PFU1		2	2		VCM9808055	MN
Kyocera	M2640idw	74593	0	X	X	KPDL/PCL	X		PFU1		2	2		VCM9808060	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kyocera	M3540IDN	97603	0	X	X	KPDL/PCL	X		PFU1		2	2		LSH7428064	TX
Kyocera	M3540IDN	100782	0	X	X	KPDL/PCL	X		PFU1		2	2		LSH7730495	TX
Kyocera	M3540IDN	372911	0	X	X	KPDL/PCL	X		PFU1		2	2		LSH7629549	TX
Kyocera	M3560IDN	142889	0	X	X	KPDL/PCL	X		PFU1		2	2		LSR7703352	TX
Kyocera	M3560IDN	161357	0	X	X	KPDL/PCL	X		PFU1		2	2		LSR7703314	TX
Kyocera	M3560IDN	381355	0	X	X	KPDL/PCL	X		PFU1		2	2		LSR7703304	TX
Kyocera	M3645IDN	110846	0	X	X	KDPL/PCL	X		PFU1		2	2		R4S9Z13022	TX
Kyocera	M3645IDN	119854	0	X	X	KDPL/PCL	X		PFU1		2	2		R4S9Z13021	TX
Kyocera	M3655IDN	20654	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9X44711	MN
Kyocera	M3655IDN	20699	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9X46599	MN
Kyocera	M3655IDN	20816	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9X47631	MN
Kyocera	M3655IDN	27313	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9X47634	MN
Kyocera	M3655IDN	32085	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9X47627	MN
Kyocera	M3655IDN	35400	0	X	X	PCL/PS	X		PFU1		2	2		R4P9X46569	MN
Kyocera	M3655IDN	44876	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9X47632	MN
Kyocera	M3655IDN	66492	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9X47626	MN
Kyocera	M3655IDN	81442	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9428933	MN
Kyocera	M3655IDN	104692	0	X		KPDL	X		PFU1		2	2		R4P2Z17093	MN
Kyocera	M3655IDN	121303	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9X46595	MN
Kyocera	M3655IDN	140781	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9Y49763	MN
Kyocera	M3655IDN	144928	0	X	X	pcl/kpdl	X		PFU1		2	2		R4P9940741	MN
Kyocera	M3655IDN	162788	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9X47630	MN
Kyocera	M3655IDN	188645	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P9Y49756	MN
Kyocera	M3655IDN	190780	0	X	X	KPDL	X		PFU1		2	2		R4P9940742	MN
Kyocera	M3655IDN	327817	0	X		KPDL	X		PFU1		2	2		R4P9428935	MN
Kyocera	M5526cdw	110734	49158	X		pcl/kpdl	X		PFU1		2	2		VE89Y10775	MN
Kyocera	M6235cidn	170096	22428	X		KPDL/PCL	X		PFU1		2	2		RC18700537	MN
Kyocera	M6535CiD N	123307	17182	X	X	KPDL/PCL	X		PFU1		2	2		V6D5400205	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kyocera	M6535CiD N	138477	112149	X	X	KPDL/PCL	X		PFU1		2	2		V6D5702550	TX
Kyocera	M6635CiD N	30162	4610	X		PCL/PS	X		PFU1		2	2		RC49Y09387	TX
Kyocera	M6635CiD N	33762	16513	X	X	KPDL/PCL	X		PFU1		2	2		RC49908477	TX
Kyocera	M6635CiD N	37612	4527	X		PCL/PS	X		PFU1		2	2		RC40210306	TX
Kyocera	M6635CiD N	38069	20118	X	X	pcl/kpdl	X		PFU1		2	2		RC49505948	MN
Kyocera	M6635CiD N	41627	14708	X	X	KDPL/PCL	X		PFU1		2	2		RC49Z09559	TX
Kyocera	P2040dw	5729	0			KPDL/PCL			PFU1		2	2		VD29537578	MN
Kyocera	P2040dw	28290	0			KPDL/PCL			PFU1		2	2		VD28Y30434	TX
Kyocera	P3045dn	50487	0			KPDL/PCL			PFU1		2	2		VM37202018	MN
Kyocera	P3145DN	5557	0			KPDL/PCL			PFU1		2	2		R4H9905491	TX
Kyocera	P3145DN	6095	0			KPDL/PCL			PFU1		2	2		R4H9905493	TX
Kyocera	P3145DN	11419	0	X		KDPL/PCL			PFU1		2	2		R4H9905494	TX
Kyocera	P3145DN	13182	0			KPDL/PCL			PFU1		2	2		R4H9905488	TX
Kyocera	P3145DN	20364	0			KPDL/PCL			PFU1		2	2		R4H9905500	TX
Kyocera	P3145DN	31986	0	X		KDPL/PCL			PFU1		2	2		R4H9905490	TX
Kyocera	P3145DN	44991	0	X		KDPL/PCL			PFU1		2	2		R4H9600676	TX
Kyocera	P3145DN	45910	0	X		KDPL/PCL			PFU1		2	2		R4H9300155	TX
Kyocera	P3145DN	46943	0	X		KDPL/PCL			PFU1		2	2		R4H9300151	TX
Kyocera	P3145DN	64976	0	X		KDPL/PCL			PFU1		2	2		R4H9905489	TX
Kyocera	P3145DN	68750	0			KPDL/PCL			PFU1		2	2		R4H9905498	TX
Kyocera	P3145DN	70137	0	X		KDPL/PCL			PFU1		2	2		R4H9804824	TX
Kyocera	P3145DN	439107	0			KPDL/PCL			PFU1		2	2		R4H9905492	TX
Kyocera	P3150dn	14176	0			KPDL/PCL			PFU1		2	2		R4D9701324	TX
Kyocera	P3150dn	23881	0			KPDL/PCL			PFU1		2	2		R4D9600404	MN
Kyocera	P3150dn	56704	0			KPDL/PCL			PFU1		2	2		R4D9600396	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kyocera	P3150dn	140334	0			KPDL/PCL			PFU1		2	2		R4D9Z02623	MN
Kyocera	P3150dn	161964	0			KPDL/PCL			PFU1		2	2		R4D9Z02792	MN
Kyocera	P3150dn	255109	0			KPDL/PCL			PFU1		2	2		R4D9Z02627	MN
Kyocera	P3150dn	258301	0			KPDL/PCL			PFU1		2	2		R4D0303719	MN
Kyocera	P3150dn	267993	0			KPDL/PCL			PFU1		2	2		R4D9Z02620	MN
Kyocera	P3150dn	302838	0			KPDL/PCL			PFU1		2	2		R4D9Z02628	MN
Kyocera	P3150dn	430066	0			kpdl/pcl			PFU1		2	2		R4D9600395	MN
Kyocera	P5026cdw	16388	8229			KPDL/PCL			PFU1		2	2		VDT0106397	MN
Kyocera	P6230CDN	21965	0	X		KDPL/PCL			PFU1		2	2		RCB9803145	TX
Kyocera	P6230CDN	43530	0	X		KDPL/PCL			PFU1		2	2		RCB9803153	TX
Kyocera	P6230CDN	74493	0	X		KDPL/PCL			PFU1		2	2		RCB9803122	TX
Kyocera	TA-2552ci	203433	58732	X		KDPL/PCL	X		Cab2		2	2		VFJ6600040	TX
Kyocera	TA-2553ci	58590	24129	X		pcl/kpdl	X		Cab2		2	2	Missing waste toner container. Tested with external supplies.	RFL9501553	MN
Kyocera	TA-2553ci	61435	31021	X		KPDL/PCL	X		Cab2		2	2	Dirty much Y toner all over & inside machine	RFL9501251	MN
Kyocera	TA-2553ci	81364	22278	X		KPDL/PCL	X		Cab2		2	2		RFL0803689	MN
Kyocera	TA-2553ci	101769	39113	X		KPDL/PCL	X	Internal	Cab2		2	2		RFL9501537	MN
Kyocera	TA-2553ci	119104	21799	X		KPDL/PCL	X		Cab2		2	2		RFL9602465	MN
Kyocera	TA-2553ci	124989	103178	X		KPDL/PCL	X		Cab2		2	2		RFL9501442	MN
Kyocera	TA-2553ci	200443	145118	X		PCL/PS	X	Internal	Cab2		2	2		RFL9602253	MN
Kyocera	TA-2553ci	202970	84654	X		KPDL/PCL	X		Cab2		2	2		RFL9501222	MN
Kyocera	TA-2553ci	217317	66698	X		KPDL/PCL	X		Cab2		2	2		RFL9501246	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kyocera	TA-2553ci	248582	172760	X		KPDL/PCL	X		Cab2		2	2		RFL9602103	MN
Kyocera	TA-307CI	57274	42155	X		KPDL/PCL	X		Cab2		2	2		R368600751	MN
Kyocera	TA-307CI	143549	12838	X	X	KPDL/PCL	X		Cab2		2	2		R368701339	MN
Kyocera	TA-307CI	149348	24502	X		KDPL/PCL	X		Cab2		2	2		R369502792	TX
Kyocera	TA-307CI	175447	122342	X	X	KPDL/PCL	X		Cab2		2	2		R369102233	MN
Kyocera	TA-308ci	68678	37991	X	X	pcl/kpdl	X		PFU3		2	2		RLZ0901935	MN
Kyocera	TA-308ci	81500	38204	X		KPDL/pCL	X		PFU3		2	2		RLZ9800029	MN
Kyocera	TA-3212i	719774	0	X		KPDL/PCL	X	DF-7120	Cab2		2	2		R419502964	MN
Kyocera	TA-3252ci	117552	85419	X		KDPL/PCL	X		Cab2		2	2		W2R8609700	TX
Kyocera	TA-3252ci	221021	88867	X		KPDL/PCL	X		Cab2		2	2		W2R8Y11274	MN
Kyocera	TA-3253ci	38793	18562	X		KPDL/PCL	X		Cab2		2	2		RFG0706181	TX
Kyocera	TA-3253ci	151004	86780	X		KPDL/PCL	X	DF-7120	Cab2		2	2		RFG8Z00194	MN
Kyocera	TA-3253ci	175731	25014	X	X	pcl/kpdl	X	DF-7120	Cab2		2	2		RFG9Z04781	MN
Kyocera	TA-3253ci	209111	145075	X		KPDL/PCL	X		Cab2		2	2		RFG9604370	MN
Kyocera	TA-3253ci	246761	151196	X		KPDL/PCL	X		Cab2		2	2		RFG9603308	MN
Kyocera	TA-3253ci	324722	169491	X	X	KPDL/PCL	X	DF-7120	PFU4		2	2		RFG0X07283	TX
Kyocera	TA-3551ci	153176	39128	X	X	KPDL/PCL	X		PFU3		2	2		L8H4Y02854	TX
Kyocera	TA-3551ci	235750	157609	X		PCL/PS	X		PFU4		2	2		L8H6706780	TX
Kyocera	TA-3551ci	299194	91890	X	X	KPDL/PCL	X	DF-770	Cab2		2	2		L8H3Z01023	TX
Kyocera	TA-3551ci	422887	224662	X		KPDL/PCL	X	DF-770	PFU4		2	2	Additional accessories enVision power conditioning system, machine is a little dusty.	L8H3800427	TX
Kyocera	TA-3552ci	67907	20532	X		KPDL/PCL	X	DF-7110	Cab2		2	2		VLQ6Y02698	MN
Kyocera	TA-3552ci	224479	78312	X		KDPL/PCL	X	DF-7120	PFU4		2	2		VLQ6X02069	TX
Kyocera	TA-3552ci	282320	153592	X		PCL/PS	X		Cab2		2	2		VLQ6901848	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kyocera	TA-3553ci	107037	36410	X		KPDL/PCL	X	Internal	PFU4		2	2		RFE0104531	MN
Kyocera	TA-3553ci	111309	48753	X		KPDL/PCL	X	Internal	PFU4		2	2		RFE1107726	MN
Kyocera	TA-3553ci	121742	33552	X		KPDL/PCL	X		Cab2		2	2		RFE0104670	MN
Kyocera	TA-3553ci	129595	88810	X	X	KPDL/PCL6	X		PFU4		2	2		RFE9602526	MN
Kyocera	TA-3553ci	174907	42090	X		pcl/kpdl	X		Cab2		2	2		RFE9703516	MN
Kyocera	TA-3553ci	191855	15751	X		KPDL/PCL	X		Cab2		2	2		RFE9703518	MN
Kyocera	TA-3553ci	196164	145059	X		KPDL/PCL	X		Cab2		2	2		RFE9502245	MN
Kyocera	TA-3553ci	197489	154177	X		KPDL/PCL	X		PFU4		2	2		RFE8Z00248	MN
Kyocera	TA-3553ci	210454	159660	X		pcl/kpdl	X	DF-7120	PFU4		2	2		RFE0405010	MN
Kyocera	TA-3553ci	284177	175039	X		pcl/kpdl	X	DF-7120	Cab2		2	2		RFE0Y07056	MN
Kyocera	TA-4002i	132225	0	X		PCL/PS	X		PFU4		2	2		W377Z09845	TX
Kyocera	TA-4002i	453755	0	X		KPDL/PCL6	X		Cab2		2	2		W376800703	MN
Kyocera	TA-4003i	250886	0	X	X	KPDL/PCL	X		PFU4		2	2		RFX9705279	TX
Kyocera	TA-4003i	469488	0	X		KDPL/PCL	X	DF-7110	PFU4		2	2		RFX9402395	TX
Kyocera	TA-4052ci	271767	62505	X		PCL/PS	X	DF-7120	PFU4		2	2		W2M6700053	TX
Kyocera	TA-4053ci	288208	167142	X		KPDL/PCL	X		Cab2		2	2		RFB9X03452	MN
Kyocera	TA-4501i	209540	0	X		KPDL/PCL	X		Cab2		2	2		L7N5307412	MN
Kyocera	TA-5002i	210554	0	X		KPDL/PCL	X	DF-7120	PFU4		2	2		W347X05538	TX
Kyocera	TA-5002i	506593	0	X		PCL/PS	X		Cab2		2	2		W347704657	TX
Kyocera	TA-5003i	128401	0	X		KPDL/PCL	X	Internal	PFU4		2	2		RFU9401117	MN
Kyocera	TA-5003i	281086	0	X		KPDL/PCL	X		PFU4		2	2	Back Panel Missing Screws	RFU9401153	MN
Kyocera	TA-5003i	286981	0	X		KPDL/PCL	X	Internal	PFU4		2	2		RFU9401121	MN
Kyocera	TA-5003i	313524	0	X	X	pcl/kpdl	X	DF-7110	PFU4		2	2		RFU9Y03384	MN
Kyocera	TA-5003i	350942	0	X		KPDL/PCL	X	DF7140	PFU4		2	2		RFU9X03150	MN
Kyocera	TA-5003i	435996	0	X		pcl/kpdl	X	DF-7110	PFU4		2	2		RFU9Y03406	MN
Kyocera	TA-5003i	870710	0	X		pcl/kpdl	X	DF-7110	PFU4		2	2		RFU9401140	MN
Kyocera	TA-5052ci	447079	156164	X	X	KDPL/PCL	X	DF-770	PFU4		2	2		W2H8106838	TX
Kyocera	TA-5053ci	49659	40062	X		KPDL/PCL	X	DF-7120	PFU4		2	2		RF70105299	MN
Kyocera	TA-5053ci	50258	33294	X		pcl/kpdl	X	DF-7120	PFU4		2	2		RF79903299	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Kyocera	TA-5053ci	65908	36855	X		KPDL/PCL	X	DF-7120	PFU4		2	2		RF79903758	MN
Kyocera	TA-5053ci	321730	74585	X		KPDL/PCL	X	DF-7120	PFU4		2	2		RF70906932	TX
Kyocera	TA-5053ci	389515	39080	X		pcl/kpdl	X	DF-7110	PFU4		2	2		RF70205531	MN
Kyocera	TA-5053ci	527240	50251	X	X	KPDL/PCL	X	Internal	PFU4		2	2		RF79904066	MN
Kyocera	TA-5501i	544343	0	X		PCL/PS	X		PFU4		2	2		L7J4905207	TX
Kyocera	TA-5551ci	65168	12923	X		PCL/PS	X		PFU4		2	2		L893Z00730	TX
Kyocera	TA-6003i	319886	0	X		KPDL/PCL	X	DF-7110	PFU4		2	2		RFQ0302901	MN
Kyocera	TA-7002i	1193260	0	X		KPDL/PCL6	X	DF-790	PFU4		2	2		VAP872060	MN
Kyocera	TA-7003i	506604	0	X		pcl/ps	X	DF-7110	PFU4		2	2		RRK9Z00450	MN
Kyocera	TA-7003i	685260	0	X		KPDL/PCL	X	DF-7110	PFU4		2	2		RRK9Z00402	MN
Kyocera	TA-7052ci	719961	201239	X		KDPL/PCL	X	DF-7110	PFU4		2	2		VA37600551	TX
Kyocera	TA-7054ci	559022	326026	X		pcl/kpdl	X	DF-7140	PFU4		2	2		RV21600026	MN
Kyocera	TA-7353ci	1153115	1011458	X		KPDL/PCL	X	DF-7110	PFU4		2	2		RS51200780	MN
Lanier	IM350F	39065	0	X	X	PCL/PS	X		PFU1		2	2		3379PA01035	TX
Lanier	IM430F	66039	0	X		PCL/PS	X		PFU1		2	2		3359PC01057	MN
Lanier	IM430F	78305	0	X	X	PCL/PS	X		PFU1		2	2		3359PC01061	MN
Lanier	IM430F	103212	0	X	X	PCL/PS	X		PFU1		2	2		3359PC00946	MN
Lanier	IM430F	129774	0	X	X	PCL/PS	X		PFU1		2	2		3359PC01050	MN
Lanier	IM430F	151149	0	X	X	PCL/PS	X		PFU1		2	2		3359PC01054	MN
Lanier	IM430F	254069	0	X	X	PCL/PS	X		PFU1		2	2		3359PC01056	MN
Lanier	IM430F	329954	0	X	X	PCL/PS	X		PFU1		2	2		3359PC01052	MN
Lanier	IM550	187845	0	X		PCL/PS	X		Cab2		2	2	Desktop on rolling cab base	3203X361268	TX
Lanier	IMC2000	163573	7347	X		PCL/PS	X		Cab2		2	2		3089RC00666	MN
Lanier	IMC2500	44717	25115	X		PCL/PS	X		Cab2		2	2		3092R100827	TX
Lanier	IMC300	67571	3005	X	X	PCL/PS	X		PFU1		2	2		3920P500244	MN
Lanier	IMC3000	38925	13795	X	X	pcl/ps	X		PFU4		2	2		3100RA00858	MN
Lanier	IMC3000	43123	20164	X		PCL/PS	X	Internal	PFU4		2	2		3109RA01595	MN
Lanier	IMC3000	122666	32600	X		pcl/ps	X	SR3260	PFU4		2	2		3109RB00482	MN
Lanier	IMC3000	132312	62251	X		pcl/ps	X	Internal	PFU4		2	2		3109RA01353	MN
Lanier	IMC3000	150318	80352	X		pcl/ps	X	Internal	PFU4		2	2		3109RA01693	MN
Lanier	IMC3000	160403	70445	X		PCL/PS	X		PFU4		2	2		3100R201175	TX
Lanier	IMC3000	219754	103129	X		pcl/ps	X	Internal	PFU4		2	2		3109RA01698	MN
Lanier	IMC3000	348416	83006	X		PCL/PS	X	SR3270	PFU3		2	2		3109RA01560	MN
Lanier	IMC3500	125411	98976	X		PCL/PS	X		PFU4		2	2		3111R100084	TX
Lanier	IMC3500	136741	81427	X	X	PCL/PS	X		Cab2		2	2	Missing HDD	3110R700132	MN
Lanier	IMC3500	410027	189270	X		PCL/PS	X	SR3260	Cab2		2	2		3110R700134	MN
Lanier	IMC4500	137929	53689	X		PCL/PS	X	SR3260	PFU4		2	2		3129RB00752	MN
Lanier	IMC4500	239475	143710	X		pcl/ps	X	SR3270	PFU3		2	2		3128MB00555	MN
Lanier	IMC4500	422888	315239	X	X	pcl/ps	X	SR3260	PFU4		2	2		3129RA01305	MN
Lanier	IMC4500	521203	313667	X		PCL/PS	X	SR3260	PFU4		2	2		3129RB00668	MN

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Lanier	MC250FW	10177	8530	X	X	PCL/PS	X		PFU1		2	2		5459P600085	MN
Lanier	MP2555	74553	0	X		PCL/PS	X		Cab2		2	2		C290R200328	MN
Lanier	MP2555	110006	0	X		PCL/PS	X		PFU4		2	2		C299RB00073	MN
Lanier	MP3555	236210	0		X	pcl/ps	X		PFU4		2	2	Arrived without finisher	C319L700083	MN
Lanier	MPC2004e x	126356	54526	X		PCL/PS	X		Cab2		2	2		C767R611279	MN
Lanier	MPC2004e x	221058	172325	X		PCL/PS	X		Cab2		2	2		C768R310949	MN
Lanier	MPC3004	516364	116314	X		pcl/ps	X	SR3210	PFU4		2	2		G696MA60513	MN
Lanier	MPC3004e x	186886	72618	X		PCL/PS	X		PFU4		2	2		C717M910052	MN
Lanier	MPC3004e x	302681	59666	X		pcl/ps	X	SR3210	PFU4		2	2		C718M610441	MN
Lanier	MPC307	12657	4371	X	X	PCL/PS	X		PFU1		2	2	Very Dirty	C509PB01249	MN
Lanier	MPC307	32238	13753	X	X	PCL/PS	X		PFU1		2	2		C507PC05449	MN
Lanier	MPC307	57288	7058	X		PCL/PS	X		PFU1		2	2		C509P302492	TX
Lanier	MPC307	152474	127499	X	X	PCL/PS	X		PFU1		2	2		C509PB01821	MN
Lanier	MPC4504E X	264627	87802	X	X	pcl/ps	X	SR3210	PFU4		2	2		C737M640591	MN
Lanier	MPC6003	543833	308873	X	X	PCL/PS	X	SR3140	PFU4		2	2		E196M110086	MN
Lanier	P502	669	0			PCL/PS			PFU1		2	2		5389PB01035	MN
Lanier	P502	2393	0			PCL/PS			PFU1		2	2		5389PA00858	MN
Lanier	P502	8386	0			PCL/PS			PFU1		2	2		5389PB00722	MN
Lanier	P502	24261	0			PCL/PS			PFU1		2	2	Dirty	5389PB01044	MN
Lanier	P502	26091	0			PCL/PS			PFU1		2	2		5389PB01039	MN
Lanier	P502	32294	0			PCL/PS			PFU1		2	2		5389PB01032	MN
Lanier	P502	36851	0			PCL/PS			PFU1		2	2		5389PB00719	MN
Lanier	P502	51921	0			PCL/PS			PFU1		2	2		5389PB01043	MN
Lanier	P502	81893	0			PCL/PS			PFU1		2	2		5389PB01036	MN
Lanier	P502	87127	0			PCL/PS			PFU1		2	2		5389PB01040	MN
Lanier	P502	103127	0			PCL/PS			PFU1		2	2		5389PB01041	MN
Lanier	PC301W	21392	18672			PCL/PS			PFU1		2	2		5439P700098	MN
Lanier	PC301W	28474	24005			PCL/PS			PFU1		2	2	Dirty	5439P700097	MN
Lexmark	C4150	12066	3665		X	pcl/ps			PFU1		2	2		5028815012KTC	MN
Lexmark	C4150	24764	23117			PCL/PS			PFU2		2	2		50289030F3P21	MN
Lexmark	C4150	26797	7694			pcl/ps			PFU1		2	2		50288310F22T9	MN
Lexmark	C4150	36556	22742			pcl/ps			PFU1		2	2		50288310F2ZVR	MN
Lexmark	C4150	72497	19168			pcl/ps			PFU1		2	2		50289020F3MZV	MN
Lexmark	C4150	79080	0			pcl/ps			PFU1		2	2		50289020F3N09	MN
Lexmark	CX622		0	X	X	pcl/ps	X		PFU1		2	2	Passed copy, user authentication is not allowing a check on the meter	75299041421HZ	MN
Lexmark	M1242	9369	0			PCL/PS			PFU1		2	2		46008170033ZC	MN
Lexmark	M1242	20391	0			pcl			PFU1		2	2		4600828108RPC	MN
Lexmark	M1246	7823	0	X		PCL/PS	X		PFU1		2	2		70178221021F8	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Lexmark	M1246	52169	0	X		PCL/PS	X		PFU1		2	2		70178221021FR	TX
Lexmark	M3250	6482	0			PCL/PS			PFU1		2	2		46009323103Z8	MN
Lexmark	M3250	7561	0	X		PCL/PS	X		PFU2		2	2		70188330025CF	TX
Lexmark	M3250	16179	0			PCL/PS			PFU1		2	2		460093030Z6ZR	TX
Lexmark	M3250	22480	0	X		PCL/PS	X		PFU1		2	2		460093030Z6ZX	TX
Lexmark	M3250	45642	0			pcl/ps			PFU1		2	2		46009323104BL	MN
Lexmark	M3250	58013	0			PCL/PS			PFU1		2	2		46009323103Z7	MN
Lexmark	M3250	89943	0	X		PCL/PS			PFU1		2	2		4600824007CHY	TX
Lexmark	XC4140	5883	861	X	X	PCL/PS	X		PFU1		2	2		75289450G4NMB	MN
Lexmark	XC4140	12066	3959	X	X	PCL/PS	X		PFU1		2	2		75280020G4Z7Y	TX
Lexmark	XC4140	71104	31116	X	X	pcl/ps	X		PFU1		2	2		75289510G4X53	MN
Lexmark	XC4140	79441	9412	X	X	pcl/ps	X		PFU1		2	2		75289280F45W9	MN
Lexmark	XC4140	87036	5540	X		PCL/PS	X		Cab1		2	2		75289250F434H	TX
Lexmark	XC4140	128988	61173	X	X	pcl/ps	X		PFU1		2	2		75289510G4X51	MN
Lexmark	XC4143	91746	51832	X	X	pcl/ps	X		PFU1		2	2		75280320G58BV	MN
Lexmark	XC4143	121899	29883	X		PCL/PS	X		PFU2		2	2		75280350G5CCF	TX
Lexmark	XC4150	128642	95158	X	X	PCL/PS	X		PFU2		2	2		75289080F3RD9	MN
Lexmark	XC4150	176209	69646	X	X	PCL/PS	X		PFU2		2	2		75289020F3KTG	MN
Lexmark	XC4150	255658	46468	X	X	PCL/PS	X		PFU1		2	2		75280170G553T	MN
Lexmark	XC4153	905	666	X	X	PCL/PS	X		PFU1		2	2		75281100H60LZ	TX
Lexmark	XC4153	4295	2420	X	X	PCL/PS	X		PFU2		2	2		75280310G5844	MN
Lexmark	XC6152	36277	31504	X	X	PCL/PS	X		PFU3		2	2		7563803010FN8	MN
Lexmark	XC6152	132687	74608	X	X	PCL/PS	X		PFU3		2	2		75639350E0RXX	MN
Lexmark	XC6153	55780	44502	X	X	PCL/PS	X		PFU3		2	2		75630310F0X0M	MN
Lexmark	XC8163	134988	10035	X	X	pcl/ps	X	Staple finisher	PFU2		2	2	Finisher door hinge damaged.	75640020F1MTK	MN
Lexmark	XM1145	48561	0	X	X	PCL/PS	X		PFU1		2	2	Missing toner used warehouse toner to pass copy	70157PHH1KHFX	MN
Lexmark	XM1145	364848	0	X	X	PCL/PS	X		PFU2		2	2		70157PHH1KGDH	MN
Lexmark	XM1246	105450	0			PCL/PS			PFU1		2	2		7017835104XB2	MN
Lexmark	XM1246	166021	0	X	X	PCL/PS	X		PFU1		2	2		70178110008DH	MN
Lexmark	XM1246	233045	0	X	X	pcl/ps	X		PFU1		2	2		7017835104XBW	MN
Lexmark	XM3250	48	0	X	X	pcl	X		PFU1		2	2		701802430B3WZ	MN
Lexmark	XM3250	174	0	X	X	PCL/PS	X		PFU1		2	2		701802430B403	MN
Lexmark	XM3250	2621	0	X	X	PCL/PS	X		PFU1		2	2		701802430B429	MN
Lexmark	XM3250	3560	0	X	X	PCL/PS	X		PFU1		2	2		701802430B48G	MN
Lexmark	XM3250	25561	0	X	X	PCL/PS	X		PFU1		2	2		7018901003VNX	MN
Lexmark	XM3250	67308	0	X	X	PCL/PS	X		PFU2		2	2		70189303062NX	MN
Lexmark	XM3250	79177	0	X	X	PCL/PS	X		PFU1		2	2		7018848003FW1	TX
Lexmark	XM5365	255974	0	X		PCL/PS	X		Cab2		2	2		7464141024Y8R	TX
Lexmark	XS654DE	109677	0	X		PCL/PS	X		PFU1		2	2		79G87XF	TX
Ricoh	IM3500	113090	0	X	X	PCL/PS	X		PFU4		2	2		4431R230074	MN
Ricoh	IM350F	4549	0	X	X	PCL/PS	X		PFU1		2	2		3370P401587	MN
Ricoh	IM350F	49131	0	X	X	PCL/PS	X		PFU1		2	2		3379PB00432	MN
Ricoh	IM350F	383539	0	X	X	pcl/ps	X		PFU1		2	2		3379P900093	MN

Highlighting Key

Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Ricoh	IM430F	50573	0	X	X	PCL/PS	X		PFU1		2	2		3352PC53556	MN
Ricoh	IM430F	57021	0	X	X	PC/PS	X		PFU1		2	2		3350P201190	MN
Ricoh	IM430F	58635	0	X	X	PCL/PS	X		PFU1		2	2		3350P201187	MN
Ricoh	IM430F	92103	0	X	X	PCL/PS	X		PFU1		2	2		3350P201395	MN
Ricoh	IM430F	116785	0	X	X	PCL/PS	X		Cab2		2	2		3350P201183	MN
Ricoh	IM430F	157586	0	X	X	pcl/ps	X		PFU1		2	2		3350P201394	MN
Ricoh	IM430F	172987	0	X	X	pcl/ps	X		PFU1		2	2		3350P201182	MN
Ricoh	IM550	123148	0	X	X	PCL/PS	X		PFU1		2	2		3209X815032	MN
Ricoh	IM600SRF	452880	0	X	X	PCL/PS	X		PFU2		2	2		3229X400018	MN
Ricoh	IMC2000	56249	41349	X	X	PCL/PS	X		Cab2		2	2		3088RC00136	TX
Ricoh	IMC2000	85029	6650	X		pcl/ps	X		Cab2		2	2		3088RC00739	MN
Ricoh	IMC2000	94075	54390	X		PCL/PS	X		Cab2		2	2		3088RB00645	MN
Ricoh	IMC2000	120095	74483	X	X	PCL/PS	X		Cab1		2	2		3089R600679	MN
Ricoh	IMC2000	137031	40479	X		PCL/PS	X		Cab2		2	2		3080R200466	TX
Ricoh	IMC2500	190756	151156	X		PCL/PS	X	Internal	PFU4		2	2		3099R300115	MN
Ricoh	IMC300	59243	6432	X	X	PCL/PS	X		PFU1		2	2		3920P500130	MN
Ricoh	IMC300	63464	23163	X	X	pcl/ps	X		PFU1		2	2		3920P101828	MN
Ricoh	IMC300	97533	15763	X	X	PCL/PS	X		PFU2		2	2		3920PA01187	MN
Ricoh	IMC3000	25053	15352	X		PCL/PS	X	Internal	PFU4		2	2		3100RA00627	MN
Ricoh	IMC3000	46674	18018	X		PCL/PS	X	Internal	PFU4		2	2	User Authentication	3100RA01065	MN
Ricoh	IMC3000	86277	16560	X		PCL/PS	X		PFU4		2	2		3100RA01609	MN
Ricoh	IMC3000	89612	32699	X		PCL/PS	X	SR3260	PFU4		2	2		3100RB00516	MN
Ricoh	IMC3000	92437	68467	X		PCL/PS	X	Internal	PFU4		2	2		3109R900333	MN
Ricoh	IMC3000	92964	28144	X		PCL/PS	X		PFU4		2	2		3100RA01607	MN
Ricoh	IMC3000	161411	102618	X		PCL/PS	X	Internal	PFU4		2	2	User Authentication	3100RB00046	MN
Ricoh	IMC3000	198665	27022	X		PCL/PS	X		PFU4		2	2	Missing Toner, tested with spare.	3109RC00264	MN
Ricoh	IMC3000	207888	69965	X	X	PCL/PS	X	SR3260	PFU4		2	2		3109R700790	TX
Ricoh	IMC3000	212853	88512	X	X	PCL/PS	X		PFU4		2	2		3100R200185	TX
Ricoh	IMC3000	242482	31302	X	X	pcl/ps	X		Cab2		2	2	Dirty and yellowing.	3109RB00742	MN
Ricoh	IMC3000	303549	176988	X	X	pcl/ps	X	SR3260	PFU4		2	2		3108RC00765	MN
Ricoh	IMC3000	353337	303582	X		PCL/PS	X		Cab2		2	2		3100R200401	MN
Ricoh	IMC3000	363378	84026	X		PCL/PS	X		Cab2		2	2		3109R600363	MN
Ricoh	IMC3000	394822	19520	X		PCL/PS	X		PFU3		2	2	Very Dirty	3109RB00705	MN
Ricoh	IMC3500	60278	0	X	X	PCL/PS	X		PFU1		2	2	User Authentication	3370P801630	MN
Ricoh	IMC3500	79744	17837	X	X	PCL/PS	X		PFU4		2	2		3119R200746	TX
Ricoh	IMC3500	180586	99586	X	X	PCL/PS	X		PFU3		2	2		3119R900364	TX
Ricoh	IMC3500	292122	92874	X	X	pcl/ps	X		PFU4		2	2		3118RB00340	MN
Ricoh	IMC3500	297491	28474	X		PCL/PS	X		Cab2		2	2		3111R970512	MN
Ricoh	IMC4500	48559	41197	X		PCL/PS	X	SR3210	PFU4		2	2		3121R910813	TX
Ricoh	IMC4500	168183	98676	X	X	PCL/PS	X	SR3270			2	2		3129R900795	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Ricoh	IMC4500	196408	111797	X	X	PCL/PS	X	SR3260	PFU4		2	2		3129RB01850	TX
Ricoh	IMC4500	260584	96374	X		PCL/PS	X	SR3260	Cab2		2	2		3129M540954	MN
Ricoh	IMC4500	316507	186397	X		pcl/ps	X	Internal	PFU3		2	2		3120R701551	MN
Ricoh	IMC4500	420093	175009	X	X	pcl/ps	X	SR3260	PFU3		2	2		3121RA11489	MN
Ricoh	IMC4500	586651	268740	X	X	PCL/PS	X	SR3206	PFU4		2	2		3120R101291	MN
Ricoh	IMC4500	810275	241712	X	X	PCL/PS	X	Internal	PFU4		2	2		3121R102923	MN
Ricoh	IMC4500	1087028	552891	X	X	pcl/ps	X		PFU4		2	2	Arrived without finisher	3120R102143	MN
Ricoh	IMC530FB	98877	63681	X	X	PCL/PS	X		PFU1		2	2		4201X300319	MN
Ricoh	IMC530FB	140704	91057	X	X	pcl/ps	X		PFU1		2	2		4201X300272	MN
Ricoh	IMC530FB	142255	99972	X	X	PCL/PS	X		PFU1		2	2		4201X300323	MN
Ricoh	IMC530FB	155670	106101	X	X	PCL/PS	X		PFU1		2	2		4201X500498	MN
Ricoh	IMC530FB	186158	86393	X	X	PCL/PS	X		PFU1		2	2		4201X300273	MN
Ricoh	IMC530FB	209087	110884	X	X	PCL/PS	X		PFU1		2	2		4201X300276	MN
Ricoh	IMC530FB	220358	110311	X	X	pcl/ps	X		PFU1		2	2		4201X400132	MN
Ricoh	IMC530FB	239890	122326	X	X	PCL/PS	X		PFU1		2	2		4201X400109	MN
Ricoh	IMC530FB	247113	135731	X	X	PCL/PS	X		PFU1		2	2		4201X300315	MN
Ricoh	IMC530FB	251858	125069	X	X	PCL/PS	X		PFU1		2	2	Waste toner bottle full.	4201X500497	MN
Ricoh	IMC530FB	256238	149304	X	X	PCL/PS	X		PFU1		2	2		4201X300267	MN
Ricoh	IMC6000	115302	32738	X		PCL/PS	X	SR3260	PFU4		2	2		3140R900050	MN
Ricoh	IMC6000	323759	175079	X	X	PCL/PS	X	Internal	PFU4		2	2		3140RB00267	MN
Ricoh	IMC6000	424872	41991	X	X	PCL/PS	X	SR3270	PFU4		2	2		3149M530030	MN
Ricoh	IMC6000	702756	383340	X	X	pcl/ps	X	SR3260	PFU4		2	2		3149RA00170	MN
Ricoh	IMC6000	2002072	610822	X		pcl/ps	X	SR3290	PFU4		2	2		3149M130701	MN
Ricoh	MP2554	78450	0	X		PCL/PS	X	Internal	PFU4		2	2		G145R800067	MN
Ricoh	MP2554	225170	0	X		PCL/PS	X		Cab2		2	2		G145R200354	TX
Ricoh	MP2554	350674	0	X	X	pcl	X		PFU4		2	2		G146R601258	MN
Ricoh	MP2555	122113	0	X	X	PCL/PS	X		Cab2		2	2		C299RC00294	TX
Ricoh	MP2555	141535	0	X		PCL/PS	X	Internal	PFU4		2	2		C290R801364	MN
Ricoh	MP2555	148502	0	X		PCL/PS	X		Cab2		2	2		C290R600065	TX
Ricoh	MP2555	151095	0	X		PCL/PS	X		Cab2		2	2		C297R320208	MN
Ricoh	MP305+	62504	0	X	X	PCL/PS	X		PFU1		2	2		G589P200147	MN
Ricoh	MP305+	241091	0	X	X	PCL/PS	X		PFU1		2	2		G589P200111	MN
Ricoh	MP305+	247514	0	X	X	PCL/PS	X		PFU1		2	2		G588PA00042	MN
Ricoh	MP305+	252191	0	X	X	PCL/PS	X		PFU1		2	2		G588P900878	MN
Ricoh	MP3054	166307	0	X		PCL/PS	X		PFU4		2	2	Arrived W/O Finisher	G154RB30065	MN
Ricoh	MP3055	93780	0	X	X	PCL/PS	X	SR3210	PFU3		2	2		C309L600283	TX
Ricoh	MP3353	301840	0	X	X	PCL	X		PFU4		2	2	Missing Exit Tray	E763L900249	MN
Ricoh	MP3555	401427	0	X	X	pcl/ps	X	Internal	Cab2		2	2		C318RB20028	MN
Ricoh	MP4002	367807	0	X	X	pcl/ps	X		Cab2		2	2	Arrived without finisher	W522L100389R1	MN
Ricoh	MP402	188222	0	X	X	PCL/PS	X		PFU1		2	2		Y176H900471	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Ricoh	MP4054	903908	0	X		PCL/PS	X		PFU4		2	2	Unit arrived without a finisher.	G175R931222	TX
Ricoh	MP4055	93176	0	X		PCL/PS	X	SR3210	PFU4		2	2		C320R200105	MN
Ricoh	MP4055	162599	0	X	X	PCL/PS	X	Internal	PFU4		2	2		C320R801655	MN
Ricoh	MP4055	171574	0	X	X	PCL/PS	X	Internal	PFU4		2	2		C320R800254	MN
Ricoh	MP4055	196225	0	X	X	PCL/PS	X	Internal	PFU4		2	2		C329R800569	MN
Ricoh	MP4055	197875	0	X	X	PCL/PS	X	Internal	PFU4		2	2		C320R901018	MN
Ricoh	MP4055	214781	0	X		PCL/PS	X	SR3210	Cab2		2	2		C329R801165	MN
Ricoh	MP4055	242729	0	X	X	PCL/PS	X	SR3210	Cab2		2	2		C329R801242	MN
Ricoh	MP4055	294423	0	X		PCL/PS	X	SR32110	Cab2		2	2		C329R801146	MN
Ricoh	MP4055	298830	0	X	X	PCL/PS	X	Internal	PFU4		2	2		C320R900988	MN
Ricoh	MP4055	334964	0	X		PCL/PS	X	Internal	PFU4		2	2		C320R900984	MN
Ricoh	MP4055	347183	0	X	X	PCL/PS	X		PFU4		2	2	Arrived W/O Finisher	C327R600118	MN
Ricoh	MP4055	363500	0	X	X	PCL	X	Internal	PFU4		2	2		C329R800647	MN
Ricoh	MP4055	368730	0	X		pcl/ps	X	SR3210	Cab2		2	2		C329R801163	MN
Ricoh	MP4055	372405	0	X	X	PCL/PS	X		Cab2		2	2		C329RA00308	MN
Ricoh	MP4055	430955	0	X	X	PCL/PS	X	SR3260	PFU3		2	2		C327R100568	MN
Ricoh	MP4055	440481	0	X	X	PCL/PS	X	SR3210	PFU4		2	2		C320RA00407	MN
Ricoh	MP4055	443284	0	X		pcl/ps	X	Internal	PFU3		2	2		C320R801429	MN
Ricoh	MP4055	488716	0	X	X	PCL/PS	X		Cab2		2	2		C328RA00421	TX
Ricoh	MP501	36260	0	X	X	PCL/PS	X		PFU1		2	2		G988X787434	MN
Ricoh	MP5054	414744	0	X	X	pcl/ps	X	Internal	PFU4		2	2		G186R720521	MN
Ricoh	MP5055	59533	0	X	X	PCL/PS	X	SR3210	PFU3		2	2		C339R800375	MN
Ricoh	MP5055	166570	0	X	X	PCL/PS	X	SR3210	PFU3		2	2		C339R800374	MN
Ricoh	MP6055	351493	0	X	X	pcl/ps	X	SR3210	PFU4		2	2		C349RA00054	MN
Ricoh	MP6055	379077	0	X		PCL/PS	X	MP-3210	PFU3		2	2		C340R800275	MN
Ricoh	MP6055	637377	0	X		pcl/ps	X	SR3210	PFU3		2	2		C340R800256	MN
Ricoh	MP6055	790520	0	X		PCL/PS	X	SR-3210	PFU3		2	2		C340R800244	MN
Ricoh	MP6503	325376	0	X		pcl	X	SR4120	PFU3		2	2		G659C100363	MN
Ricoh	MP6503	1674528	0	X	X	PCL/PS	X	SR4120	PFU3		2	2		G659C800224	MN
Ricoh	MP7503	971692	0	X	X	PCL	X	SR4120	PFU3		2	2		G668CB00071	MN
Ricoh	MP7503	1471719	0	X		PCL	X	SR4120	PFU3		2	2	Finisher Damaged	G669L100141	MN
Ricoh	MP9003	182271	0	X		PCL/PS	X	SR4120	PFU3	RT4020	2	2		G670C100182	MN
Ricoh	MPC2003	64311	28782	X	X	PCL	X		Cab2		2	2		E204M860870	MN
Ricoh	MPC2003	147167	51024	X	X	pcl/ps	X	Internal	PFU4		2	2		E205M160582	MN
Ricoh	MPC2004	342017	109902	X		pcl/ps	X		Cab2		2	2		G746R910867	MN
Ricoh	MPC2004	356453	15141	X		PCL/PS	X		Cab2		2	2		G746R710595	MN
Ricoh	MPC2004e x	52544	16345	X		pcl/ps	X		PFU4		2	2		C767R310563	MN
Ricoh	MPC2004e x	109820	79807	X		PCL/PS	X		Cab2		2	2		G746R710193	MN
Ricoh	MPC2004e x	128025	6314	X	X	PCL/PS	X		Cab2		2	2		C767R410160	MN
Ricoh	MPC2004e x	219537	45420	X		PCL/PS	X		Cab2		2	2		C767R611309	MN
Ricoh	MPC3003	122955	24439	X	X	PCL/PS	X		PFU4		2	2		E155M411157	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Ricoh	MPC3004	87977	49640	X		PCL/PS	X	SR3210	PFU4		2	2		G696MC60877	MN
Ricoh	MPC3004	141039	57483	X		PCL	X		Cab2		2	2		G696M660038	MN
Ricoh	MPC3004	152240	78941	X		PCL	X		Cab2		2	2		G696M760334	MN
Ricoh	MPC3004	206720	62380	X	X	pcl	X	SR3210	Cab2		2	2		G696MB60658	MN
Ricoh	MPC3004	277354	165447	X	X	PCL	X	Internal	PFU4		2	2		G696MC61344	MN
Ricoh	MPC3004	355787	55991	X		PCL	X	SR3210	PFU4	LCT	2	2		G696MB60521	MN
Ricoh	MPC3004	445051	106992	X		PCL	X		Cab2		2	2		G696M760011	MN
Ricoh	MPC3004e x	100301	72166	X	X	PCL/PS	X		Cab2		2	2	Yellowed	C718M111091	MN
Ricoh	MPC3004e x	143009	92869	X		PCL/PS	X		PFU4		2	2		C717M400916	MN
Ricoh	MPC3004e x	270407	89778	X	X	PCL/PS	X		PFU4		2	2	Arrived W/O Finisher	C717M600388	MN
Ricoh	MPC3004e x	296498	68302	X		PCL/PS	X		Cab2		2	2		C717M500271	MN
Ricoh	MPC3004e x	304567	86402	X		PCL/PS	X		PFU4		2	2		C717M400373	MN
Ricoh	MPC3004e x	354895	223945	X	X	PCL/PS	X		Cab2		2	2	Arrived W/O Finisher	C717M200083	MN
Ricoh	MPC306	110240	19922	X	X	PCL/PS	X		PFU1		2	2		G445P900808	MN
Ricoh	MPC307	26372	2449	X	X	pcl/ps	X		PFU2		2	2		C509P700797	MN
Ricoh	MPC307	29112	6149	X	X	pcl/ps	X		Cab2		2	2		C508PA00785	MN
Ricoh	MPC307	156284	110439	X	X	PCL/PS	X		PFU1		2	2		C507P400760	MN
Ricoh	MPC3502	508179	267878	X	X	PCL	X		Cab2		2	2		E163M760844	MN
Ricoh	MPC3503	40962	17241	X	X	PCL	X		PFU4		2	2	Missing Finisher	E164MA10018R1	MN
Ricoh	MPC3503	123531	57039	X	X	PCL/PS	X		PFU3		2	2		E165MB11004	MN
Ricoh	MPC3503	1038930	230971	X	X	PCL	X	Internal	PFU4		2	2		E164M360516	MN
Ricoh	MPC3504	269265	61970	X	X	PCL/PS	X		Cab2		2	2		G707L200188	TX
Ricoh	MPC3504	414287	92200	X		PCL/PS	X		Cab2		2	2		G707L300399	MN
Ricoh	MPC3504e x	347241	97142	X		PCL/PS	X		Cab2		2	2	Arrived W/O Finisher	C727M610015	MN
Ricoh	MPC3504e x	360885	93657	X		PCL	X		PFU4		2	2		G706M460815	MN
Ricoh	MPC3504e x	459294	210274	X		PCL/PS	X		PFU4		2	2	Arrived W/O Finisher	C727MC10379	MN
Ricoh	MPC3504e x	708175	216744	X	X	PCL/PS	X		PFU4		2	2	Arrived W/O Finisher	G706M960747	MN
Ricoh	MPC3504e x	755292	142873	X		PCL	X	SR3220	PFU4		2	2	Yellowed	G706M861146	MN
Ricoh	MPC3504e x	921321	89141	X		PCL/PS	X		Cab2		2	2	Arrived WO Finisher	C727M610213	MN
Ricoh	MPC407	68464	17848	X	X	PCL/PS	X		PFU1		2	2		C497PC00804	MN
Ricoh	MPC4503	204282	101896	X	X	PCL/PS	X	SR3140	PFU4		2	2		E174MC60376	MN
Ricoh	MPC4503	333654	0	X	X	PCL/PS	X		PFU3		2	2		E173M710154	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Ricoh	MPC4503	620497	307260	X	X	PCL	X	Missing	PFU4		2	2	Missing Finisher	E174MB11624	MN
Ricoh	MPC4503	769122	66904	X	X	PCL	X	SR3150	PFU4		2	2		E174MB11945	MN
Ricoh	MPC4504	189021	102796	X	X	PCL/PS	X	SR3210	PFU3		2	2		G716M460383	MN
Ricoh	MPC4504	306556	41499	X	X	pcl/ps	X	SR3210	PFU4		2	2		G716M960270	MN
Ricoh	MPC4504	739647	229646	X	X	PCL	X		PFU3		2	2	Arrived W/O Finisher	G716M661585	MN
Ricoh	MPC4504E X	178344	42510	X	X	PCL/PS	X		PFU3		2	2		C738MA40668	TX
Ricoh	MPC4504E X	428288	203630	X	X	PCL/PS	X		PFU4		2	2		G716M860797	MN
Ricoh	MPC4504E X	503305	106192	X	X	PCL/PS	X		Cab2		2	2		C737M740987	MN
Ricoh	MPC4504E X	553145	311055	X	X	PCL	X		PFU4		2	2	Arrived W/O Finisher	G716M510863	MN
Ricoh	MPC5502	406850	53133	X		PCL/PS	X		PFU4		2	2	Missing Finisher, missing all toner used warehouse toner to pass copy	W543L500256	MN
Ricoh	MPC5503	1319669	207606	X		PCL/PS	X	SR3160	PFU4		2	2		E184MC60474	MN
Ricoh	MPC6004	669153	101540	X	X	PCL/PS	X		PFU4		2	2	Arrived W/O Finisher	G736M760495	MN
Ricoh	MPC6004	704323	271703	X		pcl	X	SR3210	PFU3		2	2		G736MB61066	MN
Ricoh	MPC6004e x	457528	218579	X		PCL/PS	X	SR3240	PFU4		2	2		C758M700022	TX
Ricoh	MPC6004e x	1434340	461701	X	X	PCL/PS	X		PFU4		2	2	Arrived W/O Finisher	G736MA60832	MN
Ricoh	MPC6503	311770	245842	X	X	PCL	X		PFU3		2	2	Arrived W/O Finisher	C068C700325	MN
Ricoh	MPCW2201 SP	20407	9182			-	X				2	2	Empty magenta toner. 1x 36in roll. B/W 11225 sqft, Color 9182 sqft.	G930Q110054	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

													Empty magenta and yellow toner. B/W 106474 sqft. Color 128 sqft. 1x 36 in roll.		
Ricoh	MPCW2201 SP	106602	128			-	X				2	2		G937Q910037	MN
Ricoh	P501	4	0			PCL/PS			PFU1		2	2		5210PC00182	MN
Ricoh	P501	7	0			PCL/PS			PFU1		2	2		5210PB02239	MN
Ricoh	P501	170	0			PCL/PS			PFU1		2	2		5210PC00186	MN
Ricoh	P501	585	0			PCL/PS			PFU1		2	2		5210PC00151	MN
Ricoh	P501	7395	0			PCL/PS			PFU1		2	2		5210PC00138	MN
Ricoh	P501	10420	0			PCL/PS			PFU1		2	2		5210PC00136	MN
Ricoh	P501	19608	0			PCL/PS			PFU1		2	2		5210PC00145	MN
Ricoh	P501	21522	0			PCL/PS			PFU1		2	2		5212P102861	MN
Ricoh	P501	32814	0	X		PCL/PS	X		PFU1		2	2		5210PC00133	MN
Ricoh	P502	604	0			PCL/PS			PFU1		2	2		5389P600700	MN
Ricoh	P502	2345	0			PCL/PS			PFU1		2	2		5389P200324	MN
Ricoh	P502	6273	0			PCL/PS			PFU1		2	2		5383P100693	MN
Ricoh	P502	13820	0			PCL/PS			PFU1		2	2	Missing toner used warehouse toner to pass copy	5389P200362	MN
Ricoh	P502	14969	0			PCL/PS			PFU1		2	2	Missing toner	5383P100696	MN
Ricoh	P502	16112	0			PCL/PS			PFU1		2	2	Missing toner	5383P100691	MN
Ricoh	P502	18167	0			PCL/PS			PFU1		2	2		5389P600539	MN
Ricoh	P502	19644	0			PCL/PS			PFU1		2	2		5383P100688	MN
Ricoh	P502	23337	0			PCL/PS			PFU1		2	2		5383P100643	MN
Ricoh	P502	31142	0			PCL/PS			PFU1		2	2		5383P100690	MN
Ricoh	P502	50500	0			PCL/PS			PFU1		2	2		5383P100644	MN
Ricoh	ProC5200S	215936	128708	X		PCL/PS	X	SR5070	PFU3		2	2	GBC StreamPunch Ultra MP, missing HDD	C088C800033	MN
Ricoh	S150		0				X				2	2		JU301755	TX
Ricoh	SP4520DN	126683	0			PCL/PS			PFU1		2	2		T588HA03307	MN
Ricoh	SP8400DN	249028	0			PCL/PS			Cab2		2	2		Y870RC00096	TX
Savin	IMC3000	34164	30004	X	X	PCL/PS	X		Cab2		2	2		3101R970256	TX
Savin	IMC4500	375165	27461	X		PCL/PS	X		PFU4		2	2		3120R201668	TX
Savin	IMC4500	487572	167416	X	X	PCL/PS	X	SR3270	PFU3		2	2		3129M404137	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Savin	IMC4500	939735	333380	X		PCL/PS	X		Cab2		2	2		3129M340155	MN
Savin	IMC6000	342442	118000	X	X	pcl/ps	X	SR3260	PFU4		2	2		3149RC00001	MN
Savin	IMC6000	422799	104621	X		PCL/PS	X	SR3260	PFU3		2	2		3149M400207	MN
Savin	IMC600SR F	143117	0	X	X	PCL/PS	X		PFU2		2	2		3229X900643	TX
Savin	MP5002	294223	0	X	X	PCL	X	Missing	PFU4		2	2		W534L900773	MN
Savin	MPC2504ex	50974	15627	X	X	PCL/PS	X		Cab2		2	2	1 broke/missing wheel	C778R610068	MN
Savin	MPC2504ex	138647	68236	X		PCL/PS	X		PFU3		2	2		C778R210038	MN
Savin	MPC2504ex	181967	31620	X		PCL/PS	X		PFU3		2	2		C777R510228	MN
Savin	MPC3003	348688	104725	X	X	PCL	X		Cab2		2	2		E154MA60409	MN
Savin	MPC3503	654475	120209	X	X	PCL	X		PFU4		2	2		E164M360460	MN
Savin	MPC6004ex	461543	268140	X	X	PCL	X		PFU4		2	2		C758M820539	MN
Sharp	BP-50C45	165632	135138	X		PCL/PS	X	MX-FN13	PFU4		2	2		2506094X	TX
Sharp	BP-50M26	200499	0	X	X	PCL/PS	X		PFU3		2	2		25002978	TX
Sharp	BP-70C31	94015	54247	X	X	PCL/PS	X		Cab2		2	2		25051366	MN
Sharp	MX-2651	24127	18722	X	X	PCL/PS	X		Cab2		2	2		13006001	MN
Sharp	MX-2651	32925	1957	X		PCL/PS	X		Cab2		2	2		9301795Y	TX
Sharp	MX-2651	47000	29069	X	X	PCL/PS	X		PFU3		2	2		9501851X	MN
Sharp	MX-2651	68162	34392	X		PCL/PS	X	Internal	PFU3		2	2		9301744Y	MN
Sharp	MX-2651	115227	107216	X		PCL	X		Cab2		2	2		03011178a	MN
Sharp	MX-2651	200787	88401	X		PCL/PS	X		Cab2		2	2		95054721	MN
Sharp	MX-2651	271420	70567	X		PCL/PS	X	Internal	PFU3		2	2		9301953Y	MN
Sharp	MX-2651	326383	74148	X	X	PCL/PS	X		Cab2		2	2		95046155	MN
Sharp	MX-3050N	99578	32386	X		PCL/PS	X		PFU4		2	2		75043630	TX
Sharp	MX-3050N	233833	151690	X	X	PCL/PS	X		PFU4		2	2		75043620	TX
Sharp	MX-3050N	352520	212868	X	X	PCL/PS	X		PFU4		2	2		75043780	TX
Sharp	MX-3051	79864	48801	X		PCL/PS	X	MX-FN28	Cab2		2	2		95064024	TX
Sharp	MX-3051	127476	33038	X	X	PCL/PS	X		Cab2		2	2		15035239	TX
Sharp	MX-3051	131109	68371	X		PCL/PS	X		PFU3		2	2		95066652	TX
Sharp	MX-3051	143597	23746	X		PCL/PS	X		PFU3		2	2		95067912	TX
Sharp	MX-3051	146604	52260	X	X	PCL	X	Internal	PFU4		2	2		03018139a	MN
Sharp	MX-3051	159005	25250	X	X	PCL/PS	X	Internal	PFU4		2	2		03018269a	MN
Sharp	MX-3051	191182	9216	X		PCL/PS	X		PFU4		2	2		85092330	TX
Sharp	MX-3051	202263	8209	X	X	PCL	X	Internal	Cab2		2	2		15042380	MN
Sharp	MX-3070N	213182	34182	X		PCL/PS	X		PFU3		2	2		75039713	TX
Sharp	MX-3070N	244368	43300	X	X	PCL/PS	X		PFU4		2	2	Yellowing on top of ADF	6508717X	MN
Sharp	MX-3070V	40004	25107	X	X	PCL/PS	X		PFU4		2	2		85082208	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Sharp	MX-3070V	87090	59181	X		PCL/PS	X		PFU4		2	2		85075604	MN
Sharp	MX-3070V	156697	69645	X		PCL/PS	X		Cab2		2	2		85082198	TX
Sharp	MX-3071	29945	5454	X	X	pcl/ps	X	Internal	PFU4		2	2		03024111a	MN
Sharp	MX-3071	45586	34522	X		pcl/ps	X	Internal	Cab2		2	2		95082294	MN
Sharp	MX-3071	53929	25700	X		PCL/PS	X	Internal	PFU4		2	2		15047470	MN
Sharp	MX-3071	60811	3757	X	X	PCL/PS	X	Internal	PFU4		2	2		13029394	MN
Sharp	MX-3071	65776	44068	X		PCL/PS	X	Internal	PFU4		2	2		95085144	MN
Sharp	MX-3071	69893	40045	X		PCL/PS	X		Cab2		2	2		9510166X	TX
Sharp	MX-3071	73756	54839	X		PCL/PS	X		PFU4		2	2		05072497a	MN
Sharp	MX-3071	75723	64140	X		PCL/PS	X	Internal	PFU4		2	2		95085034	MN
Sharp	MX-3071	77361	3642	X		PCL/PS	X		Cab2		2	2		95114237	TX
Sharp	MX-3071	78428	53021	X		PCL/PS	X	Internal	PFU4		2	2		15067328	MN
Sharp	MX-3071	79093	25852	X	X	PCLPS	X		Cab2		2	2		15043349	TX
Sharp	MX-3071	82273	36049	X		PCL/PS	X	Internal	PFU4		2	2		95084435	MN
Sharp	MX-3071	85344	59709	X	X	pcl/ps	X	Internal	PFU4		2	2		13027924	MN
Sharp	MX-3071	90789	47306	X		pcl/ps	X	Internal	PFU4		2	2		15039509	MN
Sharp	MX-3071	99205	0	X	X	PCL/PS	X	Internal	PFU4		2	2		03019201a	MN
Sharp	MX-3071	102225	809	X	X	PCL/PS	X		PFU4		2	2		15034277	MN
Sharp	MX-3071	106518	53786	X		PCL/PS	X		PFU4		2	2		95023449	MN
Sharp	MX-3071	117676	37106	X	X	PCL/PS	X		PFU4		2	2		9302122Y	MN
Sharp	MX-3071	117763	42028	X	X	PCL/PS	X		PFU4		2	2		05094503a	MN
Sharp	MX-3071	119327	62995	X	X	pcl/ps	X	Internal	PFU4		2	2		95084405	MN
Sharp	MX-3071	128337	7938	X	X	PCL/PS	X		Cab2		2	2		13024283	TX
Sharp	MX-3071	129418	58881	X	X	PCL/PS	X	Internal	PFU4		2	2		95084395	MN
Sharp	MX-3071	131215	78986	X		PCL/PS	X		PFU4		2	2		3014672	MN
Sharp	MX-3071	134048	77475	X		PCL/PS	X	Internal	PFU4		2	2		95078436	MN
Sharp	MX-3071	140336	33848	X		pcl/ps	X		PFU4		2	2		3015582	MN
Sharp	MX-3071	141695	43060	X		PCL/PS	X		Cab2		2	2		95085075	MN
Sharp	MX-3071	156287	121492	X		PCL/PS	X		PFU4		2	2		9300269X	MN
Sharp	MX-3071	160137	47431	X	X	pcl/ps	X		Cab2		2	2		03018501a	MN
Sharp	MX-3071	160679	37144	X		pcl/ps	X		PFU4		2	2		3014462	MN
Sharp	MX-3071	161956	17353	X		pcl/ps	X		PFU4		2	2		3015522	MN
Sharp	MX-3071	170988	85448	X		pcl/ps	X		PFU4		2	2		3014412	MN
Sharp	MX-3071	171483	0	X		PCL/PS	X		Cab2		2	2		03021881a	MN
Sharp	MX-3071	174064	80703	X		PCL/PS	X		PFU4		2	2		3014442	MN
Sharp	MX-3071	176215	56866	X		pcl/ps	X		PFU4		2	2		3015372	MN
Sharp	MX-3071	178925	98799	X		pcl/ps	X	Internal	PFU4		2	2		3014682	MN
Sharp	MX-3071	193923	69808	X		PCL/PS	X		PFU4		2	2		9510128X	MN
Sharp	MX-3071	196252	77795	X	X	PCL/PS	X		Cab2		2	2		95075120	MN
Sharp	MX-3071	199734	66288	X		pcl/ps	X		PFU4		2	2		3015292	MN
Sharp	MX-3071	205562	150074	X	X	PCL/PS	X		Cab2		2	2		95040758	TX
Sharp	MX-3071	209975	25102	X		PCL/PS	X	Internal	PFU4		2	2		03023491a	MN
Sharp	MX-3071	219682	3107	X	X	PCL/PS	X		PFU4		2	2		05094913a	MN
Sharp	MX-3071	224487	72426	X	X	PCL/PS	X		Cab2		2	2		13024203	TX
Sharp	MX-3071	229148	186882	X		pcl/ps	X		Cab2		2	2	Arrived without finisher	13028374	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Sharp	MX-3071	231212	40331	X		PCL/PS	X		PFU4		2	2		3015032	MN
													Unit did not arrive with a finisher. code L4-11		
Sharp	MX-3071	231439	190759	X		PCL/PS	X		PFU4		2	2		15047259	TX
Sharp	MX-3071	232011	63267	X		PCL/PS	X		PFU3		2	2		95075390	TX
Sharp	MX-3071	244495	124367	X		PCL/PS	X		PFU4		2	2		3014532	MN
Sharp	MX-3071	249389	160215	X		pcl/ps	X		PFU4		2	2		3014712	MN
Sharp	MX-3071	252778	68705	X		pcl/ps	X		PFU4		2	2		3014432	MN
Sharp	MX-3071	259880	40629	X		PCL/PS	X		PFU4		2	2		3026391	MN
Sharp	MX-3071	260286	127747	X	X	PCL/PS	X		PFU4		2	2		85117020	MN
Sharp	MX-3071	270334	31854	X		pcl/ps	X		PFU4		2	2		3026531	MN
Sharp	MX-3071	280159	145341	X		pcl/ps	X		PFU4		2	2		3014732	MN
Sharp	MX-3071	288168	90452	X		pcl/ps	X		PFU4		2	2		3015642	MN
Sharp	MX-3071	305667	104705	X	X	PCL/PS	X		Cab2		2	2		85116760	MN
Sharp	MX-3071	308261	111504	X	X	PCL/PS	X	Internal	PFU4		2	2		03023571a	MN
Sharp	MX-3071	319893	157156	X		PCL/PS	X		PFU4		2	2		3015252	MN
Sharp	MX-3071	371735	231442	X		pcl/ps	X		PFU4		2	2		3014382	MN
Sharp	MX-3071	371838	88839	X	X	PCL/PS	X	Internal	PFU4		2	2		03023701a	MN
Sharp	MX-3071	443408	266674	X	X	PCL/PS	X	MX-FN31	PFU4		2	2		0303949Y	TX
Sharp	MX-3071	516115	93758	X		PCL/PS	X	Internal	PFU4		2	2		9300062X	MN
Sharp	MX-3071	532392	6912	X		PCL/PS	X		PFU3		2	2		95075400	TX
Sharp	MX-3071	1990454	1755351	X		PCL/PS	X	Internal	PFU4		2	2		9302611Y	MN
Sharp	MX-3071S	44291	27082	X	X	PCL	X	MX-FN29	PFU4		2	2		1505277X	MN
Sharp	MX-3071S	78927	70455	X		PCL/PS	X	Internal	PFU4		2	2		1514740Y	MN
Sharp	MX-3071S	90957	55440	X	X	pcl/ps	X		PFU4		2	2		25060201	MN
Sharp	MX-3570N	78420	60520	X	X	pcl/ps	X		Cab2		2	2		65086052	MN
Sharp	MX-3570N	331726	224172	X		pcl/ps	X	Internal	Cab2		2	2		75089209	MN
Sharp	MX-3570V	104549	70250	X	X	PCL/PS	X		Cab2		2	2		85104856	MN
Sharp	MX-3571	111388	64701	X		PCL/PS	X		PFU4		2	2		05144129a	MN
Sharp	MX-3571	115827	86785	X		PCL/PS	X		PFU4		2	2		13021063	MN
Sharp	MX-3571	224709	84515	X	X	PCL/PS	X		PFU4		2	2		05144219a	MN
Sharp	MX-3571	264022	157500	X		PCL/PS	X	Internal	PFU4		2	2		95086066	MN
Sharp	MX-3571	267343	109935	X	X	PCL/PS	X		PFU4		2	2		0303500Y	MN
Sharp	MX-3571	276599	107938	X	X	PCL/PS	X	Internal	PFU4		2	2		03035909a	MN
Sharp	MX-3571	279979	38642	X	X	PCL/PS	X		Cab2		2	2		95095930	TX
Sharp	MX-3571	288476	33163	X		PCL/PS	X	Internal	PFU4		2	2		95085336	MN
Sharp	MX-3571	689275	442499	X	X	PCL/PS	X		PFU4		2	2		85121720	TX
Sharp	MX-4050N	177496	75111	X	X	PCL/PS	X		PFU4		2	2		65112501	TX
Sharp	MX-4070	151981	96107	X	X	PCL/PS	X	MX-FN30	PFU4		2	2		85123797	TX
Sharp	MX-4070V	188453	79001	X	X	PCL/PS	X		PFU4		2	2		85102064	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Sharp	MX-4071	43728	26003	X		PCL/PS	X	MX-FN28	PFU4		2	2		9300554X	MN
Sharp	MX-4071	45237	27448	X		PCL/PS	X	Internal	PFU4		2	2		95043228	MN
Sharp	MX-4071	55643	0	X		PCL/PS	X		PFU4		2	2	Unit did not arrive with a finisher.	95025678	TX
Sharp	MX-4071	72266	48446	X		PCL/PSA	X	MX-FN28	PFU4		2	2		9300642X	MN
Sharp	MX-4071	72592	24635	X	X	PCL/PS	X	Internal	PFU4		2	2		95091446	MN
Sharp	MX-4071	73653	13252	X	X	PCL/PS	X		PFU4		2	2		95137917	MN
Sharp	MX-4071	106122	48577	X	X	PCL/PS	X	MX-FN30	PFU4		2	2		95099950	MN
Sharp	MX-4071	131964	37002	X		PCL/PS	X	Internal	PFU4		2	2		95043178	MN
Sharp	MX-4071	159781	96314	X		PCL/PS	X	Internal	PFU4		2	2		95111254	MN
Sharp	MX-4071	201405	104516	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		95096143	TX
Sharp	MX-4071	206777	0	X		PCL/PS	X		PFU4		2	2		95025728	TX
Sharp	MX-4071	219463	107936	X		PCL/PS	X	MX-FN29	PFU4		2	2		15115055	TX
Sharp	MX-4071	266791	82990	X		pcl/ps	X	Internal	PFU4		2	2		3031771	MN
Sharp	MX-4071	272202	221568	X		pcl/ps	X	MX-FN29	PFU4		2	2		95136197	MN
Sharp	MX-4071	275722	59680	X		pcl/ps	X		PFU4		2	2		3014522	MN
Sharp	MX-4071	282782	75869	X		PCL/PS	X	Internal	PFU4		2	2		95043188	MN
Sharp	MX-4071	292252	182232	X		PCL/PS	X		PFU4		2	2		15057089	MN
Sharp	MX-4071	302140	94404	X		pcl/ps	X	Internal	PFU4		2	2		9304080Y	MN
Sharp	MX-4071	321537	49353	X		PCL/PS	X	Internal	PFU4		2	2		95043098	MN
Sharp	MX-4071	328662	45099	X		PCL/PS	X	Internal	PFU4		2	2		3030951	MN
Sharp	MX-4071	343816	158159	X	X	pcl/ps	X	MX-FN31	PFU4		2	2		95105251	MN
Sharp	MX-4071	350643	150100	X	X	pcl/ps	X	MX-FN28	PFU4		2	2		95099125	MN
Sharp	MX-4071	384917	38802	X	X	pcl/ps	X		PFU4		2	2		3036193	MN
Sharp	MX-4071	397179	111240	X		PCL/PS	X		PFU4		2	2		3030181	MN
Sharp	MX-4071	416123	244841	X		pcl/ps	X	Internal	PFU4		2	2		3030141	MN
Sharp	MX-4071	419131	208871	X	X	PCL/PS	X		PFU4		2	2		95114079	MN
Sharp	MX-4071	496016	28527	X	X	pcl/ps	X		PFU4		2	2		95090236	MN
Sharp	MX-4071	626502	153090	X		pcl/ps	X		PFU4		2	2		9304105Y	MN
Sharp	MX-4111N	43781	24726	X	X	PCL/PS	X		PFU2		2	2		15056567	TX
Sharp	MX-5070N	327909	169499	X		pcl/ps	X	Internal	PFU4		2	2		65073230	MN
Sharp	MX-5071	73586	52341	X	X	PCL/PS	X		PFU4		2	2		03005807a	TX
Sharp	MX-5071	87608	24948	X		pcl/ps	X	Internal	PFU4		2	2		15118905	MN
Sharp	MX-5071	143987	0	X		PCL/PS	X	MX-FN29	PFU4		2	2		9300297Y	TX
Sharp	MX-5071	205717	62430	X		pcl/ps	X	Internal	PFU4		2	2		95142427	MN
Sharp	MX-5071	270828	140469	X	X	PCL/PS	X	Internal	PFU4		2	2		0302242a	MN
Sharp	MX-5071	314348	132436	X		PCL/PS	X	Internal	PFU4		2	2		95143837	MN
Sharp	MX-5071	329427	81218	X		PCL/PS	X	MX-FN28	PFU4		2	2		95103943	MN
Sharp	MX-5071	456765	56570	X	X	pcl/ps	X	Internal	PFU4		2	2		95031099	MN
Sharp	MX-5071	467073	50705	X	X	PCL/PS	X	MX-FN29	PFU4		2	2		95035189	TX
Sharp	MX-5071	510262	174244	X	X	PCL/PS	X	Internal	PFU4		2	2		03049139a	MN
Sharp	MX-5071	526227	55242	X	X	pcl/ps	X		PFU4		2	2		0302507X	MN
Sharp	MX-5071	535977	448061	X		PCL/PS	X		PFU3		2	2		13006904	MN
Sharp	MX-5071	570473	236465	X	X	pcl/ps	X	MX-FN28	PFU4		2	2		9304586Y	MN
Sharp	MX-5071	709724	105471	X	X	pcl/ps	X		PFU4		2	2		0302513X	MN
Sharp	MX-5071	745370	260796	X		pcl/ps	X		PFU4		2	2		95119674	MN
Sharp	MX-5071	753374	185909	X		pcl/ps	X		PFU4		2	2		05067794a	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Sharp	MX-5071S	33425	21648	X		PCL/PS	X		PFU4		2	2		1506220Y	TX
Sharp	MX-6070	1085999	278631	X	X	PCL/PS	X	MX-FN30	PFU4		2	2		65139604	TX
Sharp	MX-6070V	429428	134301	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		85105108	TX
Sharp	MX-6071	73530	53667	X		PCL/PS	X	MX-FN29	PFU4		2	2		15120345	MN
Sharp	MX-6071	75075	19797	X	X	PCL/PS	X	MX-FN30	PFU4		2	2		15070107	MN
Sharp	MX-6071	113828	70868	X	X	PCL/PS	X	MX-FN30	PFU4		2	2		15069817	MN
Sharp	MX-6071	125751	61907	X	X	pcl/ps	X	MX-FN30	PFU4		2	2		15069827	MN
Sharp	MX-6071	158986	128983	X		pcl/ps	X	MX-FN29	PFU4		2	2	Finisher damaged and scrapped	15120485	MN
Sharp	MX-6071	164782	82496	X	X	pcl/ps	X	MX-FN29	PFU4		2	2		15069967	MN
Sharp	MX-6071	168221	21560	X	X	PCL/PS	X	MX-FN30	PFU4		2	2		1507203Y	MN
Sharp	MX-6071	214105	149224	X		PCL/PS	X	MX-FN30	PFU4		2	2	Damaged Finisher	15070207	MN
Sharp	MX-6071	364245	117469	X	X	PCL/PS	X	MX-FN29	PFU4		2	2		95150297	MN
Sharp	MX-6071	393256	339990	X		PCL/PS	X		PFU4		2	2	Unit did not arrive with a finisher.	95046258	TX
Sharp	MX-6071	403343	315231	X	X	pcl/ps	X	MX-FN28	PFU4		2	2		0303017X	MN
Sharp	MX-6071	1094002	963602	X		PCL/PS	X		PFU4		2	2	Missing Finisher	3037451	MN
Sharp	MX-6071S	47192	39368	X	X	pcl/ps	X	MX-FN30	PFU4		2	2		1507204Y	MN
Sharp	MX-8081	286953	58557	X	X	pcl/ps	X	MX-FN34	PFU4		2	2		0300119X	MN
Sharp	MX-B350W	148304	0	X	X	PCL/PS	X		PFU2		2	2		0F006393	MN
Sharp	MX-B376W	44808	0	X	X	pcl/ps	X		PFU1		2	2		9F02617X	MN
Sharp	MX-B376W	51503	0	X	X	PCL/PS	X		Cab2		2	2		9F008358	MN
Sharp	MX-B376W	55610	0	X	X	pcl/ps	X		Cab2		2	2		9F02562X	MN
Sharp	MX-B376W	87468	0	X	X	pcl/ps	X		PFU1		2	2		9F008338	MN
Sharp	MX-B376W	88571	0	X		PCL/PS	X		PFU4		2	2		1F000677	MN
Sharp	MX-B376W	999510	0	X	X	PCL/PS	X		PFU4		2	2		9F02596X	MN
Sharp	MX-B455W	31132	0	X	X	pcl/ps	X		PFU1		2	2		9F031231	MN
Sharp	MX-B455W	81504	0	X	X	PCL/PS	X		PFU2		2	2		9F029981	MN
Sharp	MX-B455W	180911	0	X	X	PCL/PS	X		PFU2		2	2		9F031241	MN
Sharp	MX-B455W	184209	0	X	X	pcl/ps	X		PFU1		2	2		8F03056X	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Sharp	MX-B455W	192065	0	X	X	PCL/PS	X		PFU2		2	2		9F030191	MN
Sharp	MX-B476W	56224	0	X	X	PCL/PS	X		Cab2		2	2		0F012343	MN
Sharp	MX-B476W	466031	0	X	X	PCL/PS	X		PFU3		2	2		0F017014	MN
Sharp	MX-B557P	82966	0			PCL/PS			PFU1		2	2		406404001GPP2	MN
Sharp	MX-C303W	23790	13545	X	X	PCL/PS	X		Cab2		2	2		03020445a	MN
Sharp	MX-C303W	255464	3692	X	X	PCL/PS	X		Cab2		2	2		03010859a	TX
Sharp	MX-C304W	33459	6654	X	X	pcl/ps	X		PFU1		2	2		03021265a	MN
Sharp	MX-C304WH	20601	16643	X	X	PCL/PS	X		PFU1		2	2		23013417	MN
Sharp	MX-C402SC	125555	20195	X		PCL/PS	X		Cab2		2	2		85000255	TX
Sharp	MX-C407F	3111	1223	X	X	pcl/ps	X		PFU1		2	2		75281140H639F	MN
Sharp	MX-C407F	3487	1948	X	X	PCL/PS	X		PFU1		2	2		75281230H67X0	MN
Sharp	MX-C407F	3531	2670	X		PCL/PS	X		PFU1		2	2	Screen Scratched	75281230H67ZM	MN
Sharp	MX-C407F	6841	5404	X	X	pcl/ps	X		PFU1		2	2		75281230H680H	MN
Sharp	MX-C407F	8116	4355	X	X	pcl/ps	X		PFU1		2	2		75281140H639Z	MN
Sharp	MX-C407F	17986	10819	X	X	PCL/PS	X		PFU1		2	2		75281230H67X6	MN
Sharp	MX-C407F	18975	14500	X		PCL/PS	X		PFU1		2	2		75281140H639K	MN
Sharp	MX-C407F	33998	17500	X	X	PCL/PS	X		PFU1		2	2		75280530H5W7G	MN
Sharp	MX-C407F	54847	18949	X	X	PCL/PS	X		PFU1		2	2	Screen will not stay up	75281230H67XY	MN
Sharp	MX-C407F	71366	31029	X	X	pcl/ps	X		PFU1		2	2		75281230H680C	MN
Sharp	MX-C507F	5409	5117	X	X	PCL/PS	X		PFU1		2	2		75282390H76C8	MN
Sharp	MX-C507F	28713	26292	X		PCL/PS	X		PFU2		2	2		75281450H6L7P	TX
Sharp	MX-C507F	118346	45343	X	X	PCL/PS	X		PFU2		2	2		75282120H6WCM	MN
Sharp	MX-C507P	1744	1211	X		PCL/PS			PFU1		2	2		50281140H5BDT	TX
Sharp	MX-M2630	115498	0	X	X	PCL	X		Cab2		2	2		85002598	MN
Sharp	MX-M2630	141832	0	X	X	PCL/PS	X		Cab2		2	2		85002488	MN
Sharp	MX-M2630	173404	0	X	X	pcl	X		Cab2		2	2		85002498	MN
Sharp	MX-M2651	7865	0	X	X	pcl/ps	X	Internal	Cab2		2	2		13002490	MN
Sharp	MX-M2651	69514	0	X	X	PCL/PS	X		Cab2		2	2		9300038Y	TX
Sharp	MX-M2651	87325	0	X	X	PCL/PS	X		Cab2		2	2		03001512a	TX
Sharp	MX-M2651	93181	0	X	X	PCL/PS	X		Cab2		2	2		9300178Y	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Sharp	MX-M2651	241471	0	X		PCL/PS	X		Cab2		2	2		0302743X	TX
Sharp	MX-M2651		0	X		PCL/PS	X		Cab2		2	2		95014060	TX
Sharp	MX-M3051	28065	0	X	X	PCL/PS	X		Cab2		2	2		1300133X	TX
Sharp	MX-M3051	49776	0	X	X	pcl/ps	X	Internal	Cab2		2	2		03001953a	MN
Sharp	MX-M3070	57808	0	X		PCL/PS	X	Internal	PFU4		2	2		95010362	MN
Sharp	MX-M3070	59734	0	X	X	PCL/PS	X		PFU4		2	2		85006649	MN
Sharp	MX-M3070	86581	0	X	X	pcl/ps	X		PFU4		2	2		85007109	MN
Sharp	MX-M3070	131278	0	X	X	PCL/PS	X		PFU4		2	2		8501549X	MN
Sharp	MX-M3070	254550	0	X		PCL/PS	X		PFU4		2	2		7500349Y	MN
Sharp	MX-M3070	347514	0	X		PCL/PS	X		PFU4		2	2		85005900	MN
Sharp	MX-M3071	77715	0	X		PCL/PS	X		Cab2		2	2		9500415X	MN
Sharp	MX-M3071	295207	0	X		pcl/ps	X		PFU4		2	2		15022607	MN
Sharp	MX-M3071	327003	0	X		PCL/PS	X		Cab2		2	2		03003231a	MN
Sharp	MX-M3551	14621	0	X		PCL/PS	X		PFU3		2	2		15016898	TX
Sharp	MX-M3551	21777	0	X	X	PCL/PS	X		PFU3		2	2		15016858	TX
Sharp	MX-M3551	27995	0	X	X	PCL/PS	X		PFU3		2	2		15016868	TX
Sharp	MX-M3551	41451	0	X		PCL/PS	X		PFU3		2	2		15016908	TX
Sharp	MX-M3551	163983	0	X	X	PCL/PS	X		PFU3		2	2		15012516	TX
Sharp	MX-M3551	175259	0	X	X	PCL/PS	X		PFU3		2	2		15016878	TX
Sharp	MX-M3551	210377	0	X		PCL/PS	X		PFU3		2	2		15016958	TX
Sharp	MX-M3551		0	X		PCL/PS	X		PFU3		2	2		0304597X	TX
Sharp	MX-M3571	67587	0	X	X	PCL/PS	X		Cab2		2	2	User Authenticati on	15018617	MN
Sharp	MX-M3571	179228	0	X		PCL/PS	X	Internal	PFU4		2	2		9500762X	MN
Sharp	MX-M3571	205807	0	X		PCL/PS	X	Internal	PFU4		2	2		9500681X	MN
Sharp	MX-M3571	235779	0	X		PCL/PS	X	Internal	PFU4		2	2		9500788X	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Sharp	MX-M3571	244432	0	X		PCL/PS	X	Internal	PFU4		2	2		9500773X	MN
Sharp	MX-M3571	307334	0	X		PCL/PS	X	Internal	PFU4		2	2		9500774X	MN
Sharp	MX-M3571	308910	0	X		PCL/PS	X		PFU4		2	2		1300504Y	MN
Sharp	MX-M3571	355583	0	X		PCL/PS	X		PFU4		2	2		9301019Y	MN
Sharp	MX-M3571	429111	0	X		PCL/PS	X	Internal	PFU4		2	2		9500793X	MN
Sharp	MX-M3571	536848	0	X		PCL/PS	X	Internal	PFU4		2	2		9500779X	MN
Sharp	MX-M3571	620683	0	X		PCL/PS	X	Internal	PFU4		2	2		9500691X	MN
Sharp	MX-M4051	167773	0	X	X	pcl/ps	X	Internal	Cab2		2	2		15016988	MN
Sharp	MX-M4051	220650	0	X	X	PCL/PS	X	Internal	PFU4		2	2		15017187	MN
Sharp	MX-M4070	258375	0	X	X	pcl/ps	X		PFU4		2	2		95016582	MN
Sharp	MX-M4071	61081	0	X		PCL/PS	X		PFU4		2	2		13014450	MN
Sharp	MX-M4071	82986	0	X	X	PCL/PS	X	Internal	PFU4		2	2		03009401a	MN
Sharp	MX-M4071	137456	0	X	X	pcl/ps	X	Internal	PFU4		2	2		0303717X	MN
Sharp	MX-M4071	337614	0	X	X	PCL/PS	X	Internal	PFU4		2	2		95031389	MN
Sharp	MX-M4071	569524	0	X	X	PCL/PS	X		PFU4		2	2	Left Side Panel Missing Screws	95026738	MN
Sharp	MX-M464N	141990	0	X	X	pcl	X		Cab2		2	2		4501963Y	MN
Sharp	MX-M5051	651513	0	X		PCL	X		PFU4		2	2	Yellowed/Dirt	15013927	MN
Sharp	MX-M5070	522442	0	X	X	pcl/ps	X	Internal	PFU4		2	2		85013523	MN
Sharp	MX-M5070	899532	0	X	X	PCL/PS	X		PFU4		2	2		7501546Y	MN
Sharp	MX-M5071	121745	0	X	X	PCL/PS	X		PFU4		2	2		03057789a	MN
Sharp	MX-M5071	266098	0	X		PCL/PS	X		Cab2		2	2		03013175a	MN
Sharp	MX-M5071	475885	0	X		pcl/ps	X		PFU4		2	2		0302189X	MN
Sharp	MX-M5071	685527	0	X		PCL/PS	X	Internal	PFU4		2	2		5017163	MN
Sharp	MX-M5071	786296	0	X	X	PCL/PS	X		PFU4		2	2		95031678	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Sharp	MX-M6070	544182	0	X	X	pcl/ps	X		PFU4		2	2		8501075X	MN
Sharp	MX-M6071	346976	0	X		PCL/PS	X		PFU4		2	2		95043720	MN
Sharp	MX-M6071	482318	0	X	X	PCL/PS	X		PFU4		2	2		9501745X	MN
Sharp	MX-M6071	500021	0	X		PCL/PS	X		PFU4		2	2		0304314X	MN
Sharp	MX-M6071	630028	0	X		PCL/PS	X		PFU4		2	2		23013102	MN
Sharp	MX-M6071	707885	0	X		PCL/PS	X	MX-FN30	PFU4		2	2		95041578	TX
Sharp	MX-M7570	181904	0	X		pcl/ps	X	MX-FN34	PFU4		2	2	Missing waste toner door. Have to manually trip sensor.	13002573	MN
Sharp	MX-M7570	254935	0	X		PCL/PS	X	MX-FN30	PFU3		2	2		0300187X	TX
Sharp	MX-M7570	524286	0	X		PCL/PS	X	MX-FN34	PFU3		2	2		03001929a	TX
Sharp	MX-M7570	534676	0	X	X	PCL/PS	X	MX-FN34	PFU3		2	2		13001668	TX
Toshiba	E-2010AC	64865	39920	X		pcl/ps	X	Internal	PFU3		2	2		CNLL29005	MN
Toshiba	E-2010AC	74523	70117	X		PCL/PS	X		Cab2		2	2		CNFK16096	TX
Toshiba	E-2010AC	103554	97602	X		PCL/PS	X		Cab2		2	2		CNEJ18913	TX
Toshiba	E-2010AC	110971	96699	X		PCL/PS	X		Cab2		2	2		CNKJ17146	MN
Toshiba	E-2018A	16898	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZDL19490	MN
Toshiba	E-2018A	21329	0	X		pcl/ps	X	Internal	PFU3		2	2		CZEJ55296	MN
Toshiba	E-2018A	44662	0	X		PCL/PS	X	Internal	PFU3		2	2		CZDJ51770	MN
Toshiba	E-2018A	47085	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZLK66341	MN
Toshiba	E-2018A	49193	0	X		PCL/PS	X	Internal	PFU3		2	2		CZAK32079	MN
Toshiba	E-2018A	49526	0	X		PCL/PS	X		Cab2		2	2		CZBJ42848	MN
Toshiba	E-2018A	51190	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZAL10830	MN
Toshiba	E-2018A	76011	0	X		PCL/PS	X		PFU4		2	2		CZGJ62111	MN
Toshiba	E-2018A	92523	0	X		PCL/PS	X	Internal	Cab2		2	2		CZAL10874	MN
Toshiba	E-2018A	94849	0	X		PCL/PS	X	Internal	Cab2		2	2		CZGL27533	MN
Toshiba	E-2018A	102444	0	X		pcl/ps	X		Cab2		2	2		CZGL27544	MN
Toshiba	E-2018A	104440	0	X		PCL/PS	X	Internal	PFU3		2	2		CZAK32097	MN
Toshiba	E-2018A	175409	0	X		PCL/PS	X	Internal	PFU3		2	2		CZEJ55224	MN
Toshiba	E-2018A	192658	0	X		PCL/PS	X	Internal	PFU3		2	2		CZDJ51727	MN
Toshiba	E-2018A	210636	0	X		pcl/ps	X	Internal	PFU3		2	2		CZEJ55265	MN
Toshiba	E-2018A	399544	0	X		pcl/ps	X	Internal	PFU3		2	2		CZEJ55240	MN
Toshiba	E-2018A	460504	0	X		PCL/PS	X	Internal	PFU3		2	2		CZEJ55278	MN
Toshiba	E-2515AC	19905	5551	X	X	PCL/PS	X	Internal	Cab2		2	2		CNFL61449	MN
Toshiba	E-2515AC	24344	10808	X	X	PCL/PS	X	Internal	PFU3		2	2		CNFL61376	MN
Toshiba	E-2515AC	27886	10529	X		PCL/PS	X		PFU4		2	2		CNFJ59643	MN
Toshiba	E-2515AC	34216	17086	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCL47508	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Toshiba	E-2515AC	40045	25514	X	X	PCL/PS	X	Internal	PFU3		2	2		CNFL61494	MN
Toshiba	E-2515AC	66260	26074	X		PCL/PS	X		PFU3		2	2		CNKJ50535	TX
Toshiba	E-2515AC	67264	37259	X		pcl/ps	X		PFU3		2	2		CNEM34379	MN
Toshiba	E-2515AC	116964	64311	X		pcl/ps	X	Internal	PFU3		2	2		CNDK32107	MN
Toshiba	E-2515AC	153574	63122	X		PCL/PS	X	Internal	PFU4		2	2		CNIH40991	MN
Toshiba	E-2515AC	218139	140199	X	X	PCL/PS	X		Cab2		2	2		CNJL43230	TX
Toshiba	E-2515AC	224095	63405	X		PCL/PS	X	Internal	PFU3		2	2		CNCK69394	MN
Toshiba	E-2518A	102219	0	X		PCL/PS	X	Internal	PFU3		2	2		CZDJ52363	MN
Toshiba	E-2518A	139962	0	X		pcl/ps	X	Internal	PFU3		2	2		CZDJ52308	MN
Toshiba	E-2518A	190580	0	X		PCL/PS	X	Internal	PFU4		2	2		CZDJ52307	MN
Toshiba	E-2518A	230830	0	X		PCL/PS	X	Internal	PFU4		2	2		CZDJ52283	MN
Toshiba	E-2518A	292858	0	X		PCL/PS	X	Internal	PFU4		2	2		CZDJ52306	MN
Toshiba	E-2518A	296493	0	X		PCL/PS	X	Internal	PFU4		2	2		CZDJ52365	MN
Toshiba	E-2518A	451667	0	X		PCL/PS	X	Internal	PFU4		2	2		CZDJ52275	MN
Toshiba	E-2518A	583020	0	X		PCL/PS	X	Internal	PFU3		2	2		CZDJ52349	MN
Toshiba	E-2518A		0	X		PCL/PS	X		Cab2		2	2		CZIJ14998	TX
Toshiba	E-2822AF	4734	0	X	X	PCL/PS	X		PFU1		2	2	Passed copy but no image	CKLL23754	MN
Toshiba	E-2822AF	33208	0	X	X	PCL	X		PFU1		2	2		CKGL21401	MN
Toshiba	E-2822AF	89744	0	X	X	PCL	X		PFU1		2	2		CKGL21506	MN
Toshiba	E-3005AC	105771	47912	X		pcl/ps	X	MJ-1109	PFU3		2	2		CFLG69420	MN
Toshiba	E-3005AC	179583	39736	X	X	pcl/ps	X		PFU3		2	2		CFCH43747	MN
Toshiba	E-3005AC	465578	10160	X	X	PCL/PS	X		PFU3		2	2		CFCH43754	TX
Toshiba	E-3015AC	59947	5975	X	X	pcl/ps	X		Cab2		2	2		CNLJ57475	MN
Toshiba	E-3015AC	60000	22004	X	X	PCL/PS	X		PFU4		2	2		CNHL32582	TX
Toshiba	E-3015AC	60494	0	X		PCL/PS	X		PFU3		2	2		CNJJ40133	MN
Toshiba	E-3015AC	105646	74077	X		PCL/PS	X		Cab2		2	2		CNDK32848	TX
Toshiba	E-3015AC	123111	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCJ37999	MN
Toshiba	E-3015AC	199107	131829	X		pcl/ps	X	MJ-1110	PFU4		2	2	MJ-6105N	CNCK31128	MN
Toshiba	E-3015AC	268217	147537	X	X	PCL/PS	X	MJ-1109	Cab2		2	2		CNLJ59667	TX
Toshiba	E-3015AC	311023	223648	X		pcl/ps	X	Internal	Cab2		2	2		CNHK50556	MN
Toshiba	E-3015AC	315474	60908	X		PCL/PS	X		PFU4		2	2		CNLJ55695	TX
Toshiba	E-3018A	73241	0	X		pcl/ps	X		Cab2		2	2		CZLH33614	MN
Toshiba	E-3018A	110886	0	X		pcl/ps	X	Internal	Cab2		2	2		CZLJ29118	MN
Toshiba	E-3505AC	230915	139959	X		PCL/PS	X	MJ-1109	PFU3		2	2		CFFF36306	TX
Toshiba	E-3508A	180642	0	X	X	PCL/PS	X		PFU3		2	2		CGEF16686	MN
Toshiba	E-3515AC	37733	16436	X	X	PCL/PS	X		Cab2		2	2		CNGJ63675	TX
Toshiba	E-3515AC	48168	5009	X		PCL/PS	X		PFU3		2	2		CNKJ52766	TX
Toshiba	E-3515AC	54893	17179	X	X	PCL/PS	X	Internal	PFU3		2	2		SNLK84920	MN
Toshiba	E-3515AC	66814	24825	X	X	PCL/PS	X	Internal	PFU3		2	2		SNLK84820	MN
Toshiba	E-3515AC	73256	36239	X	X	PCL/PS	X		PFU3		2	2		SNFL87992	TX
Toshiba	E-3515AC	86573	36031	X	X	pcl/ps	X	MJ-1110	PFU3		2	2		CNLJ55913	MN
Toshiba	E-3515AC	95287	23891	X		PCL/PS	X		PFU3		2	2		SNIL89177	MN
Toshiba	E-3515AC	108435	73225	X		PCL/PS	X		PFU3		2	2		CNHK52504	TX
Toshiba	E-3515AC	118777	47880	X		PCL/PS	X	MJ-1109B	PFU3		2	2		CNAM61353	MN
Toshiba	E-3515AC	125799	28103	X	X	PCL/PS	X	MJ-1109B	PFU3		2	2		SNLK84781	MN
Toshiba	E-3515AC	131900	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CNAM61331	MN
Toshiba	E-3515AC	135109	71891	X	X	PCL/PS	X		PFU3		2	2		CNGK44962	TX
Toshiba	E-3515AC	144604	6416	X		PCL/PS	X		Cab2		2	2		CNCK68621	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Toshiba	E-3515AC	161587	53195	X	X	KPDL/PCL	X		PFU3		2	2		CNB333411	MN
Toshiba	E-3515AC	168121	36771	X		pcl/ps	X	MJ-1109	PFU3		2	2	MJ-6105N	CNGK44279	MN
Toshiba	E-3515AC	186715	13005	X	X	PCL/PS	X		Cab2		2	2		CNDJ43100	TX
Toshiba	E-3515AC	200110	130509	X	X	PCL/PS	X	MJ-1109-B	PFU3		2	2		CNHK52609	TX
Toshiba	E-3515AC	223654	111753	X		PCL/PS	X	MJ-1109B	PFU3		2	2		CNAM61359	MN
Toshiba	E-3515AC	258226	29768	X	X	PCL/PS	X		PFU3		2	2		SNBL86054	MN
Toshiba	E-3515AC	295503	156889	X	X	pcl/ps	X		PFU3		2	2	Arrived without finisher	CNBM30790	MN
Toshiba	E-3515AC	323219	95160	X		PCL/PS	X	Internal	PFU3		2	2		CNDK33509	MN
Toshiba	E-3515AC	341655	97965	X		PCL/PS	X	Internal	PFU3		2	2		SNFL87717	MN
Toshiba	E-3515AC	376116	82757	X	X	PCL/PS	X	MJ-1109	PFU3		2	2		CNHK52598	TX
Toshiba	E-3515AC	490250	211312	X		pcl/ps	X	Internal	PFU3		2	2		CNDK33333	MN
Toshiba	E-3515AC	510452	123036	X		PCL/PS	X	Internal	PFU3		2	2		CNCK31249	MN
Toshiba	E-3518A	10767	0	X		PCL/PS	X		Cab2		2	2		CZJL39627	TX
Toshiba	E-3518A	26870	0	X	X	PCL/PS	X		Cab2		2	2		CZJL39568	TX
Toshiba	E-3518A	33631	0	X	X	PCL/PS	X		PFU3		2	2		CZHK50633	TX
Toshiba	E-3518A	38505	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZDL17412	MN
Toshiba	E-3518A	39039	0	X		PCL/PS	X		PFU3		2	2		CZCK35724	TX
Toshiba	E-3518A	47669	0	X		PCL/PS	X		Cab2		2	2		CZBJ44743	TX
Toshiba	E-3518A	51682	0	X		PCL/PS	X		Cab2		2	2		CZJL39572	TX
Toshiba	E-3518A	52099	0	X		pcl/ps	X		Cab2		2	2		CZGJ64753	MN
Toshiba	E-3518A	54784	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZAL11620	MN
Toshiba	E-3518A	64849	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZCL15117	MN
Toshiba	E-3518A	69235	0	X	X	PCL/PS	X		Cab2		2	2		CZJL39633	TX
Toshiba	E-3518A	70185	0	X		PCL/PS	X		Cab2		2	2		CZJL39419	TX
Toshiba	E-3518A	71522	0	X	X	PCL/PS	X		Cab2		2	2		CZJL41641	TX
Toshiba	E-3518A	72446	0	X		pcl/ps	X	Internal	PFU3		2	2		CZCJ44770	MN
Toshiba	E-3518A	90620	0	X		PCL/PS	X		Cab2		2	2		CZJL39626	TX
Toshiba	E-3518A	92281	0	X		PCL/PS	X	Internal	PFU3		2	2		CZCK33842	MN
Toshiba	E-3518A	96301	0	X	X	PCL/PS	X		Cab2		2	2		CZJL39519	TX
Toshiba	E-3518A	116220	0	X	X	PCL/PS	X		Cab2		2	2		CZJL39555	TX
Toshiba	E-3518A	136869	0	X		pcl/ps	X	Internal	PFU3		2	2		CZCK33979	MN
Toshiba	E-3518A	163571	0	X		PCL/PS	X	Internal	PFU3		2	2		CZGL31107	MN
Toshiba	E-3518A	182310	0	X	X	PCL/PS	X		PFU3		2	2		CZGJ66335	MN
Toshiba	E-3518A	213227	0	X		PCL/PS	X		PFU3		2	2		CZCK35585	TX
Toshiba	E-3518A	215541	0	X	X	PCL/PS	X		PFU3		2	2		CZIK53262	TX
Toshiba	E-3518A	216066	0	X		PCL/PS	X		Cab2		2	2		CZDJ50488	TX
Toshiba	E-3518A	221817	0	X		PCL/PS	X	Internal	PFU3		2	2		CZCK33971	MN
Toshiba	E-3518A	226204	0	X	X	PCL/PS	X		PFU3		2	2		CZIK53267	TX
Toshiba	E-3518A	232698	0	X		PCL/PS	X	Impact	PFU3		2	2		CZCK35458	MN
Toshiba	E-3518A	248857	0	X		PCL/PS	X	Internal	PFU3		2	2		CZCK33956	MN
Toshiba	E-3518A	251527	0	X		PCL/PS	X	Internal	PFU3		2	2		CZCJ44797	MN
Toshiba	E-3518A	258572	0	X		PCL/PS	X	Internal	PFU3		2	2		CZIL37094	MN
Toshiba	E-3518A	324238	0	X		pcl/ps	X	Internal	PFU3		2	2		CZCK33881	MN
Toshiba	E-3518A	330177	0	X	X	PCL/PS	X		PFU3		2	2		CZHK50731	TX
Toshiba	E-3518A	336935	0	X		pcl/ps	X		PFU3		2	2		CZCK35590	MN
Toshiba	E-3518A	359727	0	X		PCL/PS	X		Cab2		2	2		CZJL10525	TX
Toshiba	E-3518A	476707	0	X	X	PCL/PS	X		PFU3		2	2		CZCK35561	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Toshiba	E-3518A	488620	0	X	X	pcl/ps	X		PFU3		2	2		CZCK35609	MN
Toshiba	E-3518A	518587	0	X		PCL/PS	X		PFU3		2	2		CZCK35591	MN
Toshiba	E-3518A	560314	0	X		PCL/PS	X	Internal	PFU3		2	2		CZCJ44803	MN
													Empty toner container. Tested with external supplies.		
Toshiba	E-3518A	592655	0	X	X	pcl/ps	X	Internal	PFU4		2	2		CZBJ44735	MN
Toshiba	E-3518A	605042	0	X		pcl/ps	X	Internal	PFU3		2	2		CZBJ44753	MN
Toshiba	E-3518A	658409	0	X		PCL/PS	X	Internal	PFU4		2	2		CZBJ44723	MN
Toshiba	E-3518A	766162	0	X	X	PCL/PS	X		PFU3		2	2		CZCK35593	MN
Toshiba	E-3555C	160132	114534	X	X	PCL/PS	X	MJ-1108	PFU3		2	2		C7AE39926	MN
Toshiba	E-389cs	35279	150	X	X	PCL/PS	X		PFU1		2	2		75288460F38R8	TX
Toshiba	E-389cs	111084	89397	X	X	pcl/ps	X		Cab2		2	2		75289310F493B	MN
Toshiba	E-4505AC	69840	54365	X	X	pcl/ps	X	MJ-1109	PFU3		2	2	MJ-6105N	CFEG67182	MN
													Arrived without finisher		
Toshiba	E-4505AC	349987	160229	X	X	pcl/ps	X		PFU3		2	2		CFKG61542	MN
Toshiba	E-4505AC	427820	180929	X		PCL/PS	X		PFU3		2	2		CFAG42162	TX
Toshiba	E-4515AC	46542	25316	X		pcl/ps	X		PFU3		2	2		CNAM64842	MN
													Empty toner. Tested with other supplies.		
Toshiba	E-4515AC	49794	0	X	X	pcl/ps	X	MJ-1109	PFU3		2	2		CNJJ42877	MN
Toshiba	E-4515AC	54736	48024	X		PCL/PS	X		PFU3		2	2		CNGK47314	TX
Toshiba	E-4515AC	62071	24012	X	X	PCL/PS	X	Internal	PFU3		2	2		SNDL87280	MN
Toshiba	E-4515AC	79726	32879	X	X	pcl/ps	X	MJ-1109	PFU3		2	2		CNCK31457	MN
													Arrived without finisher		
Toshiba	E-4515AC	83075	39980	X		pcl/ps	X		PFU3		2	2		CNLJ56317	MN
Toshiba	E-4515AC	98547	72544	X	X	PCL/PS	X		PFU4		2	2		CNJH46941	TX
Toshiba	E-4515AC	109828	46656	X	X	PCL/PS	X	Internal	PFU3		2	2		SNDL87265	MN
Toshiba	E-4515AC	110135	99177	X	X	PCL/PS	X	Internal	PFU3		2	2		CNEL60571	MN
Toshiba	E-4515AC	110323	89572	X	X	PCL/PS	X		PFU3		2	2		SNAL85984	TX
Toshiba	E-4515AC	117792	20123	X	X	PCL/PS	X	Internal	PFU3		2	2		SNDL87165	MN
Toshiba	E-4515AC	131073	85947	X		pcl/ps	X		Cab2		2	2		CNJJ43077	MN
Toshiba	E-4515AC	133337	33914	X	X	pcl/ps	X	MJ-1109	PFU3		2	2		CNJJ39270	MN
													Arrived without finisher		
Toshiba	E-4515AC	157474	66651	X		pcl/ps	X		PFU4		2	2		CNIJ36003	MN
Toshiba	E-4515AC	166023	8730	X	X	PCL/PS	X	MJ-1109B	PFU3		2	2		CNJJ43428	MN
Toshiba	E-4515AC	174385	48758	X		PCL/PS	X		Cab2		2	2		CNDL53512	TX
Toshiba	E-4515AC	179687	101625	X	X	PCL/PS	X	Internal	PFU3		2	2		CNHL33352	MN
Toshiba	E-4515AC	180606	61773	X	X	PCL/PS	X	MJ-1109	PFU3		2	2		CNHK51833	MN
													Arrived without finisher		
Toshiba	E-4515AC	181632	151897	X		pcl/ps	X		PFU3		2	2		CNLJ56307	MN
Toshiba	E-4515AC	182335	83389	X		pcl/ps	X	MJ-1110	PFU3		2	2		CNIK58674	MN

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Toshiba	E-4515AC	196322	84964	X		PCL/PS	X		PFU3		2	2		CNHH35764	TX
Toshiba	E-4515AC	206372	455	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		SNKK84538	TX
Toshiba	E-4515AC	217578	138131	X		PCL/PS	X	MJ-1109B	PFU3		2	2		CNLL59122	MN
Toshiba	E-4515AC	219608	114491	X		PCL/PS	X	MJ-1109B	PFU3		2	2	MJ-6105N	SNHL88815	MN
Toshiba	E-4515AC	226329	9690	X	X	pcl/ps	X	MJ-1109	PFU3		2	2		CNCK31495	MN
Toshiba	E-4515AC	281079	167724	X	X	PCL/PS	X		PFU3		2	2		CNLJ60167	TX
Toshiba	E-4515AC	356121	189848	X	X	PCL/PS	X		Cab2		2	2		CNGK44483	TX
Toshiba	E-4515AC	407078	143284	X		pcl/ps	X	Internal	PFU3		2	2		CNDJ44422	MN
Toshiba	E-4515AC	549479	187809	X		PCL/PS	X		PFU3		2	2		SNKK84200	TX
Toshiba	E-4515AC	594420	143867	X		pcl/ps	X	Internal	PFU3		2	2		CNCK31728	MN
													toner cartridges were replaced before the old ones were empty did not arrive with finisher		
Toshiba	E-4515AC	717622	341891	X	X	PCL/PS	X		PFU3		2	2		CNEJ51886	TX
Toshiba	E-4515AC	747097	346814	X		PCL/PS	X	Internal	PFU4		2	2		CNDJ44404	MN
Toshiba	E-4518A	44400	0	X	X	PCL/PS	X		Cab2		2	2		CZIL37290	TX
Toshiba	E-4518A	61237	0	X		PCL/PS	X	MJ-1109B	PFU3		2	2		CZKL45630	MN
Toshiba	E-4518A	170316	0	X		PCL/PS	X	Internal	PFU3		2	2		CZCK35348	MN
Toshiba	E-4518A	185915	0	X		PCL/PS	X		PFU3		2	2		CZDK36476	TX
Toshiba	E-4518A	371042	0	X		PCL/PS	X	Internal	PFU4		2	2		CZJL39716	MN
													Unable to remove user authentication, still prints.		
Toshiba	E-4518A	461264	0	X		PCL/PS	X	Internal	PFU3		2	2		CZAK31970	MN
													PFU1 hard to open.		
Toshiba	E-4518A	585015	0	X	X	pcl/ps	X	Internal	PFU3		2	2		CZIJ13922	MN
Toshiba	E-4518A	1214837	0	X		PCL/PS	X	Internal	PFU3		2	2		CZDJ50731	MN
Toshiba	E-4525AC	104749	63152	X	X	pcl/ps	X	MJ-1113	PFU4		2	2	MJ-6107N	CSHN60907	MN
Toshiba	E-457	209036	0	X	X	PCL/PS	X		Cab2		2	2		CEJE40376	TX
Toshiba	E-457	248789	0	X		PCL/PS	X		Cab2		2	2		CEJE40578	TX
Toshiba	E-478s	27909	0	X		PCL/PS	X		PFU1		2	2		701811740D9PF	TX
Toshiba	E-478s	387433	0	X	X	PCL/PS	X		PFU1		2	2		701813040F0FW	TX
Toshiba	E-5015AC	76675	52097	X	X	PCL/PS	X		PFU3		2	2		SNIL71796	TX
Toshiba	E-5015AC	90061	73318	X	X	PCL/PS	X		PFU3		2	2		SNHL71749	TX
Toshiba	E-5015AC	110284	97583	X	X	PCL/PS	X	MJ-1109-B	PFU4		2	2		SNFK71040	TX
Toshiba	E-5015AC	273947	152499	X	X	PCL/PS	X		PFU3		2	2		CNEJ48488	TX
Toshiba	E-5015AC	333663	206243	X	X	PCL/PS	X	MJ-1109	PFU3		2	2		CNKK66315	TX
Toshiba	E-5015AC	365342	75424	X	X	PCL/PS	X		PFU3		2	2		CNEL59528	TX
Toshiba	E-5018A	166612	0	X	X	PCL/PS	X		Cab2		2	2		CZJL41090	TX
Toshiba	E-5018A	804111	0	X	X	pcl/ps	X		PFU3		2	2		SZCK70957	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Toshiba	E-507	321282	0	X	X	PCL/PS	X		Cab2		2	2		SELF91286	TX
Toshiba	E-5506AC	581408	321122	X		pcl/ps	X		PFU3		2	2	Arrived W/O Finisher	CHCH26131	MN
Toshiba	E-5506AC	695136	403518	X	X	PCL/PS	X	MJ-1110	PFU3		2	2		CHJF12309	TX
Toshiba	E-5508A	1432777	0	X		PCL/PS	X	MJ-1111	PFU3		2	2		CIIG22745	TX
Toshiba	E-5516AC	196814	131257	X		pcl/ps	X	MJ-1111	PFU3		2	2		C1BN40805	MN
Toshiba	E-5516AC	255343	129298	X	X	PCL/PS	X	MJ-1111B	PFU3		2	2		C1GL30839	MN
Toshiba	E-5516AC	339343	157428	X		pcl/ps	X	MJ-1111	PFU3		2	2		C1EM36197	MN
Toshiba	E-5516AC	366768	140392	X		PCL/PS	X	MJ-1111B	PFU3		2	2	MJ-6106N	C1DJ14774	MN
Toshiba	E-5516AC	523505	26972	X	X	pcl/ps	X	MJ-1111	PFU4		2	2	Poor image quality. MJ-6106N	C1CK22878	MN
Toshiba	E-5516AC	528556	383082	X		pcl/ps	X	MJ-1111	PFU4		2	2	MJ-6106N	C1IL31796	MN
Toshiba	E-5516AC	552454	131184	X	X	pcl/ps	X	MJ-1111	PFU3		2	2		C1DJ15078	MN
Toshiba	E-5516AC	590228	120269	X		pcl/ps	X	MJ-1111	PFU3		2	2	MJ-6106N	C1DK23134	MN
Toshiba	E-5516AC	639769	247075	X		pcl/ps	X	MJ-1111	PFU3		2	2	MJ-6106N	C1DJ14801	MN
Toshiba	E-5516AC	663804	226656	X		PCL/PS	X	MJ-1111B	PFU3		2	2	MJ-6106N	C1DJ14781	MN
Toshiba	E-5516AC	818803	232492	X		PCL/PS	X	MJ-1111B	PFU3		2	2	MJ-6106N	C1DJ14780	MN
Toshiba	E-5516AC	839177	150008	X		PCL/PS	X	MJ-1111-B	PFU3		2	2		C1BK22177	MN
Toshiba	E-5516AC	914387	266300	X		pcl/ps	X	MJ-1111	PFU3		2	2	MJ-6106N. Poor image quality.	C1FJ15811	MN
Toshiba	E-5516AC	1441431	283302	X		PCL/PS	X	MJ-1111B	PFU3		2	2	MJ-6106N	C1DJ14771	MN
Toshiba	E-5518A	130657	0	X		pcl/ps	X		PFU3		2	2	Arrived without finisher	C2GL32956	MN
Toshiba	E-5518A	301800	0	X	X	pcl/ps	X	MJ-1111	PFU3		2	2		C2DL31302	MN
Toshiba	E-5518A	708302	0	X	X	PCL/PS	X	MJ-1111-B	PFU3		2	2		C2GK27065	TX
Toshiba	E-6516AC	246276	163832	X	X	PCL/PS	X	MJ-1110-B	PFU3		2	2		C1FL30460	TX
Toshiba	E-6518A	466518	0	X		PCL/PS	X	MJ-1111	PFU3		2	2		C2GL33233	TX
Toshiba	E-6518A	957329	0	X		PCL/PS	X	Exit Tray	PFU3		2	2		C2JJ20983	MN
Toshiba	E-6518A	968765	0	X		PCL/PS	X	MJ-1111	PFU3		2	2		C2EJ16563	TX
Toshiba	E-7506AC	1550667	272636	X		PCL/PS	X		PFU3		2	2	Arrived W/O Finisher	CHFG19186	MN
Toshiba	E-7516AC	463144	248210	X	X	pcl/ps	X		PFU3		2	2		C1GM37481	MN
Toshiba	E-7516AC	601308	225625	X	X	PCL/PS	X	MJ-1111-B	PFU3	MP-2502L-B	2	2		C1EL30128	TX
Toshiba	E-7516AC	627646	421885	X	X	PCL/PS	X	MJ-1111-B	PFU3	MP-2502L-B	2	2		C1CL28820	TX
Toshiba	E-7516AC	1328385	1307100	X		PCL/PS	X		PFU4		2	2		C1FJ16226	TX
Toshiba	E-7516AC	1603262	590208	X		PCL/PS	X	MJ-1111	PFU3		2	2		S1FJ90127	TX
Toshiba	E-7516AC	1612717	428134	X		PCL/PS	X	MJ-1112B	PFU3		2	2	MJ-6106N	S1LJ90384	MN
Xerox	AL B8055	145572	0	X		PCL/PS	X	BFO-1	PFU4		2	2		Y4X932682	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Xerox	AL B8055	512561	0	X		PCL/PS	X		PFU4		2	2		Y4X830786	TX
Xerox	AL B8155	883799	0	X		PCL/PS	X	A-FN21	PFU4		2	2		HQH260881	TX
Xerox	AL C8030	37799	19888	X		PCL/PS	X	A-FN07	PFU4		2	2		3TX417769	TX
Xerox	AL C8030	312667	144262	X		PCL/PS	X		PFU4		2	2		2TX066963	TX
Xerox	AL C8035	46100	31720	X		PCL/PS	X	HFN-2	PFU4		2	2		2TX073233	TX
Xerox	AL C8035	53941	35817	X		PCL/PS	X		PFU4		2	2		2TX069569	TX
Xerox	AL C8035	61703	36658	X	X	PCL/PS	X	HFN-2	PFU4		2	2		2TX074538	TX
Xerox	AL C8035	92957	64899	X		PCL/PS	X		PFU4		2	2		2TX072483	TX
Xerox	AL C8035	102399	32714	X	X	PCL/PS	X		PFU4		2	2		2TX072912	TX
Xerox	AL C8035	104204	63133	X	X	PCL/PS	X		PFU4		2	2		2TX072801	MN
Xerox	AL C8035	107385	73974	X	X	PCL/PS	X	HFN-2	PFU4		2	2		2TX074482	TX
Xerox	AL C8035	128238	103416	X		pcl/ps	X	HFN-2	PFU4		2	2		2TX108724N	MN
Xerox	AL C8035	132137	40710	X	X	pcl/ps	X		PFU4		2	2		2TX073151	MN
Xerox	AL C8035	145860	68452	X		PCL/PSP	X	HFN-2	PFU4		2	2		3TX410981	TX
Xerox	AL C8035	153430	80583	X	X	pcl/ps	X	Internal	PFU3		2	2		3TX422864	MN
Xerox	AL C8035	160185	92495	X		PCL/PS	X		PFU4		2	2		2TX069847	TX
Xerox	AL C8035	166560	121207	X	X	PCL/PS	X		PFU4		2	2		2TX073071	MN
Xerox	AL C8035	167604	72240	X	X	PCL/PS	X	HFN-2	PFU4		2	2		3TX423752	MN
Xerox	AL C8035	170351	107719	X	X	PCL/PS	X	HFN-2	PFU4		2	2		2TX066758	TX
Xerox	AL C8035	217588	54840	X	X	pcl/ps	X	HFN-2	PFU4		2	2		3TX417222	MN
Xerox	AL C8035	247719	120611	X	X	PCL/PS	X		PFU4		2	2		2TX052489	TX
Xerox	AL C8035	300092	159275	X	X	PCL/PS	X	HFN-2	PFU4		2	2		2TX052872	TX
Xerox	AL C8035	357921	203919	X	X	PCL/PS	X	A-FN07	PFU4		2	2		3TX390544	MN
Xerox	AL C8035	422521	184549	X	X	pcl/ps	X	Internal	PFU4		2	2	Poor image quality	3TX411069	MN
Xerox	AL C8035	515273	179328	X	X	PCL/PS	X		PFU4		2	2		3TX419794	TX
Xerox	AL C8035	618557	441953	X	X	pcl/ps	X	Internal	PFU3		2	2		3TX422907	MN
Xerox	AL C8045	59834	25032	X	X	PCL/PS	X	HFN-2	PFU4		2	2	Dirty	8TB594950	MN
Xerox	AL C8045	64930	48741	X	X	PCL/PS	X	HFN-2	PFU4		2	2	Dirty	8TB595060	MN
Xerox	AL C8045	82208	44891	X		PCL/PS	X	BFO-1	PFU4		2	2	Finisher model seems incorrect but that's what came with it s/b HFN-2	8TB073670N	MN
Xerox	AL C8045	83781	66453	X	X	PCL/PS	X	HFN-2	PFU4		2	2	Accounting server installed, unable to use printer features.	8TB646902	TX
Xerox	AL C8045	83989	30508	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB637009	TX
Xerox	AL C8045	91876	87258	X	X	PCL/PS	X		PFU4		2	2		8TB642368	TX
Xerox	AL C8045	103795	62001	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB594870	MN
Xerox	AL C8045	113286	58493	X	X	PCL/PS	X	A-FN07	PFU4		2	2		8TB593447	MN
Xerox	AL C8045	158026	125925	X		PCL/PS	X		PFU4		2	2		8TB636229	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Xerox	AL C8045	167846	127434	X	X	PCL/PS	X	HFN-2	PFU4		2	2	Dirty, yellowing on front of machine	8TB594719	MN
Xerox	AL C8045	173406	90904	X		PCL/PS	X		PFU4		2	2		8TB623974	TX
Xerox	AL C8045	187134	130548	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB595065	MN
Xerox	AL C8045	196430	70274	X		PCL/PS	X	A-FN07	PFU4		2	2		8TB642279	MN
Xerox	AL C8045	234359	140634	X	X	PCL/PS	X		PFU4		2	2		8TB611262	TX
Xerox	AL C8045	249056	101156	X	X	pcl/ps	X		PFU4		2	2		8TB648647	MN
Xerox	AL C8045	262348	10032	X		PCL/PS	X		PFU4		2	2		8TB645624	TX
Xerox	AL C8045	361746	169750	X		PCL/PS	X	HFN-2	PFU4		2	2		8TB645970	TX
Xerox	AL C8045	376019	215001	X	X	PCL/PS	X	HFN-2	PFU4		2	2	Yellowing on front of machine	8TB595064	MN
Xerox	AL C8045	378428	148805	X		PCL/PS	X	A-FN07	PFU4		2	2		8TB645533	MN
Xerox	AL C8045	395784	239682	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB594496	MN
Xerox	AL C8045	397959	31821	X		PCL/PS	X	HFN-2	PFU4		2	2	Slight yellowing on front panels	8TB578826	MN
Xerox	AL C8045	456102	185947	X		PCL/PS	X	A-FN07	PFU4		2	2		8TB642738	MN
Xerox	AL C8045	470972	277721	X	X	PCL/PS	X		PFU4		2	2	Yellowing on front of machine	8TB594873	MN
Xerox	AL C8045	471112	227426	X		PCL/PS	X		PFU4		2	2	Dirty, yellowing	8TB594481	MN
Xerox	AL C8045	1322996	133512	X		PCL/PS	X	A-FN07	PFU4		2	2		8TB550908	MN
Xerox	AL C8055	277204	183360	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB612036	TX
Xerox	AL C8055	376694	42536	X		PCL/PS	X	A-FN07	PFU4		2	2		8TB622255	MN
Xerox	AL C8070	420134	287998	X		PCL/PS	X	A-FN07	PFU4		2	2	Yellowing	6TB445851	MN
Xerox	AL C8070	489999	262773	X		PCL/PS	X	A-FN07	PFU4		2	2		6TB453888	TX
Xerox	AL C8070	526908	144411	X		PCL/PS	X	A-FN07	PFU4	SCF-1	2	2		6TB455147	TX
Xerox	AL C8135	92620	44156	X	X	PCL/PS	X	A-FN21	PFU4		2	2	Dirty	EKZ339273	MN
Xerox	AL C8145	62464	45880	X		PCL/PS	X		PFU4		2	2		EHQ227130	TX
Xerox	AL C8145	66747	49826	X		PCL/PS	X		PFU4		2	2		EHQ213809	TX
Xerox	AL C8145	82364	34252	X		PCL/PS	X		PFU4		2	2		EHQ213815	TX
Xerox	AL C8145	108333	72395	X	X	PCL/PS	X		PFU4		2	2		EHQ227134	TX
Xerox	AL C8145	111893	54662	X		PCL/PS	X	A-FN21	PFU4		2	2		EHQ227136	TX
Xerox	AL C8145	159454	67407	X		PCL/PS	X		PFU4		2	2		EHQ227131	TX
Xerox	AL C8145	219238	139835	X	X	PCL/PS	X	A-FN21	PFU4		2	2		EHQ227121	TX
Xerox	AL C8145	302086	169022	X	X	PCL/PS	X	A-FN07	PFU4		2	2		EHQ233600	TX
Xerox	AL C8155	375594	135337	X	X	PCL/PS		A-FN21	PFU4		2	2		EHQ209076	TX
Xerox	B205	614	0	X		PCL	X		PFU1		2	2		HCC820094	MN
Xerox	B205	1350	0	X		PCL	X		PFU1		2	2		HCC819966	MN
Xerox	B205	2698	0	X		pcl	X		PFU1		2	2		HCC820098	MN
Xerox	B205	4604	0	X		PCL/PS	X		PFU1		2	2		HCC819927	MN
Xerox	B205	6660	0	X		pcl	X		PFU1		2	2		HCC819944	MN
Xerox	B205	7486	0	X		pcl	X		PFU1		2	2		HCC820158	MN
Xerox	Color C60	268889	151036	X	X	PCL/PS	X	Exit Tray	PFU4		2	2	Blue ADF	E2B668204	MN
Xerox	Color C70 Pro	508083	256098	X		pcl/ps	X	A-FN07	PFU4		2	2	A-FN09	E2B116522	MN

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Xerox	Color C70 Pro	1213452	1082828	X		PCL/PS	X	A-FN09	PFU4		2	2		E2B109785	TX
Xerox	Color C70 Pro	1286097	283617	X		pcl/ps	X	A-FN07	PFU4		2	2	A-FN09	E2B116211	MN
Xerox	D125	8382569	0	X		PCL/PS	X	LFN-1	PFU4	RCF-1	2	2	Blue ADF	BG0975712	MN
Xerox	PL C9070	69500	41454	X		PCL/PS	X	A-FN07	PFU4		2	2		DQP133640	TX
Xerox	Versant 180Press	1336523	1326264	X		Fiery NX Pro-01	X	A-FN07	PFU3	A-CF03	2	2		1AB198307	TX
Xerox	VL B400	969	0			pcl/ps			PFU2		2	2		6HB032995	MN
Xerox	VL B400	15932	0			PCL/PS			PFU1		2	2	Very Dirty	6HB054565	MN
Xerox	VL B400	23773	0			pcl/ps					2	2	Dirty	6HB033658	MN
Xerox	VL B400	30213	0			pcl/ps			PFU1		2	2		6HB032159	MN
Xerox	VL B400	39264	0			pcl/ps			PFU1		2	2		6HB837789	MN
Xerox	VL B400	107302	0			PCL/PS			PFU1		2	2	Very Dirty	6HB032798	MN
Xerox	VL B405	4857	2749			PCL/PS			PFU1		2	2		7HB777866	TX
Xerox	VL B405	29373	0	X	X	pcl/ps	X		PFU2		2	2	Dirty and yellowed.	9HB357438	MN
Xerox	VL B405	49474	0	X	X	PCL/PS	X		PFU1		2	2		9HB182404	MN
Xerox	VL B405	92854	0	X	X	PCL/PS	X		PFU1		2	2	Dirty	9HB357451	MN
Xerox	VL B605	76942	0	X	X	PCL/PS	X		PFU1		2	2		5XB060059	MN
Xerox	VL B605	89092	0	X	X	PCL/PS	X		PFU1		2	2		5XB059998	MN
Xerox	VL B605	98504	0	X		PCL/PS	X		PFU1		2	2		5XB059999	MN
Xerox	VL B605	129801	0	X	X	PCL/PS	X		PFU1		2	2	Yellowed	5XB060184	MN
Xerox	VL B605	341389	0	X	X	PCL/PS	X		PFU2		2	2		5XB491129	TX
Xerox	VL B7030	64328	0	X		pcl/ps	X	HFN-2	PFU4		2	2		5DA855763	MN
Xerox	VL B7030	190572	0	X		PCL/PS	X		PFU4		2	2		5DA844836	TX
Xerox	VL B7030	220021	0	X		PCL/PS	X		Cab2		2	2		2DA802403	MN
Xerox	VL B7030	363362	0	X		PCL/PS	X		Cab2		2	2		2DA802310	MN
Xerox	VL B7035	21570	0	X		pcl/ps	X	HFN-2	PFU4		2	2		5DA855765	MN
Xerox	VL B7035	49210	0	X		PCL/PS	X		PFU4		2	2		5DA087806	TX
Xerox	VL B7035	75919	0	X		PCL/PS	X		PFU4		2	2		5DA857093	TX
Xerox	VL B7035	113842	0	X	X	PCL/PS	X		PFU4		2	2		5DA853554	TX
Xerox	VL B7035	270062	0	X	X	PCL/PS	X	Internal	PFU4		2	2		5DA081091	MN
Xerox	VL C400	13458	7360	X		PCL/PS	X		PFU1		2	2		7HB775279	TX
Xerox	VL C400	18413	10238			PCL/PS			PFU1		2	2		7HB776540	MN
Xerox	VL C400	46642	28113			PCL/PS			PFU1		2	2		7HB774865	MN
Xerox	VL C400	47374	6880			pcl/ps			PFU1		2	2		7HB780505	MN
													Missing waste toner container, magenta, cyan, and black toner. Tested with other supplies.		
Xerox	VL C405	11700	6193	X	X	pcl/ps	X		PFU1		2	2		4HX825851	MN
Xerox	VL C405	16596	3	X		PCL/PS	X		PFU1		2	2		4HX958510	TX
Xerox	VL C405	20737	15974	X	X	pcl/ps	X		PFU1		2	2		4HX973147	MN
Xerox	VL C405	24083	3	X		PCL/PS	X		PFU1		2	2		4HX958511	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

4/30/2025

Xerox	VL C405	26414	15253	X	X	PCL/PS	X		PFU1		2	2		4HX797808	MN
													Missing yellow, cyan, and black toner. Tested with other supplies.		
Xerox	VL C405	26783	14413	X	X	pcl/ps	X		PFU1		2	2		4HX826015	MN
Xerox	VL C405	30734	23043	X	X	pcl/ps	X		PFU1		2	2		4HX801825	MN
Xerox	VL C405	41151	1003	X		PCL/PS	X		PFU1		2	2		4HX982687	TX
Xerox	VL C405	47129	34745	X	X	PCL/PS	X		PFU1		2	2		4HX973146	MN
Xerox	VL C405	48212	28201	X	X	pcl/ps	X		PFU1		2	2		4HX825996	MN
													Tested with another toner		
Xerox	VL C405	60849	32487	X	X	PCL/PS	X		PFU1		2	2		4HX826012	MN
Xerox	VL C405	61085	4321	X	X		X		PFU1		2	2		4HX958507	TX
Xerox	VL C405	65296	37876	X	X	pcl/ps	X		PFU1		2	2		4HX826052	MN
Xerox	VL C405	78411	30489	X	X	PCL/PS	X		Cab2		2	2		4HX826469	MN
Xerox	VL C405	126001	54558	X	X	pcl/ps	X		PFU1		2	2		4HX572308	MN
Xerox	VL C500	7401	5659			PCL/PS			PFU1		2	2		7RA549562	TX
Xerox	VL C505	131970	46777	X	X	PCL/PS	X		PFU2		2	2		3RB731622	MN
Xerox	VL C600	8652	5829			PCL/PS			PFU1		2	2		9RA682116	TX
Xerox	VL C605	145474	68355	X		PCL/PS	X		PFU2		2	2		5RB745316	TX
Xerox	VL C605	401393	214011	X	X	PCL/PS	X		PFU3		2	2		9RB767627	TX
Xerox	VL C7020	40536	7896	X		PCL/PS	X		Cab2		2	2		9TX223452	TX
Xerox	VL C7020	124763	40490	X		PCL/PS	X		Cab2		2	2		9TX221986	TX
Xerox	VL C7020	193779	96802	X		PCL/PS	X		Cab2		2	2		9TX223895	TX
Xerox	VL C7025	151528	46196	X	X	PCL	X		PFU4		2	2		3UA224508	MN
Xerox	VL C7030	38249	21301	X		PCL/PS	X	Internal	PFU4		2	2		3UA291345	MN
Xerox	VL C7030	106854	39290	X		PCL/PS	X	Internal	PFU4		2	2		3UA225749	MN
Xerox	VL C7030	184626	49614	X	X	PCL/PS	X		PFU4		2	2		3UA289741	TX
Xerox	VL C8000	28950	11710			PCL/PS			PFU2		2	2	Dirty	2YX043100	MN
Xerox	WC3335	3648	0	X		pcl/ps	X		PFU1		2	2		5BT796203	MN
Xerox	WC5335	489993	0	X		pcl/ps	X		PFU4		2	2		AE9575454	MN
Xerox	WC6515	3162	993	X	X	PCL/PS	X		PFU1		2	2		5AV103546	MN
Xerox	WC7835i	245184	83984	X	X	PCL/PS	X		PFU4		2	2		MX0002353	TX
Xerox	WC7855	114582	32150	X		PCL/PS	X		PFU4		2	2		MX4501314	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480