



Make	Model	Total Meter	Color Meter	DF	Fax	Prt	Scan	Fin	PFU	LCT	EC	IC	Notes	SN	Loc
Brother	HLL6400DW	26636	0	X		PCL/PS	X		PFU1		2	2		U64185J1N429369	TX
Brother	MFCL6900DW	14725	0	X	X	PCL/PS	X		PFU1		2	2		U65541B9N122228	TX
Brother	MFCL6900DW	37114	0	X	X	PCL/PS	X		PFU1		2	2		U65541B9N122202	TX
Brother	MFCL6900DW	48134	0	X	X	PCL/PS	X		PFU1		2	2	Replace drum.	U65541B9N122201	TX
Brother	MFCL6900DW	51558	0	X	X	PCL/PS	X		PFU1		2	2		U65541B9N121694	TX
Canon	ImagePres s Lite C165	549728	485833	X	X	UFRII/PCL/PS	X	Booklet finisher - W1	PFU4	Paper deck unit - E1	2	2		3EP02066	TX
Canon	ImagePres s Lite C165	1725658	1580144	X	X	PCL/PS	X	Booklet Finisher-W1 Pro	PFU4	Paper Deck Unit-E1	2	2	multiple pieces from back of machine are detached from machine but in tact, dirty, minor scuffs and scratches	3EP01692	TX
Canon	IR-1643P	52997	0			UFRII/PCL/PS			PFU1		2	2		NQKA002349	TX
Canon	IRA DX-4745i	142263	0	X	X	UFRII/PCL/PS	X	Internal	PFU4		2	2		25J06431	MN
Canon	IRA DX-C3725i	38902	3316	X		UFRII/PCL/PS	X		Cab2		2	2		2UA10762	MN
Canon	IRA DX-C5760i	330961	292121	X	X	PCL/PS	X	Staple Finisher-Y1	PFU4		2	2	Buffer Pass Unit-Q1	3AC01253	TX
Canon	IRA-4035	397521	0	X	X	UFRII/PCL/PS	X		PFU4		2	2		HRP08070	MN
Canon	IRA-4235	190199	0	X	X	UFRII/PCL/PS	X		Cab2		2	2		RKJ03203	TX
Canon	IRA-4235	957806	0	X	X	UFRII/PCL/PS	X		PFU4		2	2		RKJ03210	TX
Canon	IRA-4535i	200481	0	X	X	ufrii/pcl/ps	X	Internal	Cab2		2	2		UMU08847	MN
Canon	IRA-4535i	230650	0	X	X	UFRII/PCL/PS	X		Cab2		2	2		UMU08725	MN
Canon	IRA-4535i	253899	0	X	X	ufrii/pcl/ps	X	Internal	Cab2		2	2		UMU10076	MN
Canon	IRA-4535i	417425	0	X	X	ufrii/pcl/ps	X	Internal	Cab2		2	2		UMU08843	MN
Canon	IRA-4535i II	801863	0	X	X	ufrii/pcl/ps	X	Internal	Cab2		2	2		XVZ02808	MN



Canon	IRA-4545I	66278	0	X	X	UFRII/PCL/PS	X		PFU4		2	2		UMV07400	TX
Canon	IRA-4551i III	113249	0	X		UFRII/PCL/PS	X	Internal	Cab2		2	2		2ND03389	MN
Canon	IRA-4551i III	1123655	0	X		UFRII/PCL/PS	X		Cab2		2	2		2ND03391	MN
Canon	IRA-C250if	68244	13877	X	X	UFRII/PCL/PS	X		Cab2		2	2		QNR10559	TX
Canon	IRA-C256if	50586	9976	X		UFRii/PCL/PS	X		Cab1		2	2		28X02052	MN
Canon	IRA-C256if III	102459	75025	X	X	UFRII/PCL/PS	X		PFU1		2	2		28X00776	MN
Canon	IRA-C256if III	131738	98799	X	X	UFRII/PCL/PS	X		PFU1		2	2	Poor image quality	28X00863	MN
Canon	IRA-C256if III	236732	75085	X	X	UFRII/PCL/PS	X		Cab2		2	2		2MV06817	TX
Canon	IRA-C256Ifii	43949	27041	X	X	UFRII/PCL/PS	X		PFU1		2	2		2AD07083	MN
Canon	IRA-C257if	55762	14584	X	X	UFRII/PCL/PS	X		PFU2		2	2		3CE02168	TX
Canon	IRA-C3525i	123516	56360	X	X	UFRII/PCL/PS	X		Cab2		2	2		XTK02777	TX
Canon	IRA-C3525i III	45950	5842	X		UFRII/PCL/PS	X		Cab2		2	2		2GH12925	MN
Canon	IRA-C3525i III	402542	277678	X		UFRII/PCL/PS	X		Cab2		2	2		2GH01676	MN
Canon	IRA-C3530i	204252	65378	X	X	UFRII/PCL/PS	X	AA1	PFU4		2	2		WSB04261	MN
Canon	IRA-C3530i III	7383	3896	X	X	ufrii/pcl/ps	X		PFU4		2	2		2GU04822	MN
Canon	IRA-C3530i III	8673	4970	X		ufrii/pcl/ps	X		PFU4		2	2		2GU04825	MN
Canon	IRA-C3530i III	263072	32371	X	X	UFRII/PCL/PS	X		PFU4		2	2	Machine is dirty	2GU08502	TX
Canon	IRA-C3530i III		1	X	X	Print	X	Internal	PFU4		2	2	Missing HDD/Firmware. Unable to Print/Get Info.	2GU04815	MN
Canon	IRA-C356if ii	100788	34532	X	X	UFRII/PCL/PS	X		Cab2		2	2		2QC06942	TX
Canon	IRA-C3725i	177231	36988	X	X	PCL/PS	X		PFU4		2	2		2UA03191	TX
Canon	IRA-C5235A	315942	76995	X		-	X		PFU4		2	2	Touch Screen Doesn't Work	RRB12090	MN
Canon	IRA-C5235A	698484	338439	X	X	UFRII	X	J1	PFU4		2	2		RRB01625	MN



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Canon	IRA-C5535i	231941	86915	X	X	UFRII/PCL/PS	X		PFU4		2	2		WXF05206	MN
Canon	IRA-C5535i III	189414	91878	X		ufrii/pcl/ps	X		PFU4		2	2	Missing wheel.	2KK05419	MN
Canon	IRA-C5540i III	199395	56860	X	X	UFRII/PCL/PS	X	Y1	PFU4		2	2		2JU08623	MN
Canon	IRA-C5540i III	431293	234348	X	X	UFRII/PCL/PS	X		PFU4		2	2		2JV02910	MN
Canon	IRA-C5560i	86817	53565	X	X	PCL/PS	X	Staple Finisher-Y1	PFU3		2	2	buffer Pass Unit-Q1	XLA02093	TX
Canon	IRA-C5560i	152246	140646	X		PCL/PS	X	Y1	PFU4		2	2		WXC07418	TX
Canon	IRA-C5560i	1286036	710391	X	X	PCL/PS	X	Staple Finisher-Y1	PFU3		2	2		WXC01500	TX
Canon	IRA-C5560i III	1839247	1103526	X		UFR ii/PCL/PS	X		PFU3		2	2		2HT04691	MN
Canon	IRA-C7565i II	429433	174891	X		UFRII/PCL/PS	X	V2	PFU4		2	2		XXJ01973	MN
Canon	LBP215dw	5088	0			UFRII/PCL/PS			PFU1		2	2		NKAA006171	MN
Canon	LBP215dw	8323	0			UFRII/PCL/PS			PFU1		2	2		NKAA006170	MN
Canon	LBP215dw	16194	0			UFRII/PCL/PS			PFU1		2	2		NKAA006172	MN
Canon	LBP312dn	20248	0			UFRII/PCL/PS			PFU1		2	2		NGQA004350	MN
Canon	LBP312dn	22848	0			UFRII/PCL/PS			PFU1		2	2		NGQA009554	MN
Canon	MF735CD W	4687	1592	X	X	UFRII/PCL/PS	X		PFU1		2	2	very dirty	WTL17233	MN
Canon	MF735CD W	11145	3841	X	X	UFRII/PCL/PS	X		PFU1		2	2	Yellowed	WTL17222	MN
Canon	MF735CD W	17412	10570	X	X	UFRII/PCL/PS	X		PFU1		2	2		WTL17237	MN
Canon	MF735CD W	28967	13204	X	X	UFRII/PCL/PS	X		PFU1		2	2	Dirty	WTL17218	MN
Canon	MF735CD W	33714	9771	X	X	UFRII/PCL/PS	X		PFU1		2	2	dirty	WTL17224	MN
Canon	MF735CD W	34884	5272	X	X	UFRII/PCL/PS	X		PFU1		2	2	dirty, yellowed	WTL17223	MN
Canon	MF735CD W	35193	21473	X	X	UFRII/PCL/PS	X		PFU1		2	2		WTL17235	MN
Canon	MF735CD W	57158	16522	X	X	UFRII/PCL/PS	X		PFU1		2	2		WTL17243	MN
Canon	MF735CD W	107073	31145	X	X	UFRII/PCL/PS	X		PFU1		2	2	Dirty, refuses to print in color.	WTL17236	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Epson	SureColor T3270	3339	0	X		PCL/PS			PFU1		2	2		Y84E005155	TX
													Error no cartridge found. Additional accessories ; feeder sealer and 2 more accessories		
Formax			0								2	2		ZG2140215660	TX
HP	E50045	2957	0			pcl/ps			PFU1		2	2		PHMCM5J2S8	MN
HP	E50045	11541	0			pcl/ps			PFU1		2	2		PHMCM5J2TL	MN
HP	E50045	100969	0			pcl/ps			PFU1		2	2		PHMCM50105	MN
HP	E50145	4385	0			PCL/PS			PFU1		2	2		VNCCQ6Y14S	MN
HP	E50145	18919	0			pcl/ps			PFU2		2	2		PHCCNB81K7	MN
HP	E50145	19384	0			pcl/ps			PFU1		2	2		PHCCNB81KX	MN
HP	E50145	32427	0			pcl/ps			PFU1		2	2		PHCCNB81KK	MN
HP	E50145	33682	0			PCL/PS			PFU2		2	2		PHCCNB81L2	MN
HP	E50145	33724	0			pcl/ps			PFU1		2	2		PHBCM5R12J	MN
HP	E50145	43992	0			pcl/ps			PFU1		2	2		PHBCM5R11J	MN
HP	E50145	57019	0			PCL/PS			PFU1		2	2		PHCCNB81LV	MN
HP	E50145	89533	0			pcl/ps			PFU2		2	2		PHCCNB81L1	MN
HP	E50145	91483	0			pcl/ps			PFU1		2	2		PHBCM5R0ZB	MN
HP	E50145	96274	0	X		pcl/ps	X		PFU1		2	2		PHCCNB81K3	MN
HP	E50145	114929	0			pcl/ps			PFU1		2	2		PHBCN1H2WF	MN
HP	E50145	119963	0			pcl/ps			PFU2		2	2		PHCCNB81KM	MN
HP	E52545	17353	0	X		PCL/PS	X		PFU1		2	2		MXMCM3W11V	MN
HP	E52545	20009	0	X		pcl/ps	X		PFU1		2	2		MXMCM3W126	MN
HP	E52545	53397	0	X		pcl/ps	X		PFU1		2	2		MXMCL790KH	MN
HP	E52645	24332	0	X	X	PCL/PS	X		PFU1		2	2		CNC1N1104V	TX
HP	E52645	24332	0					PCL/PS	PFU1		2	2		MXBCMC41ZG	TX
HP	E52645	28564	0	X	X	PCL/PS	X		PFU1		2	2		MXBCM9M0QR	TX
HP	E52645	29244	0	X	X	PCL/PS	X		PFU3		2	2		MXBCM6M12T	TX
HP	E52645	34307	0	X	X	PCL/PS	X		Cab2		2	2	Machine is hard to roll.	MXBCM6M15T	TX
HP	E52645	51097	0	X	X	PCL/PS	X		PFU1		2	2		MXBCM7R1LY	TX
HP	E52645	84764	0	X	X	pcl/ps	X		Cab2		2	2		MXBCNCS2FS	MN
HP	E52645	90188	0	X		PCL/PS	X		Cab3		2	2		MXBCNCS24T	MN
HP	E52645	129265	0	X		PCL/PS	X		PFU1		2	2		MXBCMBR1TJ	TX
HP	E55040	2337	1260			PCL/PS			PFU1		2	2		JPBCM65093	TX
HP	E55040	4400	3411			PCL/PS			PFU1		2	2		JPBCMDV2W4	MN
HP	E55040	8337	3791			PCL/PS			PFU1		2	2	Dirty	JPBCMDV2VB	MN
HP	E55040	11326	8739			PCL/PS			PFU1		2	2		JPBCM65099	TX
HP	E55040	31517	21184			pcl/ps			PFU1		2	2		JPBCMDV2XW	MN
HP	E57540	1296	646	X		PCL/PS	X		PFU1		2	2		MXBCM7Q2WS	MN
HP	E57540	4227	3076	X		PCL/PS	X		PFU1		2	2		MXBCM5X0TZ	MN
HP	E57540	6692	3930	X		PCL/PS	X		PFU1		2	2		MXBCM7Q2VZ	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

HP	E57540	8335	447	X		PCL/PS	X		PFU1		2	2		MXBCM5X0VP	MN
HP	E57540	8444	2386	X		PCL/PS	X		PFU1		2	2		MXBCM9B11L	MN
HP	E57540	10533	5155	X	X	pcl/ps	X		PFU1		2	2		MXBCM6T3BD	MN
HP	E57540	15710	10568	X		pcl/ps	X		PFU1		2	2		MXBCM7Q2WL	MN
HP	E57540	16272	6476	X	X	PCL/PS	X		PFU1		2	2		MXBCM5X0V5	MN
HP	E57540	17077	12468	X	X	PCL/PS	X		PFU1		2	2		MXBCM9B11N	MN
HP	E57540	25921	11494	X		pcl/ps	X		PFU1		2	2		MXBCM6T3B3	MN
HP	E57540	26534	16543	X	X	PCL/PS	X		PFU1		2	2		MXBCM6T3B6	MN
HP	E57540	29840	20990	X		PCL/PS	X		PFU1		2	2		MXBCM5X0VV	MN
HP	E57540	33397	22768	X		pcl/ps	X		PFU1		2	2		MXBCM9B115	MN
HP	E57540	33443	24359	X		PCL/PS	X		PFU1		2	2		MXBCM6T39M	MN
HP	E57540	33779	14505	X		pcl/ps	X		PFU1		2	2		MXBCM7Q2X2	MN
HP	E57540	37113	26104	X		pcl/ps	X		PFU1		2	2		MXBCM6T39W	MN
HP	E57540	38888	30044	X		PCL/PS	X		Cab2		2	2		MXBCP1C0HJ	TX
HP	E57540	66708	51946	X	X	PCL/PS	X		PFU1		2	2		MXBCN26074	TX
HP	E57540	70712	22654	X	X	PCL/PS	X		PFU1		2	2		MXBCM9B11H	MN
HP	E57540	96523	10405	X	X	pcl/ps	X		PFU1		2	2		MXBCN1Y0NS	MN
HP	E57540	121790	11588	X		pcl/ps	X		PFU1		2	2		MXBCM9V4BP	MN
HP	E57540	127202	9307	X	X	PCL/PS	X		PFU1		2	2		MXBCP2C0ZF	MN
HP	E57540	142176	62667	X	X	pcl/ps	X		PFU2		2	2		MXBCN1Y1Q8	MN
HP	E58650	64489	46442	X	X	PCL/PS	X		Cab2		2	2		CN124FK04D	TX
HP	E62555	65114	0	X		PCL/PS	X		Cab2		2	2		MXRCM2D0SC	TX
HP	E62665	256370	0	X		PCL/PS	X		PFU1		2	2		MXSCMBQ2TK	MN
HP	E67560	487125	276493	X		PCL/PS	X		PFU1		2	2	Toner low	MXCCL4COMH	TX
HP	E72525	50500	0	X	X	PCL/PS	X		Cab2		2	2		MXBCL6V0D7	TX
HP	E72525	152919	0	X		PCL/PS	X		Cab2		2	2	Dirty	CNC1M8V07C	MN
HP	E72535	18100	0	X		PCL/PS	X		Cab2		2	2		CNC1M7R05F	MN
HP	E72535	73331	0	X		PCL/PS	X		PFU4		2	2		CND1P3202B	TX
HP	E72535	150579	0	X		PCL/PS	X		Cab2		2	2		CNC1M7R05L	MN
HP	E77650	113837	51722	X	X	PCL/PS	X		PFU4		2	2		MXBCN6Q071	TX
HP	E77650	184997	120532	X		PCL/PS	X		PFU4		2	2		MXBCMDD0TC	TX
HP	E77822	47299	10445	X		pcl/ps	X		Cab2		2	2		CNC1M88094	MN
HP	E77825	121029	6537	X		pcl/ps	X	Internal	Cab2		2	2		CND1N49068	MN
HP	E77830	86170	31494	X	X	PCL/PS	X		PFU4		2	2		CNB8K6500M	TX
HP	E78325	250881	88077	X		pcl/ps	X		PFU4		2	2		CNB3NCVXCS	MN
HP	E78325	366730	125912	X		pcl/ps	X		Cab2		2	2		CNB3NCVXBJ	MN
HP	E78330	55701	26463	X	X	PCL/PS	X		Cab2		2	2	copy and supplies are admin password protected	CNB1NCB0NF	TX
HP	E82540	26621	0	X		PCL/PS	X		PFU4		2	2		CNC1PCX028	TX
HP	E82540	192312	0	X	X	PCL/PS	X		PFU4		2	2		CNB8KBD0Z6	TX
HP	E82540	254513	0	X	X	PCL/PS	X		PFU4		2	2		CNB8K5H09G	TX
HP	E82540	265732	0	X	X	PCL/PS	X		PFU4		2	2		CNB1L6N2RP	TX
HP	E82540	289944	0	X	X	PCL/PS	X		PFU4		2	2		CNB1L5S2WN	TX
HP	E82550	347567	0	X	X	PCL/PS	X	Laserjet stplr/stkr finisher	PFU4		2	2		CNC1P9D03F	TX
HP	E82550	568137	0	X	X	PCL/PS	X		PFU4		2	2		CNC1N1104W	TX
HP	E82550	813921	0	X	X	PCL/PS	X		PFU4		2	2		CBB1L3Q44D	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

HP	E82550	913053	0	X	X	PCL/PS	X		PFU4		2	2		CNC1N1104Z	TX
HP	E87640	38631	11698	X	X	PCL/PS	X		PFU4		2	2		CNC1N4Y019	TX
HP	E87650	330670	27291	X		pcl/ps	X	Y1G18A	PFU4		2	2		CNC1N2K030	MN
HP	E87650	761417	41461	X		pcl/ps	X	Y1G18A	PFU4		2	2		CNC1N2K02Z	MN
HP	M402dne	634	0			PCL/PS			PFU1		2	2		PHB5C82806	MN
HP	M402dne	721	0			PCL/PS			PFU1		2	2		PHB5C82814	MN
HP	M402dne	1110	0			PCL/PS			PFU1		2	2		JPBDZ34762	MN
HP	M402dne	2558	0			PCL/PS			PFU1		2	2		PHB5B87705	MN
HP	M402dne	2683	0			PCL/PS			PFU1		2	2		PHB5B87703	MN
HP	M402dne	2815	0			PCL/PS			PFU1		2	2		PHB5B88218	MN
HP	M402dne	3270	0			PCL/PS			PFU1		2	2		PHB5B88230	MN
HP	M402dne	3319	0			PCL/PS			PFU1		2	2		PHB5C82804	MN
HP	M402dne	3468	0			PCL/PS			PFU1		2	2		PHB5C82808	MN
HP	M402dne	3821	0			PCL/PS			PFU1		2	2	Missing toner	PHB5B87706	MN
HP	M402dne	5133	0			PCL/PS			PFU1		2	2		PHB5B88208	MN
HP	M402dne	5368	0			PCL/PS			PFU1		2	2		PHB5C82813	MN
HP	M402dne	7060	0			PCL/PS			PFU1		2	2		JPBDZ08731	TX
HP	M402dne	8860	0			PCL/PS			PFU1		2	2		PHB5B88225	MN
HP	M402dne	9186	0			PCL/PS			PFU1		2	2		PHB5B87700	MN
HP	M402dne	9287	0			PCL/PS			PFU1		2	2		PHB5C82805	MN
HP	M402dne	9552	0			PCL/PS			PFU1		2	2		PHB5H49183	MN
HP	M402dne	9915	0			PCL/PS			PFU1		2	2		PHB5B88219	MN
HP	M402dne	11917	0			PCL/PS			PFU1		2	2		PHB5B87694	MN
HP	M402dne	12784	0			PCL/PS			PFU1		2	2		JPBDZ08716	TX
HP	M402dne	12976	0			PCL/PS			PFU1		2	2		JPBDZ08724	TX
HP	M402dne	13295	0			PCL/PS			PFU1		2	2		JPBDZ08730	TX
HP	M402dne	13372	0			PCL/PS			PFU1		2	2		PHB5B87695	MN
HP	M402dne	13742	0			PCL/PS			PFU1		2	2		PHB5B88227	MN
HP	M402dne	15617	0			PCL/PS			PFU1		2	2		PHB5B87693	MN
HP	M402dne	15651	0			PCL/PS			PFU1		2	2		PHB5B87699	MN
HP	M402dne	15712	0			PCL/PS			PFU1		2	2		PHB5B88222	MN
HP	M402dne	15861	0			PCL/PS			PFU1		2	2		PHB5B88224	MN
HP	M402dne	17234	0			PCL/PS			PFU1		2	2		PHB5B87708	MN
HP	M402dne	18925	0			PCL/PS			PFU1		2	2		PHB5C82816	MN
HP	M402dne	19017	0			PCL/PS			PFU1		2	2		PHB5B87701	MN
HP	M402dne	19916	0			PCL/PS			PFU1		2	2		PHB5B88178	MN
HP	M402dne	20539	0			PCL/PS			PFU1		2	2		PHB5C82799	MN
HP	M402dne	20944	0			PCL/PS			PFU1		2	2		PHB5B88213	MN
HP	M402dne	22245	0			PCL/PS			PFU1		2	2		JPBDZ08728	TX
HP	M402dne	23159	0			PCL/PS			PFU1		2	2		PHB5C82810	MN
HP	M402dne	24380	0			PCL/PS			PFU1		2	2	Missing toner	PHB5C82807	MN
HP	M402dne	26456	0			PCL/PS			PFU1		2	2		PHB5B88221	MN
HP	M402dne	27718	0			PCL/PS			PFU1		2	2		PHB5B88212	MN
HP	M402dne	29917	0			PCL/PS			PFU1		2	2		PHB5B88217	MN
HP	M402dne	30933	0			PCL/PS			PFU1		2	2		PHB5B88228	MN
HP	M402dne	34491	0			PCL/PS			PFU1		2	2		PHB5B87696	MN
HP	M402dne	37296	0			PCL/PS			PFU1		2	2		JPBDZ34772	MN
HP	M402dne	43686	0			PCL/PS			PFU1		2	2		PHB5C82802	MN
HP	M402dne	44723	0			PCL/PS			PFU1		2	2		PHB5B88232	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

HP	M402dne	45315	0			PCL/PS			PFU1	2	2		PHB5B88214	MN
HP	M402dne	45982	0			PCL/PS			PFU1	2	2		PHB5B88220	MN
HP	M402dne	46250	0			PCL/PS			PFU1	2	2		PHB5B88209	MN
HP	M402dne	46419	0			PCL/PS			PFU1	2	2		PHB5B87709	MN
HP	M402dne	47603	0			PCL/PS			PFU1	2	2		PHB5B88226	MN
HP	M402dne	48724	0			PCL/PS			PFU1	2	2		PHB5B88223	MN
HP	M402dne	52574	0			PCL/PS			PFU1	2	2		PHB5B88205	MN
HP	M402dne	56742	0			PCL/PS			PFU1	2	2		PHB5B88207	MN
HP	M402dne	58797	0			PCL/PS			PFU1	2	2		PHB5C82812	MN
HP	M402dne	59760	0			PCL/PS			PFU1	2	2		PHB5F24038	TX
HP	M402dne	70660	0			PCL/PS			PFU1	2	2		PHB5B87692	MN
HP	M402dne	71984	0			PCL/PS			PFU1	2	2		PHB5B88211	MN
HP	M402dne	72123	0			PCL/PS			PFU1	2	2		PHB5B87698	MN
HP	M402dne	75266	0			PCL/PS			PFU1	2	2		JPBDZ08717	TX
HP	M402dne	77847	0			PCL/PS			PFU1	2	2		PHB5C82796	MN
HP	M402dne	78437	0			PCL/PS			PFU1	2	2		PHB5B88216	MN
HP	M402dne	84192	0			PCL/PS			PFU1	2	2		PHB5B88215	MN
HP	M402dne	89552	0			pcl/ps			PFU1	2	2		PHB5B88210	MN
HP	M402DW	6324	0			PCL/PS			PFU1	2	2		PHBVH24988	MN
HP	M404n	181	0			PCL/PS			PFU1	2	2		PHBC328624	TX
HP	M404n	7737	0			PCL/PS			PFU1	2	2		PHBC328625	TX
HP	M404n	16683	0		X	PCL/PS			PFU1	2	2		PHBC328620	TX
HP	M452DN	1984	1263			PCL/PS			PFU1	2	2		VND3M06058	MN
HP	M506	38328	0			PCL/PS			PFU1	2	2		PHBGT35865	MN
HP	M506	88174	0			pcl/ps			PFU1	2	2		PHBGT35852	MN
HP	M506	135974	0			PCL/PS			PFU1	2	2		PHBGT35854	MN
HP	M506	139257	0			pcl/ps			PFU1	2	2		PHBGT35849	MN
HP	M570DN	41317	27115	X		PCL/PS	X		PFU1	2	2	poor print Quality	CNCKN4Y0PY	MN
HP	M570DN	48227	23202	X		PCL/PS	X		PFU1	2	2		CNCKN734GT	MN
HP	M570DN	86688	55790	X	X	pcl/ps	X		PFU1	2	2		CNCKN3Z5ZK	MN
HP	M578	200944	8082	X	X	pcl/ps	X		PFU1	2	2		MXBC21BHGQ	MN
HP	M605	14680	0			PCL/PS			PFU1	2	2		CNDCJ77124	TX
HP	M607	129	0			PCL/PS			PFU1	2	2		CNBCMDB3V1	TX
HP	M607	663	0			PCL/PS			PFU1	2	2		CNBCMDB1BY	TX
HP	M607	1953	0			PCL/PS			PFU1	2	2		CNBCMDB18J	TX
HP	M607	1954	0			PCL/PS			PFU1	2	2		CNBCMDB18V	TX
HP	M607	2047	0			PCL/PS			PFU1	2	2		CNBCMDB0Y5	TX
HP	M607	3176	0			PCL/PS			PFU1	2	2	damage to PFU does not register as fully closed	CNBCMDB1C4	TX
HP	M607	3323	0			PCL/PS			PFU1	2	2		CNBCMB835Z	TX
HP	M607	8329	0			PCL/PS			PFU1	2	2		CNBCMB83SB	TX
HP	M608	4172	0			PCL/PS			PFU1	2	2		CNBCN8C1BF	MN
HP	M608	21075	0			PCL/PS			PFU1	2	2		CNBCN3B2ZR	MN
HP	MFP3301fdw	5328	2976	X	X	PCL/PS	X		PFU1	2	2		VND1J03848	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



HP	T830		0			-	X				2	2	No wheels attached. Paper won't cut. 1x 36in roll. Passes paper but can't retrieve count.	CN99H7M02H	MN	
HP	XL4100	102270	19517			-	X				2	2	Pagewide. B/W and Color counts combined. 120315 sqft. Print heads included.	MY01NHQ007	MN	
Kip	660	13322	4246								2	2	Total run = 1354 linear meters, B&W meter = Meter A in Square Feet, Color Meter = Meter B in Square Feet	14800778	TX	
Kon/Min	AccurioPre ssC3080	737718	496351	X			PCL/PS	X	OT-510	PFU2	PF-707m	2	2	RU-518 IQ-501	A9VE011000955	TX
Kon/Min	BZ-227	168501	0	X	X		pcl/ps	X		Cab3		2	2		A7AK017001120	MN
Kon/Min	BZ-25e	35021	0	X	X		PCL	X		PFU1		2	2		DD136120158026	MN
Kon/Min	BZ-287	272104	0	X	X		PCL/PS	X		PFU4		2	2		A7AH011001959	MN
Kon/Min	BZ-300i	134084	62848	X			PCL/PS	X		Cab2		2	2		AA2K011006533	TX
Kon/Min	BZ-363	118408	0	X			PCL/PS	X		Cab2		2	2		A1UE011106007	MN
Kon/Min	BZ-364e	152383	0	X	X		PCL/PS	X	Internal	PFU4		2	2		A61F011021483	MN
Kon/Min	BZ-368	187977	0	X			PCL/PS	X		PFU2		2	2		A9HJ011010890	MN
Kon/Min	BZ-368	513120	0	X			pcl/ps	X		Cab2		2	2		A9HJ011010293	MN
Kon/Min	BZ-368e	51270	0	X				X				2	2		AA6V017008397	TX
Kon/Min	BZ-368e	110153	0	X			PCL/PS	X		Cab2		2	2		AA6V017007778	TX
Kon/Min	BZ-368e	160149	0	X			PCL/PS	X		PFU4		2	2		AA6V011001956	MN
Kon/Min	BZ-368e	178809	0	X	X		pcl/ps	X	Internal	Cab2		2	2		AA6V017008490	MN
Kon/Min	BZ-368e	663647	0	X	X		PCL/PS	X		PFU4		2	2		AA6V017002610	TX
Kon/Min	BZ-4052	3345	0	X	X		PCL/PS	X		PFU1		2	2		AA1R011010592	MN

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Kon/Min	BZ-4052	15322	0	X	X	PCL/PS	X		PFU1		2	2		AA1R011013941	MN
Kon/Min	BZ-450i	38647	0	X	X	PCL/PS	X	FS-539	PFU3		2	2		AC76011004461	MN
Kon/Min	BZ-450i	174704	0	X		PCL/PS	X	FS-539	PFU4		2	2		AC76011001639	TX
Kon/Min	BZ-450i	210253	0	X	X	PCL/PS	X	FS-536	PFU3		2	2		AC76011001825	TX
Kon/Min	BZ-450i	509030	0	X		PCL/PS	X		PFU4		2	2		AC76011003995	MN
Kon/Min	BZ-454	190713	0	X		PCL/PS	X	FS-534	PFU3		2	2		A61E011028464	MN
Kon/Min	BZ-454e	147654	0	X		PCL/PS	X	FS-534	PFU3		2	2		A61E011028483	MN
Kon/Min	BZ-454e	400223	0	X	X	PCL/PS	X	FS-534	PFU3		2	2		A61E011022464	MN
Kon/Min	BZ-458	205687	0	X	X	PCL/PS	X	FS-536	PFU4		2	2		A9HH011005234	MN
Kon/Min	BZ-458e	262029	0	X	X	PCL/PS	X		Cab2		2	2		AA6U011019741	TX
Kon/Min	BZ-458e	404809	0	X		PCL/PS	X		PFU3		2	2		AA6U011019761	TX
Kon/Min	BZ-458e	459580	0	X		PCL/PS	X		PFU3		2	2		AA6U011019700	TX
Kon/Min	BZ-458e	638964	0	X	X	PCL/PS	X	FS-534	PFU1		2	2		AA6U011017837	MN
Kon/Min	BZ-4702P	4822	0			PCL/PS			PFU1		2	2		AAFH011008135	TX
Kon/Min	BZ-4702P	20723	0			PCL/PS			PFU1		2	2		AAFH011005470	MN
Kon/Min	BZ-4702P	40670	0			PCL/PS			PFU1		2	2		AAFH011005471	MN
Kon/Min	BZ-4702P	71669	0			PCL/PS			PFU1		2	2		AAFH011005484	MN
Kon/Min	BZ-4752	42470	0	X		PCL/PS	X		PFU1		2	2		AA1P011008200	TX
Kon/Min	BZ-4752	43646	0	X		PCL/PS	X		PFU1		2	2		AA1P011008202	TX
Kon/Min	BZ-4752	82458	0	X		PCL/PS	X		PFU1		2	2		AA1P011008189	TX
Kon/Min	BZ-4752	145978	0	X		PCL/PS	X		PFU2		2	2		AA1P011008204	TX
Kon/Min	BZ-4752	199427	0	X		PCL/PS	X		PFU2		2	2		AA1P011008195	TX
Kon/Min	BZ-4752	224464	0	X		PCL/PS	X		PFU2		2	2		AA1P011008151	TX
Kon/Min	BZ-558e	483047	0	X		PCL/PS	X		PFU4		2	2		AA6T011010036	MN
Kon/Min	BZ-558e	483459	0	X	X	PCL/PS	X		PFU3		2	2		AA6T011008797	TX
Kon/Min	BZ-558e	525917	0	X	X	PCL/PS	X	FS-536	PFU3		2	2		AA6T011008829	TX
Kon/Min	BZ-558e	631805	0	X	X	PCL/PS	X		PFU3		2	2		AA6T011008810	TX
Kon/Min	BZ-558e	663727	0	X		PCL/PS	X		PFU4		2	2		AA6T011010041	MN
Kon/Min	BZ-650i	491806	0	X	X	PCL/PS	X		PFU4		2	2		AC74011000460	MN
Kon/Min	BZ-658e	40586	0	X	X	pcl/ps	X	FS-536	PFU3		2	2		AA6R011005970	MN
Kon/Min	BZ-658e	382360	0	X	X	PCL/PS	X	FS-536	PFU3		2	2		AA6R011005504	TX
Kon/Min	BZ-658e	585947	0	X	X	PCL/PS	X	FS-536	PFU3		2	2		AA6R011005969	MN
Kon/Min	BZ-808	897167	0	X	X	PCL/PS	X	FS-534	PFU4		2	2		A8KN011003818	MN
Kon/Min	BZ-808	1861570	0	X	X	pcl/ps	X		PFU4		2	2	Front door hinges damaged. Right front corner panel damaged.	A8KN011000828	MN
Kon/Min	BZ-958	1345123	0	X	X	PCL/PS	X	FS-536	PFU4		2	2	Error Code: C8103	A796011003570	MN
Kon/Min	BZ-AccurioPri ntC4065	338244	325024	X		Fiery ES IC- 419	X	FS-532	PFU2	LU-202m	2	2		ACC2011020386	MN
Kon/Min	BZ-C227	271231	102054	X			X		Cab2		2	2		A798019502256	MN
Kon/Min	BZ-C227	294827	141766			PCL/PS			Cab3		2	2		A798019502553	MN
Kon/Min	BZ-C227	382545	206575	X		PCL/PS	X		Cab2		2	2	Missing Wheel	A798019500566	MN
Kon/Min	BZ-C250i	55393	0	X		PCL/PS	X		Cab2		2	2		AA2M011005660	TX

EC=External Condition
I=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Kon/Min	BZ-C250i	69309	57187	X		pcl/ps	X		Cab2		2	2		AA2M011005722	MN
Kon/Min	BZ-C250i	89049	4516	X		PCL/PS	X		Cab2		2	2		AA2M011003822	TX
Kon/Min	BZ-C250i	142115	102210	X		PCL/PS	X	FS-534	Cab2		2	2	SD-511	AA2M013002395	MN
Kon/Min	BZ-C250i	153269	101584	X		pcl/ps	X		PFU4		2	2	Arrived without finisher.	AA2M013001246	MN
Kon/Min	BZ-C250i	208996	30123	X	X	PCL/PS	X		Cab2		2	2		AA2M011002202	MN
Kon/Min	BZ-C250i	244461	5114	X		PCL/PS	X	FS-536	PFU4		2	2		AA2M011004537	TX
Kon/Min	BZ-C250i	341162	209948	X	X	PCL/PS	X	FS-536	PFU4		2	2	SD-511	AA2M013002790	MN
Kon/Min	BZ-C250i	372220	214050	X	X	pcl/ps	X		Cab3		2	2		AA2M011003801	MN
Kon/Min	BZ-C250i	557363	332566	X		PCL/PS	X	FS-536	Cab2		2	2	SD-511	AA2M011008980	MN
Kon/Min	BZ-C250i	577067	306207	X	X	PCL/PS	X		PFU4		2	2	missing all toner cartridges	AA2M013008330	TX
Kon/Min	BZ-C258	58565	24050	X		PCL/PS	X	Internal	Cab3		2	2		A7R0011008903	MN
Kon/Min	BZ-C258	136579	68471	X	X	PCL/PS	X		PFU4		2	2		A7R0011003397	TX
Kon/Min	BZ-C258	288702	187875	X		PCL/PS	X	FS-534	Cab2		2	2	SD-511	A7R0011017413	MN
Kon/Min	BZ-C287	185912	109421	X	X	PCL/PS	X		Cab2		2	2		A797019501654	TX
Kon/Min	BZ-C300i	28857	18632	X	X	PCL/PS	X		PFU4		2	2		AA2K011007259	MN
Kon/Min	BZ-C300i	39193	11448	X	X	PCL/PS	X		PFU3		2	2		AA2K011007465	TX
Kon/Min	BZ-C300i	40436	30567	X	X	pcl/ps	X	FS-539	PFU4		2	2		AA2K013008027	MN
Kon/Min	BZ-C300i	41945	27016	X	X	pcl/ps	X	FS-539	PFU4		2	2		AA2K013007845	MN
Kon/Min	BZ-C300i	49528	15201	X		PCL/PS	X		PFU3		2	2		AA2K011007433	TX
Kon/Min	BZ-C300i	54390	21835	X	X	pcl/ps	X	FS-539	PFU4		2	2		AA2K013008269	MN
Kon/Min	BZ-C300i	55789	21766	X	X	PCL/PS	X		Cab2		2	2		AA2K011007676	MN
Kon/Min	BZ-C300i	61189	44537	X	X	pcl/ps	X	FS-539	PFU4		2	2		AA2K013008020	MN
Kon/Min	BZ-C300i	83036	58148	X	X	PCL/PS	X	Internal	Cab2		2	2		AA2K011008583	MN
Kon/Min	BZ-C300i	94112	50153	X		PCL/PS	X		PFU3		2	2		AA2K011007333	TX
Kon/Min	BZ-C300i	97729	70966	X		PCL/PS	X	FS-534	PFU4		2	2		AA2K013007946	MN
Kon/Min	BZ-C300i	140209	107611	X		PCL/PS	X		Cab2		2	2		AA2K013000825	MN
Kon/Min	BZ-C300i	198556	95992	X	X	PCL/PS	X		Cab2		2	2		AA2K013007552	MN
Kon/Min	BZ-C300i	210731	51637	X		PCL/PS	X		PFU3		2	2		AA2K011008919	TX
Kon/Min	BZ-C300i	212528	104500	X		PCL/PS	X		Cab2		2	2		AA2K011007253	MN
Kon/Min	BZ-C300i	215172	140427	X		PCL/PS	X		Cab2		2	2		AA2K013008136	TX
Kon/Min	BZ-C300i	290605	115127	X	X	pcl/ps	X		PFU4		2	2	Arrived without finisher.	AA2K013003861	MN
Kon/Min	BZ-C300i	371667	265629	X	X	PCL/PS	X		PFU4		2	2		AA2K011004501	TX
Kon/Min	BZ-C300i	375170	63504	X	X	pcl/ps	X	Internal	PFU3		2	2		AA2K011007784	MN
Kon/Min	BZ-C308	95215	52935	X		PCL/PS	X		Cab2		2	2		A7PY017010491	MN
Kon/Min	BZ-C308	122163	86106	X	X	pcl/ps	X		PFU3		2	2		A7PY011015902	MN
Kon/Min	BZ-C308	139450	45470	X		pcl/ps	X		PFU4		2	2		A7PY017010211	MN
Kon/Min	BZ-C308	167021	65143	X	X	PCL/PS	X		PFU4		2	2	Missing Wheel	A7PY011018932	MN
Kon/Min	BZ-C308	206745	36449	X	X	PCL/PS	X		PFU4		2	2		A7PY017010261	MN
Kon/Min	BZ-C308	211471	28042	X	X	pcl/ps	X	Internal	Cab2		2	2		A7PY011014658	MN
Kon/Min	BZ-C308	229875	102555	X	X	PCL/PS	X	Internal	PFU3		2	2		A7PY011013406	MN
Kon/Min	BZ-C308	235096	51823	X	X	pcl/ps	X	Internal	Cab2		2	2		A7PY017010232	MN
Kon/Min	BZ-C3100P	6405	0			pcl/ps			PFU1		2	2		A6DR012107949	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Kon/Min	BZ-C3300i	22378	2470	X	X	PCL/PS	X		PFU1		2	2		AAJT011202616	TX
Kon/Min	BZ-C3300i	47442	29875	X		PCL/PS			PFU1		2	2		AAJT011000603	TX
Kon/Min	BZ-C3320i	38671	3594	X		PCL/PS	X		PFU2		2	2		AAJP011000325	TX
Kon/Min	BZ-C3351	19770	8422	X	X	pcl/ps	X		PFU2		2	2		A92F011010726	MN
Kon/Min	BZ-C3351	217080	132388	X	X	PCL/PS	X		Cab3		2	2		A92F011012540	TX
Kon/Min	BZ-C360i	95720	30892	X		pcl/ps	X		PFU3		2	2	Bottom right door not latching.	AA2J011014996	MN
Kon/Min	BZ-C360i	147617	139731	X		PCL/PS	X		PFU4		2	2		AA2J013002597	TX
Kon/Min	BZ-C360i	170762	116097	X	X	PCL/PS	X	FS-536	PFU3		2	2		AA2J011008149	TX
Kon/Min	BZ-C360i	185749	49985	X		PCL/PS	X	Internal	PFU3		2	2		AA2J011004667	MN
Kon/Min	BZ-C360i	202661	128782	X	X	pcl/ps	X		PFU4		2	2	Arrived without finisher	AA2J011008389	MN
Kon/Min	BZ-C360i	214850	94140	X	X	PCL/PS	X	FS-539	PFU4		2	2	missing toner, tested with spare. Removed front door hinge.	AA2J013000522	MN
Kon/Min	BZ-C360i	219558	84916	X		pcl/ps	X		PFU3		2	2		AA2J013004135	MN
Kon/Min	BZ-C360i	261795	159364	X		PCL/PS	X	FS-536	Cab2		2	2		AA2J011009555	MN
Kon/Min	BZ-C360i	262149	82545	X	X	PCL/PS	X	Internal	PFU4		2	2		AA2J013000534	MN
Kon/Min	BZ-C360i	267714	119217	X		PCL/PS	X		Cab2		2	2		AA2J011009357	TX
Kon/Min	BZ-C360i	292561	137288	X	X	PCL/PS	X	FS-536	PFU3		2	2		AA2J011008419	TX
Kon/Min	BZ-C360i	331261	209762	X	X	pcl/ps	X	Internal	PFU4		2	2		AA2J011003821	MN
Kon/Min	BZ-C360i	379352	214141	X		PCL/PS	X	FS-536	Cab2		2	2		AA2J011004244	TX
Kon/Min	BZ-C360i	483060	278424	X		PCL/PS	X	Internal	PFU3		2	2		AA2J011009552	MN
Kon/Min	BZ-C360i	720414	457414	X	X	PCL/PS	X	FS-536	PFU4		2	2	SD-511	AA2J011010809	MN
Kon/Min	BZ-C364e	174429	93765	X	X	PCL/PS	X	FS-534	PFU4		2	2		AC78013000905	MN
Kon/Min	BZ-C364e	491362	184216	X		PCL/PS	X	FS-534	PFU4		2	2	Yellowed	A5C1011026821	MN
Kon/Min	BZ-C368	28420	24212	X	X	pcl/ps	X	FS-534	PFU3		2	2		A7PU017202600	MN
Kon/Min	BZ-C368	89378	26249	X		PCL/PS	X	Internal	Cab3		2	2		A7PU011018478	MN
Kon/Min	BZ-C368	277027	109575	X	X	PCL/PS	X	Internal	PFU4		2	2		A7PU017005396	MN
Kon/Min	BZ-C368	364898	133132	X	X	PCL/PS	X	FS-534	PFU3		2	2		A7PU011026495	MN
Kon/Min	BZ-C368	437172	171223	X		PCL/PS	X	Internal	PFU3		2	2		A7PU017201997	MN
Kon/Min	BZ-C368	495281	266184	X	X	pcl/ps	X	Internal	PFU4		2	2		A7PU017202079	MN
Kon/Min	BZ-C368	548030	162740	X		pcl/ps	X	FS-534	Cab2		2	2		A7PU011023193	MN
Kon/Min	BZ-C368	562480	296342	X	X	pcl/ps	X	FS-534	PFU3		2	2		A7PU011015677	MN
Kon/Min	BZ-C450i	68723	44320	X		PCL/PS	X	FS-539	PFU3		2	2		AA7R011015889	MN
Kon/Min	BZ-C450i	102297	11336	X	X	PCL/PS	X		PFU4		2	2		AA7R011018084	MN
Kon/Min	BZ-C450i	115466	42531	X	X	PCL/PS	X	FS-536	PFU4		2	2		AA7R011001550	TX
Kon/Min	BZ-C450i	144513	72509	X		PCL/PS	X		PFU4		2	2	Missing Bridge Unit	AA7R011008201	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Kon/Min	BZ-C450i	160868	88640	X	X	pcl/ps	X		PFU4		2	2		AA7R011007385	MN
Kon/Min	BZ-C450i	162403	62954	X		PCL/PS	X		PFU3		2	2		AA7R011018418	TX
Kon/Min	BZ-C450i	169054	80717	X	X	pcl/ps	X		PFU4		2	2		AA7R011001009	MN
Kon/Min	BZ-C450i	187919	97917	X	X	pcl/ps	X	FS-539	PFU3		2	2		AA7R011001299	MN
													Can't bypass service mode authentication. Can only test B/W copy.		
Kon/Min	BZ-C450i	203568	75810	X	X	pcl/ps	X	Internal	PFU3		2	2		AA7R011020796	MN
Kon/Min	BZ-C450i	266436	119649	X		PCL/PS	X	FS-539	PFU4		2	2		AA7R011001055	MN
Kon/Min	BZ-C450i	362328	108474	X		PCL/PS	X	FS-539	PFU4		2	2		AA7R011008174	TX
Kon/Min	BZ-C450i	378416	49757	X	X	PCL/PS	X	FS-536	PFU3		2	2		AA7R011002823	MN
Kon/Min	BZ-C450i	639974	154169	X	X	PCL/PS	X	FS-539	PFU4		2	2		AA7R011007635	MN
Kon/Min	BZ-C454e	297795	153537	X		PCL/PS	X	FS-534	PFU3		2	2		A5C0011020657	MN
Kon/Min	BZ-C454e	400237	187195	X		PCL/PS	X	FS-534	PFU3		2	2		A5C0011008118	MN
Kon/Min	BZ-C454e	748376	230147	X	X	pcl/ps	X		PFU3		2	2		A5C0011033777	MN
Kon/Min	BZ-C458	171214	110917	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79M011052562	TX
Kon/Min	BZ-C458	256702	118646	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79M011042733	TX
Kon/Min	BZ-C458	289526	82598	X		FIERY E200-09	X	FS-536			2	2		A79M011038706	TX
Kon/Min	BZ-C458	318695	11325	X		PCL/PS	X		PFU4		2	2	Dirty	A79M011042278	MN
Kon/Min	BZ-C458	398285	81717	X	X	PCL/PS	X	FS-539	PFU3		2	2		A79M011035258	TX
Kon/Min	BZ-C458	628115	332339	X	X	PCL/PS	X	FS-536	PFU4		2	2		A79M011016382	MN
Kon/Min	BZ-C458	943855	463744	X	X	PCL/PS	X		PFU4		2	2		A79M011031190	TX
Kon/Min	BZ-C458	952887	135724	X		PCL/PS	X	FS-536	Cab2		2	2		A79M011051182	TX
Kon/Min	BZ-C458	1200348	611647	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79M011006512	MN
Kon/Min	BZ-C458	1537080	251381	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79M011007229	MN
Kon/Min	BZ-C550i	150604	50564	X		PCL/PS	X		PFU3		2	2	Missing Finisher	AA7P017705612	MN
Kon/Min	BZ-C550i	189573	127329	X		PCL/PS	X		PFU3		2	2	no finisher	AA7P011001434	TX
Kon/Min	BZ-C550i	1143951	921287	X		pcl/ps	X	FS-540SD	PFU4		2	2		AA7P011000833	MN
Kon/Min	BZ-C550i		0	X		PCL/PS	X		PFU3		2	2		AA7P011001054	TX
Kon/Min	BZ-C558	101688	39490	X	X	PCL/PS	X	FS-536	PFU4		2	2		A79K011008679	MN
Kon/Min	BZ-C558	121301	75049	X		PCL/PS	X		PFU3		2	2		A79K011025986	TX
Kon/Min	BZ-C558	136678	62867	X		pcl/ps	X	FS-536	PFU4		2	2		A79K011027973	MN
Kon/Min	BZ-C558	186330	153185	X	X	PCL/PS	X	FS-536	PFU3		2	2		A79K011027784	MN
Kon/Min	BZ-C558	276794	157202	X	X	PCL/PS	X	FS-536	PFU4		2	2		A79K011009538	MN
Kon/Min	BZ-C558	277627	137859	X		pcl/ps	X	FS-536	PFU4		2	2		A79K011024329	MN
Kon/Min	BZ-C558	288804	145592	X	X	Fiery E200-09	X	FS-536	PFU3		2	2	SD-511, unable to print from controller	A79K011027047	MN
Kon/Min	BZ-C558	395356	283059	X	X	PCL/PS	X		PFU4		2	2		A79K011014557	MN
Kon/Min	BZ-C558	627790	319966	X	X	Fiery E200-09	X	FS-536	PFU3		2	2	SD-511, unable to print from controller	A79K011027147	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Kon/Min	BZ-C558	646844	25472	X		PCL/PS	X	FS-536	PFU4		2	2	SD-511	A79K011020079	MN
Kon/Min	BZ-C558	813304	175555	X		PCL/PS	X	FS-536	PFU3		2	2		A79K011021569	MN
Kon/Min	BZ-C650i	333614	207024	X		PCL/PS	X	FS-539SD	PFU4		2	2		AA7N011007741	MN
Kon/Min	BZ-C654	2271015	1011563	X	X	PCL/PS	X		PFU4		2	2	Arrived W/O Finisher	a2x1011006847	MN
Kon/Min	BZ-C759	199005	72373	X		Fiery ES IC-418	X	FS-537	PFU4		2	2	SD-512	A8JE011004962	MN
Kon/Min	BZ-C759	352507	296621	X		Fiery ES IC-418	X	FS-537	PFU4		2	2	SD-512	A8JE011004821	MN
Kyocera	CS-4551ci	436840	85044	X		KDPL/PCL	X	DF-7120	PFU4		2	2		LA95902584	TX
Kyocera	FS-4100DN	19049	0			pcl/kpdl			PFU1		2	2		NUK3813262	MN
Kyocera	FS-4100DN	55159	0			KPDL/PCL			PFU1		2	2		NUK3610990	MN
Kyocera	FS-4100DN	69474	0			KPDL./PCL			PFU1		2	2		LQP569676	TX
Kyocera	FS-4200DN	26013	0			PCL/PS			PFU1		2	2		LPD6145051	TX
Kyocera	FS-4200DN	36212	0			PCL/PS			PFU1		2	2		LPD4409939	TX
Kyocera	FS-4200DN	45157	0			KPDL/PCL			PFU1		2	2		LPD4511779	TX
Kyocera	FS-4200DN	82354	0			KPDL/PCL			PFU1		2	2		LPD4104396	TX
Kyocera	FS-4200DN	102465	0			KPDL/PCL			PFU1		2	2		LPD6448839	TX
Kyocera	M2035DN	14187	0	X		KPDL/PCL	X		PFU1		2	2	dirty	LVV6X07390	TX
Kyocera	M2540dw	29633	0	X	X	KDPL/PCL	X		PFU1		2	2		VCJ0X36301	TX
Kyocera	M2640idw	6893	0	X		pcl/kpdl	X		PFU1		2	2	Yellowed and dirty.	VCM9808065	MN
Kyocera	M2640idw	18094	0	X		PCL/PS	X		PFU1		2	2		VCM0109395	TX
Kyocera	M2640idw	24978	0	X	X	KDPL/PCL	X		PFU1		2	2		VCM0X11757	TX
Kyocera	M2640idw	54350	0	X		PCL/PS	X		PFU1		2	2		VCM0109392	TX
Kyocera	M3540IDN	10292	0	X	X	KDPL/PCL	X		PFU1		2	2		LSH4803690	TX
Kyocera	M3655IDN	51450	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P0460377	MN
Kyocera	M3655IDN	55298	0	X	X	KPDL/PCL	X		PFU2		2	2		R4P2601398	MN
Kyocera	M3655IDN	65508	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P2601775	MN
Kyocera	M3655IDN	100849	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P0460375	MN
Kyocera	M3655IDN	175639	0	X	X	pcl/kpdl	X		PFU1		2	2		R4P0X65017	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Kyocera	M3655IDN	258935	0	X	X	KPDL/PCL	X		PFU1		2	2		R4P0460383	MN
Kyocera	M5526cdw	23478	5310	X		PCL/PS	X		PFU1		2	2		VE89709832	TX
Kyocera	M5526cdw	26809	0	X		pcl/kpdl	X		PFU1		2	2		VE80Y14247	MN
Kyocera	M5526cdw	37708	10290	X		PCL/PS	X		PFU1		2	2		VE89709728	TX
Kyocera	M5526cdw	46714	40346	X	X	KPDL/PCL6	X		PFU4		2	2		VE89Z11132	MN
Kyocera	M6235cidn	99085	20699	X		KPDL/PCL	X		PFU1		2	2		RC11Y05849	TX
Kyocera	M6535CiD N	95237	41600	X	X	KDPL/PCL	X		PFU1		2	2		V6D5904208	TX
Kyocera	M6535CiD N	126618	93513	X		KPDL/PCL	X		PFU2		2	2		V6D7612414	MN
Kyocera	M6535CiD N		1	X		-	X		PFU1		2	2	Cannot Bypass Papercut	V6D5702529	MN
Kyocera	M6635CiD N	21084	7399	X	X	PCL/KPDL	X		PFU1		2	2		RC41Y19365	MN
Kyocera	M6635CiD N	38069	20118	X	X	pcl/kpdl	X		PFU1		2	2		RC49505948	MN
Kyocera	M6635CiD N	88473	41546	X	X	KPDL/PCL	X		PFU1		2	2		RC40X13568	TX
Kyocera	M6635CiD N	112998	31372	X	X	pcl/kpdl	X		PFU1		2	2		RC42420375	MN
Kyocera	P2040dw	24613	0			KPDL/PCL			PFU1		2	2		VD29537712	MN
Kyocera	P3045dn	21469	0			KPDL/PCL			PFU1		2	2		VM37Z15960	MN
Kyocera	P3045dn	45017	0			KPDL/PCL			PFU1		2	2		VM37707453	MN
Kyocera	P3050dn	53052	0			KPDL/PCL			PFU2		2	2		VLY8910608	MN
Kyocera	P3050dn	61683	0			pcl/kpdl			PFU1		2	2		VLY8910609	MN
Kyocera	P3050dn	75706	0			pcl/kpdl			PFU1		2	2		VLY8910559	MN
Kyocera	P3050dn	88569	0			KPDL/PCL			PFU2		2	2		VLY8910603	MN
Kyocera	P3050dn	229747	0			pcl/kpdl			PFU1		2	2		VLY8911096	MN
Kyocera	P3050dn	486444	0	X		pcl/kpdl	X		PFU1		2	2		VLY8910606	MN
Kyocera	P3055DN	6234	0			KPDL/PCL			PFU1		2	2		VG49246952	TX
Kyocera	P3055DN	7740	0			KPDL/PCL			PFU1		2	2		VG49246935	TX
Kyocera	P3055DN	68735	0			KPDL/PCL			PFU1		2	2		VG49246953	TX
Kyocera	P3145DN	8932	0			PCL/PS			PFU1		2	2		R4H9600679	TX
Kyocera	P3150dn	8025	0			PCL/PS			PFU1		2	2		R4D9Z02671	TX
Kyocera	P3150dn	22392	0			KPDL/PCL			PFU1		2	2		R4D0Z04940	MN

Highlighting Key

Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Kyocera	P3150dn	35142	0			KPDL/PCL			PFU1		2	2		R4D1405435	TX
Kyocera	P3150dn	39834	0	X		KDPL/PCL			PFU1		2	2		R4D9701329	TX
Kyocera	P3260dn	207382	0			KPDL/PCL			PFU1		2	2		RP69500009	TX
Kyocera	P6235CDN	33136	10733			PCL/PS			PFU1		2	2		RCG9Y03810	TX
Kyocera	P6235CDN	45141	22649			KPDL/PCL			PFU1		2	2	replace waste toner soon	RCG9X03712	TX
Kyocera	P7240cdn	66798	55984			PCL/PS			PFU2		2	2		RCL8Z00638	TX
Kyocera	TA-2552ci	56072	42528	X		PCL/PS	X		PFU4		2	2		W2V6800798	TX
Kyocera	TA-2552ci	153221	54521	X		PCL/PS	X	DF-7120	PFU4		2	2		W2V6X01135	TX
Kyocera	TA-2552ci	324099	242357	X	X	KPDL/PCL	X		PFU4		2	2		VFJ7901349	TX
Kyocera	TA-2552ci	361783	132779	X		KPDL/PCL	X		PFU4		2	2		VFJ6800203	MN
Kyocera	TA-2553ci	52663	29206	X		PCL/PS	X		PFU4		2	2		RFL9501402	TX
Kyocera	TA-2553ci	77020	12832	X		KPDL/PCL	X		Cab2		2	2		RFL9602974	MN
Kyocera	TA-2553ci	81364	22278	X		KPDL/PCL	X		Cab2		2	2		RFL0803689	MN
Kyocera	TA-2553ci	101769	39113	X		KPDL/PCL	X	Internal	Cab2		2	2		RFL9501537	MN
Kyocera	TA-2553ci	103350	46330	X		KPDL/PCL6	X		Cab2		2	2		RFL9501567	MN
Kyocera	TA-2553ci	115919	28502	X	X	PCL/PS	X		PFU4		2	2		RFL0X04622	TX
Kyocera	TA-2553ci	126736	15097	X		pcl/kpdl	X		Cab2		2	2		RFL9602479	MN
Kyocera	TA-3011i	216525	0	X	X	KPDL/PCL	X		Cab2		2	2		V927703183	TX
Kyocera	TA-3051ci	57967	32787	X	X	KPDL/PCL	X		Cab2		2	2		L855Z15487	TX
Kyocera	TA-307CI	57274	42155	X		KPDL/PCL	X		Cab2		2	2		R368600751	MN
Kyocera	TA-307CI	77996	45997	X	X	KPDL/PCL	X		PFU4		2	2		R369603559	TX
Kyocera	TA-307CI	146924	50912	X	X	pcl/kpdl	X		Cab2		2	2		R369603512	MN
Kyocera	TA-308ci	68678	37991	X	X	pcl/kpdl	X		PFU3		2	2		RLZ0901935	MN
Kyocera	TA-308ci	81500	38204	X		KPDL/pCL	X		PFU3		2	2		RLZ9800029	MN
Kyocera	TA-3212i	73175	0	X		PCL/PS	X		Cab2		2	2		R419603465	TX
Kyocera	TA-3212i	82754	0	X		KPDL/PCL	X		Cab2		2	2		R419102553	MN
Kyocera	TA-3252ci	73715	35920	X		PCL/PS	X	DF-7120	PFU4		2	2		VFG6800276	TX
Kyocera	TA-3252ci	139454	34271	X		KPDL/PCL	X		Cab2		2	2		VFG6Y00622	TX
Kyocera	TA-3252ci	221021	88867	X		KPDL/PCL	X		Cab2		2	2		W2R8Y11274	MN
Kyocera	TA-3252ci	230871	72999	X		pcl/kpdl	X	DF-7120	Cab2		2	2		W2R7Y07035	MN

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Kyocera	TA-3252ci	331456	148673	X		KPDL/PCL	X	DF-7120	Cab2		2	2		W2R7705590	MN
Kyocera	TA-3252ci	350627	260166	X		KDPL/PCL	X	DF-7110	PFU4		2	2		W2R6Y01782	TX
Kyocera	TA-3252ci	367562	111165	X		PCL/PS	X		PFU4		2	2		W2R8910516	TX
Kyocera	TA-3252ci	383387	95299	X		PCL/PS	X		Cab2		2	2		W2R7303443	TX
Kyocera	TA-3252ci	415305	192910	X	X	pcl/kpdl	X	Internal	PFU4		2	2		W2R7Y06981	MN
Kyocera	TA-3253ci	53252	25215	X		KPDL/PCL	X	DF-7120	PFU4		2	2		RFG9100847	MN
Kyocera	TA-3253ci	76043	51008	X		pcl/kpdl	X	DF-7120	Cab2		2	2		RFG9Z05141	MN
Kyocera	TA-3253ci	115853	19175	X		KDPL/PCL	X		Cab2		2	2		RFG9Z04961	TX
Kyocera	TA-3253ci	281068	157558	X	X	KPDL/PCL	X		Cab2		2	2		RFG9Z05175	TX
Kyocera	TA-3253ci	361021	51534	X		KDPL/PCL	X		Cab2		2	2		RFG9401652	TX
Kyocera	TA-3253ci	1078203	426247	X		PCL/PS	X	DF-7110	PFU4		2	2		RFG9100771	MN
Kyocera	TA-3511i	191688	0	X		KPDL/PCL	X		Cab2		2	2		V967601173	MN
Kyocera	TA-3551ci	497966	311734	X	X	KPDL/PCL	X	DF-770	PFU4		2	2		LH5704635	TX
Kyocera	TA-3552ci	356545	272011	X		pcl/kpdl	X		Cab2		2	2	Cab door doesn't latch. Arrived with incorrect finisher.	VLQ6800735	MN
Kyocera	TA-3553ci	145392	69996	X		KPDL/PCL	X		Cab2		2	2		RFE0705587	MN
Kyocera	TA-3553ci	184743	46518	X	X	KPDL/PCL	X		Cab2		2	2		RFE9Z04457	MN
Kyocera	TA-3553ci	1014897	871030	X		KPDL/PCL	X	DF-7110	Cab2		2	2		RFE0404938	MN
Kyocera	TA-358CI	57256	28989	X		KPDL/PCL	X		Cab2		2	2		R2Z0Y00590	TX
Kyocera	TA-358CI	63616	34235	X		KPDL/PCL	X		Cab2		2	2		R2Z0900454	TX
Kyocera	TA-4002i	187589	0	X		KPDL/PCL	X		Cab2		2	2		W378813755	MN
Kyocera	TA-4002i	293682	0	X		KPDL/PCL	X		Cab2		2	2		W378713388	MN
Kyocera	TA-4004i	384253	0	X		KPDL/PCL	X	DF-7140	PFU4		2	2		W9T2302828	MN
Kyocera	TA-4052ci	359145	176361	X		PCL/PS	X		PFU4		2	2		W2M8303949	TX
Kyocera	TA-4053ci	424484	140241	X		KPDL/PCL	X	DF-7110	PFU4		2	2		RFB9601580	MN
Kyocera	TA-4053ci	644789	279307	X		KPDL/PCL	X	DF-7110	PFU4		2	2		RFB9601589	MN
Kyocera	TA-4053ci	699776	251710	X		KPDL/PCL	X	DF-7120	PFU4		2	2		RFB9601640	MN



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Kyocera	TA-4053ci	722161	444506	X		KPDL/PCL	X	DF-7120	PFU4		2	2		RFB9601739	MN
Kyocera	TA-4053ci	743122	406979	X		KPDL/PCL	X	DF-7110	PFU4		2	2		RFB9601745	MN
Kyocera	TA-406ci	259806	133707	X	X	KPDL/PCL	X	DF-5110	PFU4		2	2		V786402988	TX
Kyocera	TA-408ci	127109	86827	X		KPDL/PCL	X		Cab2		2	2		VZU2802685	TX
Kyocera	TA-5003i	424242	0	X		PCL/PS	X		Cab2		2	2		RFU9401710	TX
Kyocera	TA-5052ci	107969	60932	X	X	KDPL/PCL	X	DF-7110	PFU4		2	2		W2H7503437	TX
Kyocera	TA-5052ci	348090	188129	X		PCL/PS	X		PFU4		2	2		W2H8608990	TX
Kyocera	TA-5052ci	421161	329326	X		E300-01	X	DF-7110	PFU4		2	2		W2H8407963	MN
Kyocera	TA-5052ci	527176	264317	X		PCL/PS	X	DF-770	PFU4		2	2		W2H6X01055	TX
Kyocera	TA-5052ci	543484	389996	X		pcl/kpdl	X	DF-7110	PFU4		2	2		VFF7701200	MN
Kyocera	TA-5052ci	713564	0	X		pcl/kpdl	X	DF-7110	PFU4		2	2		W2H7403133	MN
Kyocera	TA-5052ci	983250	663017	X		PCL/KPDL	X		PFU4		2	2		VFF7701233	MN
Kyocera	TA-5052ci	1046866	339005	X		KPDL/PCL	X	DF-7120	PFU4		2	2		W2H8307533	MN
Kyocera	TA-5053ci	291834	87789	X		PCL/PS	X		PFU4		2	2		RF71308941	TX
Kyocera	TA-5053ci	375006	182534	X		pcl/kpdl	X	DF-7120	PFU4		2	2		RF70806661	MN
Kyocera	TA-5053ci	556390	145157	X		KPDL/PCL	X		PFU4		2	2		RF70907508	MN
Kyocera	TA-5053ci	756848	393807	X		KPDL/PCL	X	DF-7120	PFU4		2	2		RF70806616	MN
Kyocera	TA-5054ci	267807	14250	X		KPDL/PCL	X	DF-7140	PFU4		2	2		W9S2301801	MN
Kyocera	TA-5501i	1920670	0	X		KPDL/PCL	X	DF-770	PFU4		2	2		L7J6411039	MN
Kyocera	TA-6002i	125550	0	X		KPDL/PCL	X	DF-7120	PFU4		2	2		W2Z7X04137	MN
Kyocera	TA-6002i	137214	0	X		pcl/kpdl	X	DF-7120	PFU4		2	2		W2Z7X04124	MN
Kyocera	TA-6002i	313640	0	X	X	pcl/kpdl	X	DF-7120	PFU4		2	2		W2Z7X04144	MN
Kyocera	TA-6002i	421669	0	X	X	pcl/kpdl	X	DF-7120	PFU4		2	2		W2Z7X04121	MN
Kyocera	TA-6002i	1278602	0	X		pcl/kpdl	X	DF-7120	PFU4		2	2		W2Z7X04159	MN
Kyocera	TA-6052ci	374672	123039	X		KPDL/PCL	X	DF-7120	PFU4		2	2		W2D6900437	MN
Kyocera	TA-6052ci	866880	207108	X		KPDL/PCL	X	DF-7120	PFU4		2	2		W2D7Z02667	MN
Kyocera	TA-6052ci	889207	258828	X		pcl/kpdl	X	DF-7110	PFU4		2	2		W2D7501533	MN
Kyocera	TA-6052ci	1037769	348267	X	X	pcl/kpdl	X	DF-7120	PFU4		2	2		W2D6Y01120	MN
Kyocera	TA-6053ci	396410	307864	X		KPDL/PCL	X	DF7110	PFU4		2	2		RF39500864	MN
Kyocera	TA-6501i	1158852	0	X		pcl/kpdl	X		PFU4		2	2	Arrived without finisher	L8X5703028	MN
Kyocera	TA-7052ci	593288	411025	X		KPDL/PCL	X	DF-7110	PFU4	PF-730	2	2		VA38801228	MN
Kyocera	TA-8002i	417194	0	X		KPDL/PCL	X	DF-7110	PFU4		2	2	Screen Damaged	VAK6Y00294	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Kyocera	TA-8002i	725043	0	X		KPDL/PCL	X	DF-7110	PFU4		2	2		VAK7Z01450	MN
Kyocera	TA-8002i	2093268	0	X		pcl/kpdl	X	DF-7110	PFU4		2	2		VAK7Z01529	MN
Lanier	IM430F	23040	0	X	X	PCL/PS	X		PFU1		2	2		3359PC00988	TX
Lanier	IM430F	61732	0	X		PCL/PS	X		PFU1		2	2		3359PC00989	TX
Lanier	IM430F	108097	0	X		PCL/PS	X		PFU1		2	2		3359PC00990	TX
Lanier	IM430F	108880	0	X	X	pcl/ps	X		PFU1		2	2	No toner. Tested with external supplies.	3350P200630	MN
Lanier	IM550	81856	0	X	X	PCL/PS	X		Cab4		2	2	Machine is missing a couple of small pieces on the back.	3209XB21207	TX
Lanier	IM550	287067	0	X	X	PCL/PS	X		PFU1		2	2		3209XB21208	TX
Lanier	IM550	347026	0	X	X	PCL/PS	X		PFU1		2	2		3209XC22914	TX
Lanier	IM550	752090	0	X		PCL/PS	X		PFU4		2	2	Machine is a little hard to roll, missing a couple of small plastic pieces on back of machine.	3209XC23017	TX
Lanier	IM550	923640	0	X	X	PCL/PS	X		PFU1		2	2		3209XB21270	TX
Lanier	IM550	945799	0	X		PCL/PS	X		PFU1		2	2		3209XC23176	TX
Lanier	IMC2000	68151	44498	X		PCL/PS	X	Internal	Cab2		2	2		3089RC00080	MN
Lanier	IMC2000	85043	67440	X		PCL/PS	X		Cab2		2	2		3089RC00398	MN
Lanier	IMC2000	89233	74588	X		PCL/PS	X	Internal	PFU4		2	2		3089RC00678	MN
Lanier	IMC2000	148241	45655	X	X	PCL/PS	X		Cab2		2	2		3089RC000943	MN
Lanier	IMC2000	163573	7347	X		PCL/PS	X		Cab2		2	2		3089RC00666	MN
Lanier	IMC2000	176016	55349	X		PCL/PS	X		Cab2		2	2		3089RC00569	MN
Lanier	IMC2500	62584	24485	X	X	PCL/PS	X		Cab2		2	2		3090R201426	MN
Lanier	IMC2500	108756	77727	X	X	PCL/PS	X		PFU4		2	2		3090R100290	TX
Lanier	IMC2500	241541	138424	X	X	PCL/PS	X		PFU4		2	2		3090R100454	TX
Lanier	IMC3000	34814	22426	X		pcl/ps	X	SR3260	Cab2		2	2		3109RC00272	MN
Lanier	IMC3500	291099	61601	X	X	pcl/ps	X		PFU4		2	2		3110R100368	MN
Lanier	IMC4500	172683	121121	X		PCL/PS	X	SR3260	PFU4		2	2		3129RC00020	MN
Lanier	IMC4500	218170	13417	X		PCL/PS	X	SR3260	PFU3		2	2		3120RC01174	MN
Lanier	IMC4500	239475	143710	X		pcl/ps	X	SR3270	PFU3		2	2		3128MB00555	MN
Lanier	IMC4500	244336	135855	X		PCL/PS	X	SR3260	PFU4		2	2		3129RC00515	MN
Lanier	IMC4500	310138	51222	X	X	PCL/PS	X	SR3270	PFU3		2	2		3120R202374	MN
Lanier	IMC4500	356549	126975	X		PCL/PS	X		PFU4		2	2		3129R900858	MN
Lanier	IMC4500	501996	319942	X	X	PCL/PS	X		PFU4		2	2		3120R200296	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Lanier	IMC4500	571466	129250	X		PCL/PS	X		PFU4		2	2		3120R200249	TX
Lanier	IMC4500	844655	181303	X		PCL/PS	X	SR3260	PFU4		2	2		3129R801239	MN
Lanier	IMC530FB	98289	34969	X	X	PCL/PS	X	SR3270	PFU2		2	2		4202X100084	MN
Lanier	IMC530FB	102458	12738	X	X	PCL/PS	X		PFU2		2	2		4201XC00082	MN
Lanier	IMC6000	442029	65633	X	X	pcl/ps	X	SR3260	Cab2		2	2		3140RB01103	MN
Lanier	IMC6000	741372	504162	X		PCL/PS	X		PFU4		2	2		3140R100513	TX
Lanier	IMC6000	999905	119959	X	X	PCL/PS	X	SR3270	PFU4		2	2		3149RA00747	MN
Lanier	IMC6500	721071	285764	X		PCL/PS	X	SR4150	PFU3		2	2		3831C600051	TX
Lanier	MP2554	454692	0	X		PCL	X		Cab2		2	2		G145R100965	MN
Lanier	MP2555	74553	0	X		PCL/PS	X		Cab2		2	2		C290R200328	MN
Lanier	MP2555	97210	0	X	X	PCL/PS	X		Cab2		2	2		C299R420224	TX
Lanier	MPC2004ex	221058	172325	X		PCL/PS	X		Cab2		2	2		C768R310949	MN
Lanier	MPC6004	1305365	534334	X		PCL/PS	X	SR3240	PFU4		2	2		G736M661045	MN
Lanier	MPC6503	256574	105931	X		PCL/PS	X	SR4120	PFU3		2	2		C069CC00005	TX
Lanier	MPW7100	294409	0	X		PCL/PS	X		PFU2		2	2	Meter count is in feet.	G509Y800004	TX
Lanier	SP8300DN	276154	0			PCL/PS			PFU3		2	2		T425GA00002	MN
Lanier	SP8300DN	370822	0			PCL/PS			PFU3		2	2		T425GA00015	MN
Lanier	SP8300DN	429930	0			PCL/PS			PFU3		2	2		T426G300209	MN
Lanier	SP8300DN	572076	0			PCL/PS			PFU3		2	2		T426G300205	MN
Lanier	SP8300DN	617248	0			PCL/PS			PFU3		2	2		T426G300201	MN
Lanier	SPC440DN	122257	96977			pcl/ps			PFU1		2	2		X686P400592	MN
Lanier	SPC440DN	162637	85605			PCL/PS			PFU1		2	2		X686P400598	MN
Lanier	SPC830DN	44	42			PCL/PS			PFU4		2	2		T364M300041	MN
Lexmark	C2240	13698	80			PCL			PFU1		2	2		502914104HX0H	MN
Lexmark	C2240	26551	16908			PCL			PFU1		2	2		502914104HWV6	MN
Lexmark	C2240	46244	22240			PCL/PS			PFU1		2	2		5029843040VW6	TX
Lexmark	C4150	72497	19168			pcl/ps			PFU1		2	2		50289020F3MZV	MN
Lexmark	C4150	79080	0			pcl/ps			PFU1		2	2		50289020F3N09	MN
Lexmark	C4150	134884	20151			PCL/PS			PFU1		2	2		50289020F3N4D	MN
Lexmark	C4150	136268	0	X		PCL/PS	X		PFU1		2	2		50281310H5HR3	MN
Lexmark	CX622		0	X	X	pcl/ps	X		PFU1		2	2	Passed copy, user authentication is not allowing a check on the meter	75299041421HZ	MN
Lexmark	M3150	58366	0			PCL/PS			PFU1		2	2		451458HH2LVPK	TX
Lexmark	M3250	18966	0			PCL/PS			PFU1		2	2		46002284278H2	MN
Lexmark	M3250	23402	0			PCL/PS			PFU1		2	2		46002194264T0	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Ricoh	IM350F	31386	0	X	X	PCL/PS	X		PFU1		2	2		3379PC02925	MN
Ricoh	IM350F	42199	0	X	X	PCL/PS	X		PFU1		2	2		3379PC00132	MN
Ricoh	IM350F	144371	0	X	X	PCL/PS	X	PCL/PS	PFU1		2	2		3370P402798	MN
Ricoh	IM4000	443427	0	X		PCL/PS	X		PFU4		2	2		4441R500116	TX
Ricoh	IM430F	84771	0	X	X	PCL/PS	X		PFU1		2	2		3351P850079	MN
Ricoh	IM430F	124817	0	X	X	PCL/PS	X		PFU1		2	2		3350P401337	TX
Ricoh	IM430F	192847	0	X	X	PCL/PS	X		PFU1		2	2		3359PC01803	TX
Ricoh	IM430F	298557	0	X	X	PCL/PS	X		Cab1		2	2		3359P601830	TX
Ricoh	IM550	237575	0	X	X	PCL/PS	X		PFU1		2	2		3201X137641	MN
Ricoh	IM550	259640	0	X	X	PCL/PS	X		Cab2		2	2		3209XB20936	TX
Ricoh	IM6000	204470	0	X		PCL/PS	X	SR3260	PFU4		2	2		4461R500074	TX
Ricoh	IMC2000	94075	54390	X		PCL/PS	X		Cab2		2	2		3088RB00645	MN
Ricoh	IMC2500	38739	26731	X	X	pcl/ps	X		Cab2		2	2		3092RB00325	MN
Ricoh	IMC300	63464	23163	X	X	pcl/ps	X		PFU1		2	2		3920P101828	MN
Ricoh	IMC300	137942	46819	X	X	PCL/PS	X		Cab2		2	2		3921P550585	TX
Ricoh	IMC3000	19177	2344	X	X	PCL/PS	X	SR3260	Cab2		2	2		3101RB70361	TX
Ricoh	IMC3000	81913	39287	X		PCL/PS	X	Internal	Cab2		2	2	1 broke wheel	3109R900564	MN
Ricoh	IMC3000	87091	37142	X	X	PCL/PS	X	SR3260	PFU4		2	2		3109RA01543	MN
Ricoh	IMC3000	92437	68467	X		PCL/PS	X	Internal	PFU4		2	2		3109R900333	MN
Ricoh	IMC3000	94677	72547	X		PCL/PS	X	Internal	PFU4		2	2		3109R400157	MN
Ricoh	IMC3000	98718	64732	X	X	PCL/PS	X		Cab2		2	2		3101R202164	MN
Ricoh	IMC3000	119105	33527	X		PCL/PS	X	Internal	PFU4		2	2		3109RA01346	MN
Ricoh	IMC3000	220030	124053	X		Internal	X	PCL/PS	Cab2		2	2		3109R700482	MN
Ricoh	IMC3000	242482	31302	X	X	pcl/ps	X		Cab2		2	2	Dirty and yellowing.	3109RB00742	MN
Ricoh	IMC3000	254493	179336	X		pcl/ps	X	SR3260	PFU4		2	2		3109R200182	MN
Ricoh	IMC3000	314191	57893	X		PCLPS	X	Internal	Cab2		2	2		3109RB01143	MN
Ricoh	IMC3000	394822	19520	X		PCL/PS	X		PFU3		2	2	Very Dirty	3109RB00705	MN
Ricoh	IMC3500	122418	46967	X		PCL/PS	X		PFU4		2	2		3110R800281	TX
Ricoh	IMC3500	242412	83863	X	X	PCL/PS	X	SR3260	PFU4		2	2		3110R700135	MN
Ricoh	IMC3500	243976	119568	X		PCL/PS	X		PFU4		2	2		3111R500143	TX
Ricoh	IMC3500	292122	92874	X	X	pcl/ps	X		PFU4		2	2		3118RB00340	MN
Ricoh	IMC4500	118958	34044	X		PCL/PS	X	SR3270	Cab2		2	2		3129RC00899	MN
Ricoh	IMC4500	123667	83361	X		PCL/PS	X		PFU3		2	2		3129RC01424	TX
Ricoh	IMC4500	175616	113302	X		PCL/PS	X	Internal	PFU4		2	2		3129RC01124	MN
Ricoh	IMC4500	223496	174621	X		PCL/PS	X	Internal	PFU4		2	2		3129RC01930	MN
Ricoh	IMC4500	272004	181805	X		pcl/ps	X	Internal	PFU4		2	2		3129RC01020	MN
Ricoh	IMC4500	285045	182631	X		PCL/PS	X	Internal	PFU4		2	2		3129RC00787	MN
Ricoh	IMC4500	316507	186397	X		pcl/ps	X	Internal	PFU3		2	2		3120R701551	MN
Ricoh	IMC4500	341838	286297	X	X	PCL/PS	X	SR3270	PFU4		2	2		3120R701261	MN
Ricoh	IMC4500	350267	249623	X	X	pcl/ps	X		PFU4		2	2		3129M402002	MN
Ricoh	IMC4500	362466	139868	X		pcl/ps	X	Internal	PFU4		2	2	Jams at finisher	3129RC00959	MN
Ricoh	IMC4500	545300	11454	X		PCL/PS	X		PFU4		2	2	Missing finisher	3129M440199	MN
Ricoh	IMC4500	1157568	686543	X		PCL/PS	X	Internal	PFU4		2	2		3120R101614	MN
Ricoh	IMC6000	210349	151747	X		PCL/PS	X	SR3260	PFU4		2	2		3140RB00253	MN
Ricoh	IMC6000	713614	345410	X	X	pcl/ps	X	SR3260	PFU4		2	2	Dirty. Yellowing.	3149RC00420	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Ricoh	MP2501SP	184937	0	X	X	PCL	X		PFU4		2	2		E338M210027	MN
Ricoh	MP2555	25463	0	X		PCL/PS	X		Cab2		2	2		C299RA20162	MN
Ricoh	MP2555	36730	0	X		PCL/PS	X		Cab2		2	2		C299RC20004	MN
Ricoh	MP2555	213857	0	X	X	pcl/ps	X	Internal	Cab2		2	2		C299R300727	MN
Ricoh	MP301SPF	146443	0	X	X	PCL/PS	X		PFU1		2	2		W914P201791	MN
Ricoh	MP305+	21176	0	X	X	PCL/PS	X		PFU1		2	2		G588P700258	MN
Ricoh	MP305+	29875	0	X	X	PCL/PS	X		PFU2		2	2		G587P200588	TX
Ricoh	MP3055	229172	0	X	X	PCL/PS	X		Cab2		2	2	Dirty & Yellowing	C307R920010	MN
Ricoh	MP3055	229969	0	X	X	PCL/PS	X		Cab2		2	2	Dirty	C307R920081	MN
Ricoh	MP3055	300098	0	X	X	pcl/ps	X		Cab2		2	2		C307R620347	MN
Ricoh	MP3055	345737	0	X	X	PCL/PS	X		Cab2		2	2	dirty	C308R320335	MN
Ricoh	MP4054	64475	0	X		PCL/PS	X	SR3140	PFU4		2	2		G176R530431	TX
Ricoh	MP4054	668375	0	X		PCL/PS	X	SR3260	PFU4		2	2		G175R130011	TX
Ricoh	MP4054	921971	0	X		PCL/PS	X	SR3210	PFU4		2	2		G176R630126	TX
Ricoh	MP4055	157259	0	X	X	PCL/PS	X	SR3210	PFU4		2	2		C320R700937	MN
Ricoh	MP4055	221694	0	X		PCL/PS	X	SR3210	PFU4		2	2		C328R800604	TX
Ricoh	MP4055	242599	0	X		PCL/PS	X	SR3210	PFU4		2	2		C328R800091	TX
Ricoh	MP4055	369982	0	X		PCL/PS	X	SR3210	PFU4		2	2		C321R250218	TX
Ricoh	MP4055	414122	0	X	X	pcl/ps	X	Internal	Cab2		2	2		C328R800498	MN
Ricoh	MP4055	601405	0	X	X	PCL/PS	X	SR-3210	PFU4		2	2	dirty	C329R800529	TX
Ricoh	MP4055	704759	0	X		PCL/PS	X	SR3210	PFU4		2	2		C320R800750	TX
Ricoh	MP4055	809192	0	X		PCL/PS	X	SR3230	PFU4		2	2		C329R500089	TX
Ricoh	MP5002	1535675	0	X	X	pcl/ps	X		PFU3		2	2		W532L900462	MN
Ricoh	MP501	36260	0	X	X	PCL/PS	X		PFU1		2	2		G988X787434	MN
Ricoh	MP5055	23608	0	X		pcl/ps	X	SR3210	PFU4		2	2		C339R400832	MN
Ricoh	MP6055	109667	0	X	X	PCL	X	SR3210	PFU4		2	2		C340R100238	MN
Ricoh	MP6055	844263	0	X		PCL/PS	X		PFU3		2	2		C348R400160	TX
Ricoh	MP6055	1249471	0	X		PCL/PS	X		PFU3		2	2		C349R800075	TX
Ricoh	MP6503	915374	689093	X		PCL/PS	X	SR4120	PFU3		2	2		C068C100170	TX
Ricoh	MP6503	921618	0	X		PCL/PS	X	SR4120	PFU3		2	2		G658L300139	MN
Ricoh	MP6503	1180448	0	X	X	PCL	X	SR4120	PFU3	LCT	2	2		G659CB00123	MN
Ricoh	MP7503	1514367	0	X		PCL/PS	X	SR4120	PFU3		2	2		G669C400455	TX
Ricoh	MPC2003	164669	34886	X		PCL	X	Internal	Cab2		2	2	1 broke wheel	E205M460106	MN
Ricoh	MPC2003	232566	89660	X	X	PCL/PS	X		Cab2		2	2		E205M260403	MN
Ricoh	MPC2004e x	164586	52701	X		PCL/PS	X		Cab2		2	2	1 broke wheel	C767R810083	MN
Ricoh	MPC2504	263899	6360	X	X	pcl	X		PFU4		2	2		G756R710126	MN
Ricoh	MPC3003	70564	42506	X		PCL/PS	X	Internal	PFU4		2	2		E156M160002	MN
Ricoh	MPC3003	444258	218874	X	X	PCL/PS	X		PFU4		2	2		E154MA60188	MN
Ricoh	MPC3003	467490	122370	X	X	PCL	X	Internal	PFU3		2	2		E155M161189	MN
Ricoh	MPC3003	502395	72211	X	X	PCL	X		Cab2		2	2		E154M760317	MN
Ricoh	MPC3004	273338	73332	X		pcl	X	SR3210	PFU3		2	2		G696MC60732	MN
Ricoh	MPC3004	426519	182840	X	X	PCL/PS	X		PFU4		2	2		G696MC61093	MN
Ricoh	MPC3004e x	133562	32401	X		PCL/PS	X		Cab2		2	2		C717M510302	MN
Ricoh	MPC3004e x	175471	41249	X		PCL/PS	X	SR3210	PFU4		2	2	Dirty	C718M111053	MN

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Ricoh	MPC3004e x	212339	154428	X	X	pcl/ps	X	SR3210	PFU4		2	2		C718M111005	MN
Ricoh	MPC3004e x	1055107	415940	X		PCL/PS	X	SR3220	PFU4		2	2		C717M501097	MN
Ricoh	MPC307	3607	643	X		PCL/PS	X		PFU1		2	2		C508PB02335	MN
Ricoh	MPC307	10846	0	X	X	PCL/PS	X		PFU1		2	2		C509P600066	TX
Ricoh	MPC307	15339	6157	X	X	pcl/ps	X		PFU1		2	2		C507P702213	MN
Ricoh	MPC307	29882	13520	X	X	PCL/PS	X		Cab2		2	2		C509P800085	MN
Ricoh	MPC307	73888	48246	X	X	PCL/PS	X		Cab1		2	2		C508PB00300	TX
Ricoh	MPC307	114198	29733	X	X	PCL/PS	X		Cab2		2	2		C508P601133	MN
Ricoh	MPC307	187321	21915	X	X	PCL/PS	X		PFU1		2	2	Missing all toner	C507P103699	MN
Ricoh	MPC3502	740696	187977	X	X	PCL	X	SR3090	PFU4		2	2		W503L200073	MN
Ricoh	MPC3503	497155	196174	X		PCL/PS	X		PFU4		2	2		E165M111074	MN
Ricoh	MPC4503	166123	69775	X		PCL/PS	X	SR3140	PFU4		2	2		E174M810010	TX
Ricoh	MPC4503	333654	0	X	X	PCL/PS	X		PFU3		2	2		E173M710154	MN
Ricoh	MPC4503	647090	132027	X	X	PCL	X		PFU4		2	2		E175M810238	MN
Ricoh	MPC4503	1610852	50238	X	X	PCL	X	SR3140	Cab2		2	2		E175M162513	MN
Ricoh	MPC4504	398144	124041	X		PCL/PS	X	SR3210	PFU4		2	2		G716MC11027	TX
Ricoh	MPC4504E X	217377	120250	X		PCL/PS	X	SR3210	PFU4		2	2		C738MB41052	TX
Ricoh	MPC4504E X	394755	160769	X		PCL/PS	X		PFU4		2	2		C737MB40947	TX
Ricoh	MPC4504E X	559909	207825	X	X	PCL/PS	X	SR3210	PFU4		2	2	finisher damaged	C737M840638	MN
Ricoh	MPC4504E X	1008908	624195	X		PCL/PS	X	SR3140	PFU4		2	2		C738M941389	TX
Ricoh	MPC4504E X	1303194	480081	X	X	PCL/PS	X	SR3210	PFU4		2	2		C738M142513	MN
Ricoh	MPC5503	439107	139159	X	X	PCL/PS	X	SR3170	PFU4		2	2	Machine does print, need user code to access copy function.	E186M260591	TX
Ricoh	MPC6503	966345	641726	X		PCL/PS	X	SR3230	PFU3		2	2		C067CC00114	TX
Ricoh	MPC8003	372818	63903	X	X	PCL	X	SR4120	PFU3		2	2		C078CA00066	MN
Ricoh	MPCW2201 SP	5313	626			-	X				2	2	2x 36in rolls. B/W 4687 sqft. Color 626 sqft.	G931M310040	MN
Ricoh	ProC5100S	539566	461078	X		Fiery E-22B	X	Exit Tray	PFU3		2	2		E255C900026	MN
Ricoh	ProC7210s x	1746049	1619369	X		Fiery E-46A	X	SR5110	PFU2	RT5120	2	2	Extra Fuser	C880FAA0025	MN

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Ricoh	ProC7210s x	2948163	1594073	X		PCL/PS	X	SR5060	PFU2	RT5120	2	2	Missing 1 power cord, missing top cover between ADF & monitor	C889LA00293	MN
Ricoh	SPC430DN	22347	11842			PCL/PS			PFU1		2	2		S9329400364	TX
Ricoh	SPC430DN	30235	5984			PCL/PS			PFU1		2	2		S9308900201	TX
Ricoh	SPC430DN	56557	3665			PCL/PS			PFU1		2	2		S9329100084	TX
Riso	SF5130	771566	0	X			X				2	2	Machine has no ink or paper, borrowed from another unit to test.	44101590	TX
Riso	SF5130	816900	0	X			X				2	2	Machine has no ink or paper, had to borrow from another unit to test.	44101602	TX
Riso	SF5130	942775	0	X			X				2	2	Machine has no ink, borrowed from another machine to do test.	44101597	TX
Riso	SF5130	1078605	0	X			X				2	2	Machine has no ink had to borrow from another unit to test with.	44101599	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Riso	SF5130	1520404	0	X			X				2	2	Machine has no ink, had to borrow from another unit.	44101600	TX
Riso	SF5130	1586278	0	X			X				2	2	Machine has no ink or paper, borrowed from another unit to test.	44101591	TX
Riso	SF5130	1669176	0	X			X				2	2	Machine has no ink or paper had to borrow from another unit to test.	44101595	TX
Riso	SF5130	1803495	0	X			X				2	2	Machine has no ink or paper, borrowed from another to test.	44101596	TX
Riso	SF5130	3236632	0	X			X				2	2	Machine has no ink, had to borrow from another unit to test with.	44101601	TX
Savin	IMC2500	27277	19504	X		PCL/PS	X	SR3260	PFU4		2	2		3091R300460	TX
Savin	IMC2500	29731	14335	X	X	PCL/PS	X		PFU4		2	2		3090RA00254	TX
Savin	IMC3000	76728	26606	X	X	PCL/PS	X		Cab2		2	2		3101RA70451	TX
Savin	IMC3000	104635	56941	X	X	PCL/PS	X		Cab2		2	2		3101RA70416	TX
Savin	IMC3000	122572	56044	X		PCL/PS	X		Cab2		2	2		3101RA70314	TX
Savin	MP4055	990505	0	X		PCL/PS	X	SR3210	PFU4		2	2		C320RA00553	MN
Savin	MP5055	528203	0	X		PCL/PS	X	SR3140	PFU4		2	2		C339R600305	TX
Savin	MPC307	203314	144543	X		PCL/PS	X		Cab1		2	2		C507P106949	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Savin	MPC4504E X	223481	131578	X		PCL/PS	X		PFU4		2	2	missing small front piece between PFU-2 and PFU-3	C738MB40439	TX
Savin	MPC4504E X	234458	75858	X	X	PCL/PS	X		PFU4		2	2		C738M240711	TX
Sharp	MX-2651	13123	8830	X		PCL	X		Cab2		2	2		95045715	MN
Sharp	MX-2651	58582	43135	X	X	pcl/ps	X	Internal	Cab2		2	2		95043106	MN
Sharp	MX-2651	59016	34050	X		PCL/PS	X		Cab2		2	2		0305212Y	TX
Sharp	MX-2651	68162	34392	X		PCL/PS	X	Internal	PFU3		2	2		9301744Y	MN
Sharp	MX-2651	68452	28854	X		pcl	X	Internal	Cab2		2	2		95060939	MN
Sharp	MX-2651	90858	19847	X		PCL/PS	X		Cab2		2	2		9501748X	TX
Sharp	MX-2651	98522	53048	X		PCL/PS	X		Cab2		2	2	Dirty	95059310	MN
Sharp	MX-2651	109765	74951	X		PCL	X	Internal	Cab2		2	2	dirty	95042966	MN
Sharp	MX-2651	127217	56069	X		PCL/PS	X		Cab2		2	2		03013281a	MN
Sharp	MX-2651	180750	80382	X	X	PCL/PS	X	Internal	Cab2		2	2		9302001Y	MN
Sharp	MX-2651	205904	40974	X	X	pcl/ps	X		Cab2		2	2		15031197	MN
Sharp	MX-2651	271420	70567	X		PCL/PS	X	Internal	PFU3		2	2		9301953Y	MN
Sharp	MX-3051	87442	64229	X		PCL/PS	X		PFU3		2	2		15035799	TX
Sharp	MX-3070N	122645	72753	X		pcl/ps	X		PFU4		2	2	Error E7-90. Can't test.	65038740	MN
Sharp	MX-3070N	144849	96636	X	X	PCL/PS	X	Internal	PFU3		2	2		55099410	MN
Sharp	MX-3070V	137657	52035	X		PCL/PS	X		Cab2		2	2	Missing Wheel	7506155Y	MN
Sharp	MX-3070V	222606	138404	X		PCL/PS	X		Cab2		2	2		7506182Y	TX
Sharp	MX-3071	19309	14147	X	X	pcl/ps	X	Internal	PFU4		2	2		15069454	MN
Sharp	MX-3071	29590	21820	X		PCL/PS	X	Internal	PFU4		2	2		15050376	MN
Sharp	MX-3071	62583	17109	X	X	pcl/ps	X		Cab2		2	2		9302836Y	MN
Sharp	MX-3071	71026	9501	X		PCL/PS	X		Cab2		2	2		05098763a	MN
Sharp	MX-3071	87066	45742	X		PCL/PS	X		PFU4		2	2		15057026	TX
Sharp	MX-3071	92064	78366	X	X	PCL/PS	X		Cab2		2	2		1514784Y	TX
Sharp	MX-3071	103936	50149	X	X	PCL/PS	X		PFU4		2	2		9303247Y	TX
Sharp	MX-3071	107727	16979	X		pcl/ps	X		PFU3		2	2		03027281a	MN
Sharp	MX-3071	115216	46201	X	X	PCL/PS	X	Internal	PFU4		2	2		05071867a	MN
Sharp	MX-3071	116662	66902	X		PCL/PS	X	MX-FN28	PFU4		2	2		0304379Y	TX
Sharp	MX-3071	117763	42028	X	X	PCL/PS	X		PFU4		2	2		05094503a	MN
Sharp	MX-3071	132687	28566	X		pcl/ps	X		PFU3		2	2		03027251a	MN
Sharp	MX-3071	137748	48275	X	X	pcl/ps	X		PFU4		2	2		0304841Y	MN
Sharp	MX-3071	162017	56892	X		PCL/PS	X		PFU3		2	2		03027211a	MN
Sharp	MX-3071	162299	93926	X		PCL/PS	X	Internal	PFU4		2	2		03014230a	MN
Sharp	MX-3071	172705	77415	X	X	pcl/ps	X		PFU3		2	2		9302693Y	MN
Sharp	MX-3071	175158	80457	X	X	PCL/PS	X		PFU3		2	2		9303160Y	MN
Sharp	MX-3071	186506	65815	X	X	PCL/PS	X		PFU2		2	2		03022711a	MN
Sharp	MX-3071	197175	58907	X	X	PCL/PS	X	Internal	Cab2		2	2		9302513Y	MN
Sharp	MX-3071	197588	105621	X		PCL/PS	X		PFU2		2	2		03031689a	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Sharp	MX-3071	198642	55308	X		PCL/PS	X		PFU3		2	2		9300129X	MN
Sharp	MX-3071	198981	7817	X	X	PCL/PS	X		PFU3		2	2		9302901Y	MN
Sharp	MX-3071	219682	3107	X	X	PCL/PS	X		PFU4		2	2		05094913a	MN
Sharp	MX-3071	238781	93749	X		pcl/ps	X		PFU3		2	2		05070307a	MN
Sharp	MX-3071	244933	141813	X	X	pcl/ps	X	Internal	PFU4		2	2		03014050a	MN
Sharp	MX-3071	247958	138399	X		PCL/PS	X		Cab2		2	2		03013540a	TX
Sharp	MX-3071	271949	229778	X		PCL/PS	X		PFU4		2	2		15069704	MN
Sharp	MX-3071	279832	196023	X		PCL/PS	X	Internal	PFU4		2	2		03014150a	MN
Sharp	MX-3071	337399	174079	X	X	pcl/ps	X		Cab2		2	2		03022651a	MN
Sharp	MX-3071	410000	161795	X	X	pcl/ps	X	Internal	PFU4		2	2		05071447a	MN
Sharp	MX-3071	432150	75289	X		PCL/PS	X		Cab2		2	2		9300037X	TX
Sharp	MX-3071	435901	205290	X		PCL/PS	X		Cab2		2	2		03026851a	MN
Sharp	MX-3071	439808	102191	X		PCL/PS	X	MX-FN28	PFU4		2	2		95026149	MN
Sharp	MX-3071	500176	413372	X		PCL/PS	X	Internal	PFU4		2	2	Maintenanc e Code TK1	03015340a	MN
Sharp	MX-3071S	23682	18913	X		PCL/PS	X	Internal	PFU4		2	2		15039827	MN
Sharp	MX-3071S	90957	55440	X	X	pcl/ps	X		PFU4		2	2		25060201	MN
Sharp	MX-3100N	233874	67353	X		PCL/PS	X	Internal	PFU3		2	2		95041685	MN
Sharp	MX-3100N	349717	145204	X		PCL	X		Cab2		2	2		85058798	MN
Sharp	MX-3501	110239	90214	X		PCL/PS	X		Cab2		2	2		05143609a	TX
Sharp	MX-3550V	121821	58030	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		85102666	TX
Sharp	MX-3551	103114	39216	X		PCL	X		Cab2		2	2		05143759a	MN
Sharp	MX-3571	111388	64701	X		PCL/PS	X		PFU4		2	2		05144129a	MN
Sharp	MX-3571	111692	30097	X		PCL/PS	X		Cab2		2	2		95085736	TX
Sharp	MX-3571	128585	57697	X		pcl/ps	X		PFU4		2	2		95095920	MN
Sharp	MX-3571	224709	84515	X	X	PCL/PS	X		PFU4		2	2		05144219a	MN
Sharp	MX-4051	332240	182130	X		PCL/PS	X		Cab2		2	2		15059276	TX
Sharp	MX-4070N	329379	192736	X	X	pcl/ps	X	Internal	PFU4		2	2		75084470	MN
Sharp	MX-4071	42098	0	X	X	PCL/PS	X		PFU4		2	2		13013350	TX
Sharp	MX-4071	44334	10713	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		9510284X	MN
Sharp	MX-4071	55268	32621	X	X	pcl/ps	X		PFU4		2	2		03035343a	MN
Sharp	MX-4071	65541	48321	X	X	pcl/ps	X		PFU4		2	2		95135137	MN
Sharp	MX-4071	74144	13644	X		PCL/PS	X		PFU4		2	2		1506190X	TX
Sharp	MX-4071	92255	19801	X		PCL/PS	X	Internal	PFU4		2	2		03042839a	MN
Sharp	MX-4071	129655	71645	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		95097423	MN
Sharp	MX-4071	133161	73874	X	X	pcl/ps	X	Internal	PFU4		2	2	Missing wheel	95106621	MN
Sharp	MX-4071	147849	69700	X		pcl/ps	X	Internal	PFU3		2	2		03021022a	MN
Sharp	MX-4071	162512	39210	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		85131290	TX
Sharp	MX-4071	165479	64254	X	X	pcl/ps	X	Internal	PFU4		2	2		15056360	MN
Sharp	MX-4071	177394	57604	X		PCL/PS	X		Cab2		2	2		15055970	TX
Sharp	MX-4071	195966	11070	X		PCL/PS	X		PFU4		2	2		1515593Y	MN
Sharp	MX-4071	212562	17473	X		PCL/PS	X		PFU4	LCT	2	2		1515612Y	MN
Sharp	MX-4071	246180	117197	X	X	pcl/ps	X	Internal	PFU4		2	2		9303902Y	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Sharp	MX-4071	259523	170494	X	X	PCL/PS	X	Internal	PFU3		2	2		9304416Y	MN
Sharp	MX-4071	309355	127488	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		9303776Y	MN
Sharp	MX-4071	323736	74651	X		pcl/ps	X	MX-FN29	PFU4		2	2		03035723a	MN
Sharp	MX-4071	326455	62756	X		pcl/ps	X	MX-FN28	PFU4		2	2		95102731	MN
Sharp	MX-4071	333878	196060	X	X	PCL/PS	X		Cab2		2	2		03031471a	MN
Sharp	MX-4071	344702	261958	X		PCL/PS	X	MX-FN28	PFU4		2	2		15061276	TX
Sharp	MX-4071	348762	187158	X	X	PCL/PS	X	Internal	PFU3		2	2		95110329	MN
Sharp	MX-4071	365649	241155	X		pcl/ps	X		PFU4		2	2	Missing wheel	95097145	MN
Sharp	MX-4071	618563	32251	X	X	pcl/ps	X	MX-FN29	PFU4		2	2		9303791Y	MN
Sharp	MX-4071	684515	347883	X		PCL/PS	X		Cab2		2	2		95090146	TX
Sharp	MX-4141N	3	0	X	X	PCL/PS	X		PFU3		2	2	missing all toner cartridges,	55157051	TX
Sharp	MX-5071	35063	6471	X		PCL/PS	X	MX-FN28	PFU4		2	2		1506266X	TX
Sharp	MX-5071	110387	51386	X	X	PCL/PS	X		PFU4		2	2		03033291a	TX
Sharp	MX-5071	181296	116440	X	X	pcl/ps	X	MX-FN28	PFU4		2	2	Dirty	03029308a	MN
Sharp	MX-5071	216217	208742	X		PCL/PS	X		PFU4		2	2		1506478Y	MN
Sharp	MX-5071	231382	144034	X		PCL/PS	X	MX-FN28	PFU4		2	2		03042553a	MN
Sharp	MX-5071	238367	114385	X	X	PCL/PS	X		PFU4		2	2		95034929	TX
Sharp	MX-5071	259156	61778	X	X	PCL/PS	X	Missing	PFU4		2	2	Missing Finisher	03036661a	MN
Sharp	MX-5071	267337	81695	X	X	PCL/PS	X		PFU4		2	2		95035539	TX
Sharp	MX-5071	281030	166715	X	X	PCL/PS	X		PFU4		2	2		95035139	TX
Sharp	MX-5071	313588	129588	X		PCL/PS	X	Internal	Cab2		2	2		03051489a	MN
Sharp	MX-5071	371509	69018	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		03036651a	MN
Sharp	MX-5071	394537	105264	X	X	PCL/PS	X	MX-FN30	PFU4		2	2		95035159	TX
Sharp	MX-5071	404937	136621	X		PCL/PS	X		PFU4		2	2		95034459	TX
Sharp	MX-5071	413863	333797	X	X	pcl/ps	X	MX-FN30	PFU4		2	2		13006404	MN
Sharp	MX-5071	434414	371854	X		pcl/ps	X	Internal	PFU4		2	2		03038605a	MN
Sharp	MX-5071	437097	205016	X		pcl/ps	X	MX-FN29	PFU4		2	2		0302150Y	MN
Sharp	MX-5071	442162	166580	X	X	PCL/PS	X	MX-FN31	PFU4		2	2		03042383a	MN
Sharp	MX-5071	446344	187462	X	X	PCL/SP	X		PFU4		2	2		95035429	MN
Sharp	MX-5071	470402	177044	X		PCL/PS	X	MX-FN29	PFU4		2	2		03029478a	MN
Sharp	MX-5071	510262	174244	X	X	PCL/PS	X	Internal	PFU4		2	2		03049139a	MN
Sharp	MX-5071	543277	50529	X		pcl/ps	X	Internal	PFU4		2	2		0302136Y	MN
Sharp	MX-5071	619551	281993	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		05035386a	MN
Sharp	MX-5071	697463	340326	X	X	PCL/PS	X	MX-FN28	PFU4		2	2		95122804	TX
Sharp	MX-5071	817886	562662	X		PCL/PS	X		PFU4		2	2		03036691a	MN
Sharp	MX-5071	825955	385109	X	X	pcl/ps	X	MX-FN30	PFU4		2	2		03038195a	MN
Sharp	MX-5071S	110246	77420	X		pcl/ps	X		PFU4		2	2		25100683	MN
Sharp	MX-5141N	447493	64288	X		PCL/PS	X		PFU4		2	2		65009621	TX
Sharp	MX-6050	57294	16476	X	X	PCL/PS	X		PFU4		2	2		6508671Y	TX
Sharp	MX-6070	849895	455536	X	X	PCL/PS	X	MX-FN29	PFU4		2	2		65105778a	TX
Sharp	MX-6070N	243537	122087	X	X	PCL/PS	X	MX-FN29	PFU4		2	2		65140684	MN
Sharp	MX-6071	146619	41267	X		pcl/ps	X	MX-FN29	PFU4		2	2		03052559a	MN
Sharp	MX-6071	333547	233473	X	X	PCL/PS	X	Internal	PFU4		2	2	Dirty	9305210Y	MN

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Sharp	MX-6071	381597	149899	X	X	pcl/ps	X	MX-FN29	PFU4		2	2	Error E6-11 shading white correction error.	95027590	MN
Sharp	MX-6071	437887	315959	X		pcl/ps	X	Internal	PFU4		2	2		03052509a	MN
Sharp	MX-6071	490159	202173	X		PCL/PS	X	Internal	PFU4		2	2	Dirty	9305195Y	MN
Sharp	MX-6071	524607	99871	X	X	pcl/ps	X		PFU4		2	2		9305067Y	MN
Sharp	MX-6071	614152	304040	X	X	PCL/PS	X	Internal	PFU4		2	2		03052399a	MN
Sharp	MX-6071	888703	430936	X		pcl/ps	X	MX-FN29	PFU4		2	2		9305233Y	MN
Sharp	MX-6580N	168134	70377	X		Fiery E300-08 (MX-PE12)	X	MX-FN22	PFU3		2	2	MX-RB15, Unable to print from controller	05121257a	MN
Sharp	MX-6580N	356957	115006	X	X	pcl/ps	X	MX-FN21	PFU4		2	2	Missing back right wheel.	5071871	MN
Sharp	MX-6580N	371131	167439	X	X	pcl/ps	X	MX-FN19	PFU4		2	2		5071601	MN
Sharp	MX-6580N	778238	131906	X	X	pcl/ps	X	MX-FN19	PFU4		2	2		5072041	MN
Sharp	MX-6580N	853957	166866	X	X	pcl/ps	X	A-FN19	PFU4		2	2		5072311	MN
Sharp	MX-6580N	1059540	173297	X	X	pcl/ps	X	MX-FN19	PFU4		2	2		5071851	MN
Sharp	MX-B355W	7211	0	X	X	pcl/ps	X		Cab1		2	2		9F002583	MN
Sharp	MX-B376W	11843	0	X	X	PCL/PS	X		PFU1		2	2		9F006978	MN
Sharp	MX-B376W	86513	0	X	X	PCL/PS	X		PFU1		2	2		0F012699	MN
Sharp	MX-B450W	966	0	X	X	pcl/ps	X		Cab1		2	2		0F00363Y	MN
Sharp	MX-B450W	2357	0	X	X	pcl/ps	X		PFU1		2	2	Dirty	9F01447X	MN
Sharp	MX-B450W	3154	0	X	X	PCL/PS	X		PFU1		2	2	dirty	9F01445X	MN
Sharp	MX-B450W	6534	0	X	X	pcl/ps	X		Cab2		2	2		9F01446X	MN
Sharp	MX-B467F	18463	0	X	X	PCL/PS	X		PFU1		2	2		701721340VR4L	MN
Sharp	MX-B467F	31434	0	X	X	PCL/PS	X		PFU1		2	2		701710230PPWK	MN
Sharp	MX-B467F	38232	0	X	X	PCL/PS	X		PFU1		2	2		701710230PPWY	MN
Sharp	MX-B467F	144594	0	X	X	PCL/PS	X		PFU1		2	2		70171440TMY4	TX
Sharp	MX-B467P	3997	0			PCL/PS			PFU1		2	2		460010231PFZT	MN
Sharp	MX-B467P	6504	0			PCL/PS			PFU1		2	2		460010231PFW6	MN
Sharp	MX-B467P	10104	0			PCL/PS			PFU1		2	2		460010231PFWL	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Sharp	MX-B467P	10399	0			PCL/PS			PFU1		2	2		460010231PFZ5	MN
Sharp	MX-B467P	10936	0			PCL/PS			PFU1		2	2		460010231PFR7	MN
Sharp	MX-B467P	12217	0			PCL/PS			PFU1		2	2		460010231PFX8	MN
Sharp	MX-B467P	12382	0			PCL/PS			PFU1		2	2		460010231PFB6	MN
Sharp	MX-B467P	13481	0			PCL/PS			PFU1		2	2		460010231PFZL	MN
Sharp	MX-B467P	18221	0			PCL/PS			PFU1		2	2		460010231PFY4	MN
Sharp	MX-B467P	19722	0			PCL/PS			PFU1		2	2		460010231PFXG	MN
Sharp	MX-B467P	19899	0			PCL/PS			PFU1		2	2		460010231PFX1	MN
Sharp	MX-B467P	25634	0			PCL/PS			PFU1		2	2		460010231PFXN	MN
Sharp	MX-B467P	26158	0			PCL/PS			PFU1		2	2		460010231PFVC	MN
Sharp	MX-B467P	27519	0			PCL/PS			PFU1		2	2		460010231PFZ0	MN
Sharp	MX-B467P	31587	0			PCL/PS			PFU1		2	2		460010231PFZG	MN
Sharp	MX-B467P	40849	0			PCL/PS			PFU1		2	2		460010231PF2H	MN
Sharp	MX-B467P	48654	0			PCL/PS			PFU1		2	2		460010231PFYY	MN
Sharp	MX-B476W	92108	0	X	X	PCL/PS	X		PFU1		2	2		0F011529	MN
Sharp	MX-B476W	140132	0	X	X	PCL/PS	X		PFU1		2	2		0F011599	MN
Sharp	MX-B476W	378161	0	X		PCL/PS	X		PFU1		2	2	Machine is a little dirty.	0F010900	TX
Sharp	MX-C303W	60049	49379	X	X	PCL/PS	X		PFU1		2	2		13022424	MN
Sharp	MX-C303W	174354	73244	X	X	pcl/ps	X		Cab2		2	2		93018957	MN
Sharp	MX-C304W	267	115	X	X	PCL/PS	X		PFU1		2	2		13019984	MN
Sharp	MX-C304W	86710	16832	X	X	PCL/PS	X		Cab1		2	2		03014705a	MN
Sharp	MX-C304W	109167	60084	X	X	pcl/ps	X		PFU1		2	2		03017140a	MN
Sharp	MX-C304W	125307	115599	X	X	PCL/PS	X		PFU1		2	2		8301993Y	MN
Sharp	MX-C304W	139375	49294	X	X	PCL/PS	X		Cab3		2	2		93028191	MN
Sharp	MX-C304W	172348	16550	X	X	pcl/ps	X		Cab2		2	2		9302000X	MN



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Sharp	MX-C304WH	77493	29795	X	X	PCL/PS	X		Cab2		2	2		23017364	MN
Sharp	MX-C304WH	87377	62204	X	X	pcl/ps	X		Cab2		2	2		23017354	MN
Sharp	MX-C304WH	88941	65154	X	X	pcl/ps	X		Cab2		2	2		23016974	MN
Sharp	MX-C407F	37870	7142	X	X	PCL/PS	X		PFU2		2	2		75280360G5DZ9	MN
Sharp	MX-C507F	11639	9705	X	X	PCL/PS	X		PFU2		2	2		75281450H6L5Y	TX
Sharp	MX-C507F	13535	10977	X		PCL/PS	X		PFU2		2	2		75281450H6L59	TX
Sharp	MX-C507F	16819	12361	X	X	PCL/PS	X		PFU2		2	2		75281450H6L55	TX
Sharp	MX-C507F	16968	10318	X	X	PCL/PS	X		PFU2		2	2		75281450H6L81	TX
Sharp	MX-C507F	21198	16191	X	X	PCL/PS	X		PFU2		2	2		75281450H6L65	TX
Sharp	MX-C507F	29103	25296	X	X	PCL/PS	X		PFU2		2	2		75281450H6L6C	TX
Sharp	MX-C507F	31165	25186	X	X	PCL/PS	X		PFU2		2	2		75281450J6L60	TX
Sharp	MX-M2651	41757	0	X	X	PCL/PS	X		Cab2		2	2		1300036X	TX
Sharp	MX-M2651	90405	0	X	X	pcl/ps	X	Internal	Cab2		2	2		15022649	MN
Sharp	MX-M3051	17383	0	X		PCL/PS	X		Cab2		2	2		95018220	MN
Sharp	MX-M3051	64323	0	X		PCL	X		Cab2		2	2		95013328	MN
Sharp	MX-M3051	66743	0	X		PCL/PS	X		Cab2		2	2		1300137X	TX
Sharp	MX-M3051	107850	0	X	X	pcl	X		Cab2		2	2		95018240	MN
Sharp	MX-M3051	116086	0	X		pcl/ps	X		Cab2		2	2	Dirty	95017720	MN
Sharp	MX-M3051	135178	0	X		PCL/PS	X		Cab2		2	2		95017780	MN
Sharp	MX-M3070	236327	0	X	X	PCL/PS	X	Internal	PFU4		2	2		95018325	MN
Sharp	MX-M3071	64004	0	X	X	PCL/PS	X		PFU4		2	2	Dirty/Yellowed	03003259a	MN
Sharp	MX-M3071	102192	0	X		PCL/PS	X	Internal	PFU4		2	2		0304135X	MN
Sharp	MX-M3071	117107	0	X		pcl/ps	X	Internal	PFU4		2	2		0304145X	MN
Sharp	MX-M3071	129516	0	X	X	pcl/ps	X		Cab2		2	2		0303990X	MN
Sharp	MX-M3071	179778	0	X		PCL/PS	X		PFU4		2	2		15010284	TX
Sharp	MX-M3071	308388	0	X		PCL/PS	X		Cab2		2	2		15010924	TX
Sharp	MX-M3071	316768	0	X	X	pcl/ps	X		Cab2		2	2		0304162X	MN
Sharp	MX-M3071	393454	0	X		pcl/ps	X		Cab2		2	2		0304169x	MN
Sharp	MX-M3570	105823	0	X		PCL/PS	X		PFU4		2	2		95007635	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Sharp	MX-M3570	168084	53344	X	X	PCL/PS	X		PFU3		2	2		5508708Y	TX
Sharp	MX-M364	366466	0	X		PCL/PS	X		Cab2		2	2	Machine is very dirty/dusty.	65002820	TX
Sharp	MX-M364	373306	0	X		PCL/PS	X		Cab2		2	2		75003035	TX
Sharp	MX-M364N	262410	0	X	X	pcl	X		Cab2		2	2		5500409Y	MN
Sharp	MX-M365N	270006	0	X		PCL/PS	X		Cab2		2	2		65009964	MN
Sharp	MX-M365N	420659	0	X		PCL/PS	X		PFU4		2	2		75009011	TX
Sharp	MX-M4071	102657	0	X		pcl/ps	X		PFU4		2	2		13018334	MN
Sharp	MX-M4071	192614	0	X	X	pcl/ps	X		Cab2		2	2		0303480X	MN
Sharp	MX-M4071	532143	0	X	X	PCL/PS	X	Internal	Cab2		2	2		3007982	MN
Sharp	MX-M465	230473	0	X		PCL/PS	X		Cab2		2	2		75009778	TX
Sharp	MX-M465	569227	0	X		PCL/PS	X		Cab2		2	2		75013635	TX
Sharp	MX-M465N	473904	0	X	X	PCL/PS	X	Internal	PFU4		2	2	Home Button Unresponsive	45023600	MN
Sharp	MX-M5071	173560	0	X		PCL/PS	X		PFU4		2	2		15011567	MN
Sharp	MX-M5071	470110	0	X	X	PCL/PS	X		PFU4		2	2		95036868	MN
Sharp	MX-M5071	642070	0	X	X	pcl/ps	X		PFU4		2	2		9300325Y	MN
Sharp	MX-M6071	472296	0	X		pcl/ps	X		Cab2		2	2		03015499a	MN
Sharp	MX-M6071	852557	0	X		PCL/PS	X	MX-FN30	PFU4		2	2		03013409a	MN
Sharp	MX-M654N	956744	0	X	X	PCL/PS	X	Internal	PFU4		2	2	Finisher cable damaged.	75001142	MN
Sharp	MX-M7570	181760	0	X	X	PCL/PS	X	MX-FN34	PFU3		2	2		95002400	TX
Sharp	MX-M7570	381830	0	X	X	PCL/PS	X	MX-FN34	PFU3		2	2		95007499	TX
Sharp	MX-M7570	597041	0	X		PCL/PS	X	Internal	PFU4		2	2		300185000	MN
Sharp	MX-M7570	642493	0	X		pcl/ps	X	MX-FN34	PFU4		2	2		5001303	MN
Sharp	MX-M7570	952530	0	X		pcl/ps	X	MX-FN34	PFU4		2	2		5001413	MN
Sharp	MX-M7570	979027	0	X		PCL/PS	X	MX-FN34	PFU4		2	2		5001213	MN
Sharp	MX-M7570	1108348	0	X	X	pcl/ps	X	MX-FN34	PFU4		2	2		5001373	MN



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Sharp	MX-M7570	1153804	0	X		PCL/PS	X	MX-FN34	PFU4		2	2	Back Right Corner Damaged	5001483	MN
Sharp	MX-M7570	1876756	0	X	X	PCL/PS	X	MX-FN34	PFU3		2	2		05003315a	MN
Sharp	MX-M7570	3260222	0	X	X	PCL/PS	X	MX-FN21	PFU3		2	2	MX-RB27	03005390a	MN
Sharp	MX-M905	902836	0	X		PCL/PS	X	MX-FN21	PFU4		2	2	MX-RB18	95004400	MN
Sharp	MX-M905	1173425	0	X		pcl/ps	X	A-FN24	PFU4		2	2		5001211	MN
Sharp	MX-M905	1425787	0	X		PCL/PS	X	MX-FN24	PFU4		2	2		05001061a	MN
Sharp	MX-M905	1935514	0	X		pcl/ps	X	MX-FN24	PFU4		2	2		95004160	MN
Sharp	MX-M905	2060036	0	X		PCL/PS	X	MX-FN24	PFU4		2	2		5001071	MN
Toshiba	E-2018A	735	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZAL10817	MN
Toshiba	E-2018A	2244	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZDL19493	MN
Toshiba	E-2018A	9427	0	X	X	pcl/ps	X	Internal	Cab2		2	2		CZAL10854	MN
Toshiba	E-2018A	16898	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZDL19490	MN
Toshiba	E-2018A	40749	0	X		pcl/ps	X	Internal	Cab2		2	2		CZKL45341	MN
Toshiba	E-2018A	42474	0	X		pcl/ps	X	Internal	Cab2		2	2		CZHL36623	MN
Toshiba	E-2018A	44662	0	X		PCL/PS	X	Internal	PFU3		2	2		CFUJ51770	MN
Toshiba	E-2018A	47085	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZLK66341	MN
Toshiba	E-2018A	51190	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZAL10830	MN
Toshiba	E-2018A	78118	0	X		pcl/ps	X	Internal	Cab2		2	2		CZHL33605	MN
Toshiba	E-2018A	100117	0	X	X	pcl/ps	X	Internal	PFU3		2	2		CZDL19487	MN
Toshiba	E-2018A	114526	0	X		pcl/ps	X	Internal	Cab2		2	2		CZIL38102	MN
Toshiba	E-2510AC	48074	19350	X	X	PCL/PS	X	Internal	Cab2		2	2		CNKL15735	TX
Toshiba	E-2515AC	3718	2181	X	X	PCL/PS	X	Internal	PFU3		2	2		SNHL88728	TX
Toshiba	E-2515AC	5714	2476	X		PCL/PS	X	Internal	PFU3		2	2		CNDJ42746	TX
Toshiba	E-2515AC	7196	2965	X		PCL/PS	X	Internal	PFU3		2	2		CNLJ57141	TX
Toshiba	E-2515AC	22656	7750	X		PCL/PS	X	Internal	PFU3		2	2		CNFJ55644	TX
Toshiba	E-2515AC	24344	10808	X	X	PCL/PS	X	Internal	PFU3		2	2		CNFL61376	MN
Toshiba	E-2515AC	31883	15487	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCJ37776	TX
Toshiba	E-2515AC	32364	18915	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCJ39632	TX
Toshiba	E-2515AC	34216	17086	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCL47508	MN
Toshiba	E-2515AC	34864	16452	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCJ39616	TX
Toshiba	E-2515AC	40045	25514	X	X	PCL/PS	X	Internal	PFU3		2	2		CNFL61494	MN
Toshiba	E-2515AC	49498	28562	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCJ39619	TX
Toshiba	E-2515AC	57616	16302	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCJ39638	TX
Toshiba	E-2515AC	73038	41796	X	X	PCL/PS	X	Internal	Cab2		2	2		CNKJ44809	TX
Toshiba	E-2515AC	73858	56036	X	X	pcl/ps	X	Internal	PFU3		2	2		CNIL38601	MN
Toshiba	E-2515AC	73985	59470	X		PCL/PS	X	Internal	Cab2		2	2		CNKJ44813	TX
Toshiba	E-2515AC	75872	15079	X	X	PCL/PS	X	Internal	PFU3		2	2		CNDJ42717	TX
Toshiba	E-2515AC	84972	63777	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCJ39621	TX
Toshiba	E-2515AC	96771	49731	X	X	PCL/PS	X	Internal	PFU3		2	2		CNEJ53411	TX
Toshiba	E-2515AC	99280	79535	X		PCL/PS	X	Internal	PFU4		2	2		CNDK32121	MN
Toshiba	E-2515AC	133557	59458	X		PCL/PS	X	Internal	Cab2		2	2		CNKJ44817	TX
Toshiba	E-2515AC	154857	15072	X	X	PCL/PS	X	Internal	PFU3		2	2		CNCJ37775	TX
Toshiba	E-2515AC	164869	134081	X	X	pcl/ps	X	Internal	PFU3		2	2		SNDL87180	MN
Toshiba	E-2518A	2230	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZHH18083	TX
Toshiba	E-2518A	5292	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CZEJ54718	TX
Toshiba	E-2518A	7525	0	X		PCL/PS	X	Internal	PFU3		2	2		CZHH18070	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

														Duplex cover on the right does not shut, message displayed on screen		
Toshiba	E-3015AC	136641	80744	X	X	PCL/PS	X		PFU3		2	2		CNGJ63411	TX	
Toshiba	E-3015AC	145262	30715	X		PCL/PS	X	MJ-1109	Cab2		2	2		SNFL87704	MN	
Toshiba	E-3015AC	177537	96870	X		PCL/PS	X		PFU3		2	2		CNGJ63422	TX	
Toshiba	E-3015AC	190760	98804	X		PCL/PS	X		PFU3		2	2		CNGJ63396	TX	
Toshiba	E-3015AC	215717	134603	X	X	PCL/PS	X	MJ-1109	PFU3		2	2		CNDK32845	TX	
Toshiba	E-3015AC	270291	175246	X	X	PCL/PS	X		PFU3		2	2		CNGJ63417	TX	
Toshiba	E-3018A	95349	0	X		pcl/ps	X	Internal	Cab2		2	2		CZIK53769	MN	
Toshiba	E-3018A	244558	0	X		PCL/PS	X		PFU3		2	2		ZJJ70484	MN	
Toshiba	E-3508A	657637	0	X		PCL/PS	X		PFU3		2	2		CGBG59392	TX	
Toshiba	E-3515AC	45192	26510	X	X	PCL/PS	X		PFU3		2	2		SNGL88489	TX	
Toshiba	E-3515AC	45939	21498	X	X	pcl/ps	X		Cab2		2	2		CNLL57900	MN	
Toshiba	E-3515AC	54893	17179	X	X	PCL/PS	X	Internal	PFU3		2	2		SNLK84920	MN	
Toshiba	E-3515AC	58774	31385	X	X	PCL/PS	X		PFU3		2	2		CNHJ30061	TX	
Toshiba	E-3515AC	66814	24825	X	X	PCL/PS	X	Internal	PFU3		2	2		SNLK84820	MN	
Toshiba	E-3515AC	79397	31893	X	X	PCL/PS	X		PFU3		2	2		CNFJ58390	TX	
Toshiba	E-3515AC	80920	46855	X	X	PCL/PS	X	Internal	PFU3		2	2		SNFL88225	MN	
Toshiba	E-3515AC	89051	40785	X	X	PCL/PS	X		PFU3		2	2		CNHJ30048	TX	
Toshiba	E-3515AC	93888	56356	X	X	PCL/PS	X	Internal	PFU3		2	2		SNLK84946	MN	
Toshiba	E-3515AC	131900	0	X	X	PCL/PS	X	Internal	PFU3		2	2		CNAM61331	MN	
Toshiba	E-3515AC	156063	6782	X		PCL/PS	X		Cab2		2	2		SNFL87738	TX	
Toshiba	E-3515AC	167192	108814	X		PCL/PS	X		Cab2		2	2		CNAM67354	TX	
Toshiba	E-3515AC	167700	105388	X		PCL/PS	X		PFU3		2	2		CNHJ30065	TX	
Toshiba	E-3515AC	168121	36771	X		pcl/ps	X	MJ-1109	PFU3		2	2	MJ-6105N	CNGK44279	MN	
Toshiba	E-3515AC	171832	88430	X	X	PCL/PS	X	MJ-1109	PFU4		2	2		CNGK41916	MN	
Toshiba	E-3515AC	189093	116281	X	X	PCL/PS	X		PFU3		2	2		CNGJ61964	TX	
Toshiba	E-3515AC	205806	76792	X	X	PCL/PS	X		PFU3		2	2		CNHJ30047	TX	
Toshiba	E-3515AC	218874	92832	X	X	PCL/PS	X	MJ-1109B	PFU4		2	2		CNGK41935	MN	
Toshiba	E-3515AC	221176	54134	X	X	pcl/ps	X		Cab2		2	2		CNKJ47891	MN	
Toshiba	E-3515AC	233905	81858	X		PCL/PS	X		PFU3		2	2		CNHJ30070	TX	
Toshiba	E-3515AC	258210	53449	X	X	PCL/PS	X		Cab2		2	2		SNFL87746	TX	
Toshiba	E-3515AC	272586	163575	X	X	PCL/PS	X		PFU3		2	2		CNFJ58372	TX	
Toshiba	E-3515AC	346562	183337	X		PCL/PS	X		PFU3		2	2		CNHK51415	TX	
Toshiba	E-3515AC	425251	271002	X	X	PCL/PS	X		PFU3		2	2		CNGJ61951	TX	
Toshiba	E-3515AC	532208	277729	X	X	PCL/PS	X		PFU3		2	2		CNFJ58335	TX	
Toshiba	E-3515AC	685639	71464	X	X	PCL/PS	X		PFU3		2	2		CNFJ58491	TX	
Toshiba	E-3518A	392	0	X	X	PCL/PS	X		PFU3		2	2		CZEJ54670	TX	
Toshiba	E-3518A	3852	0	X	X	PCL/PS	X		PFU3		2	2		CZJL41199	MN	
Toshiba	E-3518A	6956	0	X		PCL/PS	X		PFU3		2	2		SCZGJ62624	TX	
Toshiba	E-3518A	13764	0	X	X	pcl/ps	X	Internal	PFU3		2	2		CZEM65120	MN	
Toshiba	E-3518A	14473	0	X	X	PCL/PS	X		PFU3		2	2		CZKH29521	TX	
Toshiba	E-3518A	56168	0	X		PCL/PS	X		PFU3		2	2		CZFJ59470	TX	
Toshiba	E-3518A	64512	0	X	X	PCL/PS	X		PFU3		2	2		CZGL28301	TX	
Toshiba	E-3518A	65841	0	X	X	PCL/PS	X		PFU3		2	2		CZGJ62504	TX	
Toshiba	E-3518A	66224	0	X	X	PCL/PS	X		PFU3		2	2		CZFJ59580	TX	

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Toshiba	E-3518A	82228	0	X		PCL/PS	X		PFU3		2	2		CZFK42076	TX
Toshiba	E-3518A	88619	0	X	X	PCL/PS	X		Cab2		2	2		CZHK47308	TX
Toshiba	E-3518A	98119	0	X	X	PCL/PS	X		PFU3		2	2		CZFK60824	TX
Toshiba	E-3518A	107612	0	X		PCL/PS	X		PFU3		2	2		CZGK45570	TX
Toshiba	E-3518A	111356	0	X	X	PCL/PS	X		PFU3		2	2		CZKH29516	TX
Toshiba	E-3518A	140912	0	X	X	PCL/PS	X		Cab2		2	2		CZHK47373	TX
Toshiba	E-3518A	143430	0	X	X	PCL/PS	X		PFU3		2	2		CZGJ62499	TX
Toshiba	E-3518A	165181	0	X	X	PCL/PS	X		PFU3		2	2		CZKH29523	TX
Toshiba	E-3518A	182310	0	X	X	PCL/PS	X		PFU3		2	2		CZGJ66335	MN
Toshiba	E-3518A	225233	0	X		PCL/PS	X		Cab2		2	2		CZCL14527	TX
Toshiba	E-3518A	240954	0	X		PCL/PS	X		PFU3		2	2		CZGJ62621	TX
Toshiba	E-3518A	324717	0	X		PCL/PS	X	MJ-1109-B	Cab2		2	2	dirty, toner ran out mid test.	CZJL41412	MN
Toshiba	E-3518A	335603	0	X		PCL/PS	X		PFU3		2	2		CZFK42080	TX
Toshiba	E-3518A	336935	0	X		pcl/ps	X		PFU3		2	2		CZCK35590	MN
Toshiba	E-3518A	393142	0	X		PCL/PS	X		PFU3		2	2		CZHK47310	TX
Toshiba	E-3518A	476707	0	X	X	PCL/PS	X		PFU3		2	2		CZCK35561	MN
Toshiba	E-3518A	488620	0	X	X	pcl/ps	X		PFU3		2	2		CZCK35609	MN
Toshiba	E-3518A	518587	0	X		PCL/PS	X		PFU3		2	2		CZCK35591	MN
Toshiba	E-3518A	528841	0	X		pcl/ps	X		Cab2		2	2		CZJL41684	MN
Toshiba	E-3518A	766162	0	X	X	PCL/PS	X		PFU3		2	2		CZCK35593	MN
Toshiba	E-4505AC	69840	54365	X	X	pcl/ps	X	MJ-1109	PFU3		2	2	MJ-6105N	CFEG67182	MN
Toshiba	E-4505AC	86741	39810	X	X	PCL/PS	X	Internal	PFU3		2	2		CFCG51435	MN
Toshiba	E-4505AC	134250	68769	X	X	PCL/PS	X		PFU3		2	2		CFKG63069	TX
Toshiba	E-4505AC	272563	137287	X	X	PCL/PS	X	MJ-1109	PFU3		2	2		CFJF64124	TX
Toshiba	E-4515AC	62071	24012	X	X	PCL/PS	X	Internal	PFU3		2	2		SNDL87280	MN
Toshiba	E-4515AC	69412	36572	X	X	PCL/PS	X		PFU3		2	2		CNGJ62284	TX
Toshiba	E-4515AC	76329	4551	X		PCL/PS	X		PFU3		2	2		CNGJ62243	TX
Toshiba	E-4515AC	79726	32879	X	X	pcl/ps	X	MJ-1109	PFU3		2	2		CNCK31457	MN
Toshiba	E-4515AC	94004	30256	X		PCL/PS	X		PFU3		2	2		CNCJ62257	TX
Toshiba	E-4515AC	95239	59969	X	X	PCL/PS	X	MJ-1110B	PFU3		2	2	MJ-6105N	CNAK64958	MN
Toshiba	E-4515AC	109828	46656	X	X	PCL/PS	X	Internal	PFU3		2	2		SNDL87265	MN
Toshiba	E-4515AC	110135	99177	X	X	PCL/PS	X	Internal	PFU3		2	2		CNEL60571	MN
Toshiba	E-4515AC	117792	20123	X	X	PCL/PS	X	Internal	PFU3		2	2		SNDL87165	MN
Toshiba	E-4515AC	130201	47152	X	X	PCL/PS	X		PFU3		2	2		CNGJ58727	TX
Toshiba	E-4515AC	138653	89386	X	X	pcl/ps	X	Internal	PFU3		2	2		CNEL59118	MN
Toshiba	E-4515AC	147082	71703	X		pcl/ps	X	Internal	PFU3		2	2		CNHL33096	MN
Toshiba	E-4515AC	179687	101625	X	X	PCL/PS	X	Internal	PFU3		2	2		CNHL33352	MN
Toshiba	E-4515AC	180606	61773	X	X	PCL/PS	X	MJ-1109	PFU3		2	2		CNHK51833	MN
Toshiba	E-4515AC	182335	83389	X		pcl/ps	X	MJ-1110	PFU3		2	2		CNIK58674	MN
Toshiba	E-4515AC	188300	25707	X	X	pcl/ps	X	MJ-1110	PFU3		2	2	MJ-6106N	CNLL59226	MN
Toshiba	E-4515AC	199741	134595	X	X	PCL/PS	X		PFU3		2	2		CNFJ58733	TX
Toshiba	E-4515AC	226329	9690	X	X	pcl/ps	X	MJ-1109	PFU3		2	2		CNCK31495	MN
Toshiba	E-4515AC	269532	27175	X		PCL/PS	X		PFU3		2	2		CNFJ58578	TX
Toshiba	E-4515AC	276330	112982	X	X	PCL/PS	X		PFU3		2	2		SNIK83486	TX
Toshiba	E-4515AC	378686	162705	X		PCL/PS	X		PFU3		2	2		CNFJ58599	TX
Toshiba	E-4515AC	421803	344252	X		PCL/PS	X		PFU3		2	2		CNGJ62356	TX
Toshiba	E-4515AC	441977	185052	X		pcl/ps	X		PFU4		2	2		CNGK45152	MN
Toshiba	E-4515AC	482813	215970	X	X	PCL/PS	X		Cab2		2	2		CNEL60532	TX
Toshiba	E-4515AC	525063	62446	X		PCL/PS	X		PFU3		2	2		CNFJ58707	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Toshiba	E-4518A	6227	0	X		PCL/PS	X		Cab2		2	2		CZKL46777	TX
Toshiba	E-4518A	9699	0	X		PCL/PS	X		PFU3		2	2		CZFL23554	MN
Toshiba	E-4518A	17838	0	X		PCL/PS	X		PFU3		2	2		CZAM56218	TX
Toshiba	E-4518A	28024	0	X	X	PCL/PS	X		PFU3		2	2		CZPJ61033	TX
Toshiba	E-4518A	32173	0	X		PCL/PS	X		PFU3		2	2		CZAM56252	TX
Toshiba	E-4518A	40728	0	X	X	PCL/PS	X		PFU3		2	2		CZPJ68077	TX
Toshiba	E-4518A	44555	0	X	X	PCL/PS	X		PFU3		2	2		CZGJ62782	TX
Toshiba	E-4518A	86643	0	X	X	PCL/PS	X	MJ-1109	PFU3		2	2		CZAL11331	MN
Toshiba	E-4518A	87048	0	X	X	PCL/PS	X		PFU3		2	2		CZPJ61041	TX
Toshiba	E-4518A	117972	0	X	X	PCL/PS	X		PFU3		2	2		CZPJ60982	TX
Toshiba	E-4518A	141885	0	X		PCL/PS	X		PFU3		2	2		CZPJ68064	TX
Toshiba	E-4518A	185975	0	X	X	PCL/PS	X		PFU3		2	2		CZGJ62892	TX
Toshiba	E-4518A	187809	0	X	X	PCL/PS	X		PFU3		2	2		CZPJ60974	TX
Toshiba	E-4518A	201939	0	X	X	PCL/PS	X		PFU3		2	2		CZPJ68068	TX
Toshiba	E-4518A	269875	0	X	X	PCL/PS	X		PFU3		2	2		CZPJ60986	TX
Toshiba	E-4518A	362458	0	X		pcl/ps	X	MJ-1109	PFU3		2	2		CZJL42154	MN
Toshiba	E-4518A	501834	0	X		PCL/PS	X		Cab2		2	2		CZKJ21470	MN
Toshiba	E-4518A	849677	0	X		PCL/PS	X		PFU3		2	2		CZAM56366	TX
Toshiba	E-4518A	1030557	0	X		PCL/PS	X		PFU3		2	2		CZAM56251	TX
Toshiba	E-4525AC	212992	208566	X	X	PCL/PS	X		PFU3		2	2		SSJM80649	TX
Toshiba	E-478s	38748	0	X	X	PCL/PS	X		PFU2		2	2		7018921304HZG	TX
Toshiba	E-478s	52772	0	X		PCL/PS	X		PFU1		2	2	grinding noise while printing	701811740D9ND	TX
Toshiba	E-478s	87428	0	X	X	PCL/PS	X		PFU1		2	2		701814540FBGX	TX
Toshiba	E-5005AC	290230	98396	X	X	pcl/ps	X		PFU3		2	2	Arrived without finisher	CFHF52992	MN
Toshiba	E-5015AC	143223	11060	X		PCL/PS	X		PFU3		2	2		CNFJ60672	TX
Toshiba	E-5015AC	254464	110943	X		PCL/PS	X		PFU3		2	2		CNHJ67771	TX
Toshiba	E-5015AC	258708	8784	X		PCL/PS	X		PFU3		2	2		CNFJ60670	TX
Toshiba	E-5015AC	467733	113564	X	X	PCL/PS	X		PFU3		2	2		CNHJ67764	TX
Toshiba	E-5015AC	681583	157602	X		PCL/PS	X		PFU3		2	2		CNHJ67796	TX
Toshiba	E-5018A	81219	0	X		PCL/PS	X		PFU3		2	2		CZCK35174	TX
Toshiba	E-5018A	82094	0	X		PCL/PS	X		Cab2		2	2		CZDL19511	TX
Toshiba	E-5018A	102741	0	X		PCL/PS	X		Cab2		2	2		CZCL15174	TX
Toshiba	E-5018A	104817	0	X		PCL/PS	X		Cab2		2	2		CZDL16481	TX
Toshiba	E-5018A	145842	0	X	X	PCL/PS	X		Cab2		2	2		CZCL15171	TX
Toshiba	E-5018A	183234	0	X		PCL/PS	X		Cab2		2	2		CZCL15179	TX
Toshiba	E-5018A	203834	0	X		PCL/PS	X		Cab2		2	2		CZDL16486	TX
Toshiba	E-5018A	254776	0	X		PCL/PS	X		Cab2		2	2	dirty	CZCL14626	TX
Toshiba	E-5018A	264455	0	X		PCL/PS	X		Cab2		2	2		CZDL19512	TX
Toshiba	E-5018A	318905	0	X		PCL/PS	X		Cab2		2	2		CZCL15186	TX
Toshiba	E-5018A	324894	0	X		PCL/PS	X		Cab2		2	2		CZCL15167	TX
Toshiba	E-5018A	363120	0	X		PCL/PS	X		Cab2		2	2		CZDL19540	TX
Toshiba	E-5018A	377252	0	X		PCL/PS	X		Cab2		2	2		CZCL15185	TX
Toshiba	E-5508A	957674	0	X	X	PCL/PS	X		PFU3		2	2	Unit did not arrive with a finisher.	CIHF11542	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Toshiba	E-5516AC	217741	133258	X	X	PCL/PS	X	MJ-1111-B	PFU4		2	2		C1DL29447	TX
Toshiba	E-5516AC	255343	129298	X	X	PCL/PS	X	MJ-1111B	PFU3		2	2		C1GL30839	MN
Toshiba	E-5516AC	269966	85597	X	X	pcl/ps	X	MJ-1111	PFU3		2	2	MJ-6106N	C1GL30802	MN
Toshiba	E-5516AC	273679	150963	X	X	PCL/PS	X	MJ-1111-B	PFU3		2	2		C1KK26551	TX
Toshiba	E-5518A	36280	0	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C2GJ18269	TX
Toshiba	E-5518A	55144	0	X	X	PCL/PS	X	MJ-1111-B	PFU3		2	2		C2GJ18285	TX
Toshiba	E-5518A	321019	0	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C2GJ18251	TX
Toshiba	E-5518A	564052	0	X	X	PCL/PS	X	MJ-1111-B	PFU3		2	2		C2GJ18258	TX
Toshiba	E-6516AC	173267	62260	X	X	PCL/PS	X	MJ-1111-B	PFU3		2	2		C1CL29218	MN
Toshiba	E-6516AC	227561	130730	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ16766	TX
Toshiba	E-6516AC	234540	30474	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1FJ16132	TX
Toshiba	E-6516AC	235504	134851	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ17131	TX
Toshiba	E-6516AC	257322	147713	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ16750	TX
Toshiba	E-6516AC	277810	189104	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ17129	TX
Toshiba	E-6516AC	400895	157259	X	X	PCL/PS	X	MJ-1111-B	PFU3		2	2		C1HJ17503	TX
Toshiba	E-6516AC	462009	97061	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ17124	TX
Toshiba	E-6516AC	600328	282953	X	X	PCL/PS	X	MJ-1111-B	PFU3		2	2		C1GJ16733	TX
Toshiba	E-6516AC	648568	127147	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ17111	TX
Toshiba	E-6516AC	656139	221100	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ17130	TX
Toshiba	E-6516AC	671072	73404	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ16769	TX
Toshiba	E-6516AC	686610	312738	X		PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ16771	TX
Toshiba	E-6516AC	845699	110486	X		pcl/ps	X	MJ-1111	PFU4		2	2	MJ-6106N	C1DJ15138	MN
Toshiba	E-6516AC	1072867	517220	X	X	PCL/PS	X	MJ-1111	PFU3		2	2		C1GJ16746	TX
Toshiba	E-8518A	572952	0	X		PCL/PS	X		PFU3		2	2		C2CL30690	TX
Toshiba	E-8518A	1248793	0	X		PCL/PS	X	MJ-1111	PFU3		2	2		C2JL35299	TX
Xerox	AL B8045	125111	0	X	X	PCL/PS	X	BFO-1	PFU4		2	2		Y4X932532	TX
Xerox	AL B8045	162543	0	X		PCL/PS	X		PFU4		2	2		Y4X931986	TX
Xerox	AL B8045	204195	0	X		PCL/PS	X	BFO-1	PFU4		2	2		Y4X932119	TX
Xerox	AL B8045	230810	0	X		PCL/PS	X	BFO-1	PFU4		2	2		Y4X933144	TX
Xerox	AL B8055	346632	0	X	X	PCL/PS	X		PFU4		2	2		YAX837285	TX
Xerox	AL B8065	512709	0	X		PCL/PS	X	BFO-1	PFU4		2	2		3AG878910	TX
Xerox	AL B8145	114729	0	X		PCL/PS	X	A-FN21	PFU4		2	2		HQH272772	TX
Xerox	AL B8145	214550	0	X		PCL/PS	X	A-FN21	PFU4		2	2		HQH272605	TX
Xerox	AL B8145	313753	0	X	X	PCL/PS	X		PFU4		2	2		HQH276881	TX
Xerox	AL B8145	328999	0	X		PCL/PS	X	A-FN21	PFU4		2	2		HQH272779	TX
Xerox	AL B8145	449341	0	X		PCL/PS	X		PFU4		2	2		HQH272757	TX
Xerox	AL B8155	284251	0	X		PCL/PS	X		PFU4		2	2	Unit does not have a finisher.	HQH266430	TX
Xerox	AL C8030	383078	194065	X	X	pcl/ps	X	A-FN21	PFU4		2	2		2TX062920	MN
Xerox	AL C8035	102033	50711	X		PCL/PS	X	HFN-2	PFU4		2	2	Yellowing	2TX052395	MN
Xerox	AL C8035	114133	86851	X		PCL/PS	X	HFN-2	PFU4		2	2		2TX347329	TX
Xerox	AL C8035	167604	72240	X	X	PCL/PS	X	HFN-2	PFU4		2	2		3TX423752	MN
Xerox	AL C8035	294784	101443	X		PCL/PS	X		PFU4		2	2		2TX066382	MN

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

EC=External Condition
IC=Internal Condition

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Xerox	AL C8035	337823	243868	X	X	PCL/PS	X		PFU4		2	2		2TX064508	MN
Xerox	AL C8045	59834	25032	X	X	PCL/PS	X	HFN-2	PFU4		2	2	Dirty	8TB594950	MN
Xerox	AL C8045	64930	48741	X	X	PCL/PS	X	HFN-2	PFU4		2	2	Dirty	8TB595060	MN
Xerox	AL C8045	103795	62001	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB594870	MN
Xerox	AL C8045	167846	127434	X	X	PCL/PS	X	HFN-2	PFU4		2	2	Dirty, yellowing on front of machine	8TB594719	MN
Xerox	AL C8045	170048	18626	X	X	PCL/PS	X	HFN-2	PFU4		2	2	copy and some other settings are accounting password blocked	8TB644101	TX
Xerox	AL C8045	174807	43523	X	X	PCL/PS	X	A-FN07	PFU4		2	2		8TB649970	TX
Xerox	AL C8045	187134	130548	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB595065	MN
Xerox	AL C8045	217877	132066	X	X	PCL/PS	X		PFU4		2	2		8TB646486	TX
Xerox	AL C8045	231027	119791	X		pcl/ps	X		PFU4		2	2		8TB654114	MN
Xerox	AL C8045	236379	1725	X	X	PCL/PS	X		PFU4		2	2		8TB637022	TX
Xerox	AL C8045	249056	101156	X	X	pcl/ps	X		PFU4		2	2		8TB648647	MN
Xerox	AL C8045	259159	97095	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB649523	TX
Xerox	AL C8045	346814	124	X	X	PCL/PS	X		PFU4		2	2		8TB640775	TX
Xerox	AL C8045	358759	163232	X	X	pcl/ps	X		PFU4		2	2		8TB566659	MN
Xerox	AL C8045	376019	215001	X	X	PCL/PS	X	HFN-2	PFU4		2	2	Yellowing on front of machine	8TB595064	MN
Xerox	AL C8045	395784	239682	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB594496	MN
Xerox	AL C8045	420278	245412	X		PCL/PS	X		PFU4		2	2		8TB646708	TX
Xerox	AL C8045	470972	277721	X	X	PCL/PS	X		PFU4		2	2	Yellowing on front of machine	8TB594873	MN
Xerox	AL C8045	471112	227426	X		PCL/PS	X		PFU4		2	2	Dirty, yellowing	8TB594481	MN
Xerox	AL C8055	37656	18342	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB646897	MN
Xerox	AL C8055	49439	29041	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB636350	MN
Xerox	AL C8055	51797	37700	X		PCL/PS	X	HFN-2	PFU4		2	2		8TB620449	TX
Xerox	AL C8055	333819	215388	X		PCL/PS	X	HFN-2	PFU4		2	2		8TB647422	TX
Xerox	AL C8055	371665	174927	X	X	PCL/PS	X	HFN-2	PFU4		2	2		8TB615202	MN
Xerox	AL C8055	531282	274408	X	X	HFN-2	X	PCL/PS	PFU4		2	2		8TB626385	MN
Xerox	AL C8070	258961	213316	X		PCL/PS	X		PFU4		2	2		6TB455880	TX
Xerox	AL C8070	420134	287998	X		PCL/PS	X	A-FN07	PFU4		2	2	Yellowing	6TB445851	MN
Xerox	AL C8130	77484	28309	X		PCL/PS	X		PFU4		2	2		ELQ510282	TX
Xerox	AL C8130	202482	59774	X		PCL/PS	X	A-FN07	PFU4		2	2		ELQ518832	TX
Xerox	AL C8135	92620	44156	X	X	PCL/PS	X	A-FN21	PFU4		2	2	Dirty	EKZ339273	MN
Xerox	AL C8135	96800	55253	X		PCL/PS	X	A-FN21	PFU4		2	2		ELQ509871	MN
Xerox	AL C8135	104319	83790	X		PCL/PS	X		PFU4		2	2		ELQ517073	TX
Xerox	AL C8135	116696	85922	X		PCL/PS	X	A-FN21	PFU4		2	2		ELQ510437	MN
Xerox	AL C8135	195220	102301	X		PCL/PS	X	A-FN21	PFU4		2	2		ELQ510619	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Xerox	AL C8135	215327	96237	X	X	PCL/PS	X	A-FN07	PFU4		2	2		EKZ341359	MN
Xerox	AL C8135	229101	25833	X	X	PCL/PS	X		PFU4		2	2	missing cyan toner cartridge	ELQ510450	TX
Xerox	AL C8145	71772	51003	X		PCL/PS	X	A-FN21	PFU4		2	2		EHQ214343	MN
Xerox	AL C8145	122970	17064	X		PCL/PS	X		PFU4		2	2		EHQ234973	MN
Xerox	AL C8155	492090	284396	X		PCL/PS	X	A-FN21	PFU4		2	2		EHQ209558	MN
Xerox	AL C8170	160402	89619	X	X	PCL/PS	X	A-FN07	PFU4		2	2		EFQ269304	TX
Xerox	AL C8170	334545	193737	X		PCL/PS	X		PFU4		2	2	Unit did not arrive with finisher	EFQ644344	TX
Xerox	Color C60	268889	151036	X	X	PCL/PS	X	Exit Tray	PFU4		2	2	Blue ADF	E2B668204	MN
Xerox	ColorC70	235785	156915	X		PCL/PS	X	A-FN07	PFU3		2	2	FIERY E300-07	E2B663171	TX
Xerox	D125	8382569	0	X		PCL/PS	X	LFN-1	PFU4	RCF-1	2	2	Blue ADF	BG0975712	MN
Xerox	D95	3738409	0	X		pcl/ps	X		PFU4		2	2	Arrived without finisher and LCT. Tested with another machines attachment s.	BG2941137	MN
Xerox	D95A Pro PrimeLink	675009	0	X		pcl/ps	X	LFN-2	PFU4		2	2		BG2484184	MN
Xerox	B9125	1748059	0	X		RCF-1	X	A-FN13	PFU4		2	2	A-GW07	ECQ670331	MN
Xerox	VL B400	868	0			PCL/PS			PFU1		2	2		6HB032193	TX
Xerox	VL B400	969	0			pcl/ps			PFU2		2	2		6HB032995	MN
Xerox	VL B400	2093	0			PCL/PS			PFU1		2	2		6HB032279	TX
Xerox	VL B400	4385	0			PCL/PS			PFU1		2	2		6HB032285	TX
Xerox	VL B400	8910	0			pcl/ps			PFU1		2	2		6HB839886	MN
Xerox	VL B400	15932	0			PCL/PS			PFU1		2	2	Very Dirty	6HB054565	MN
Xerox	VL B400	23773	0			pcl/ps			PFU1		2	2	Dirty	6HB033658	MN
Xerox	VL B400	30213	0			pcl/ps			PFU1		2	2		6HB032159	MN
Xerox	VL B400	107302	0			PCL/PS			PFU1		2	2	Very Dirty	6HB032798	MN
Xerox	VL B405	1961	0	X		PCL/PS	X		Cab1		2	2		9HB185811	TX
Xerox	VL B405	3154	0	X		PCL/PS	X		PFU2		2	2		9HB925797	TX
Xerox	VL B405	3912	0	X		PCL/PS	X		PFU1		2	2		9HB921027	TX
Xerox	VL B405	6302	0	X		PCL/PS	X		PFU2		2	2		9HB921367	TX
Xerox	VL B405	6338	0	X		PCL/PS	X		PFU1		2	2		9HB925905	TX
Xerox	VL B405	14832	0	X		PCL/PS	X		PFU1		2	2		9HB464521	TX
Xerox	VL B405	15780	0	X	X	PCL/PS	X		PFU1		2	2		9HB921016	TX
Xerox	VL B405	17557	0	X	X	PCL/PS	X		PFU1		2	2		9HB185810	TX
Xerox	VL B405	23183	0	X		PCL/PS	X		PFU1		2	2		9HB378213	TX
Xerox	VL B405	29373	0	X	X	pcl/ps	X		PFU2		2	2	Dirty and yellowed.	9HB357438	MN
Xerox	VL B405	29705	0	X	X	pcl/ps	X		PFU1		2	2		9HB967174	MN
Xerox	VL B405	38765	0	X	X	PCL/PS	X		PFU1		2	2		9HB925118	TX

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Xerox	VL B405	43720	0	X		PCL/PS	X		PFU1		2	2		9HB921024	TX
Xerox	VL B405	47180	0	X	X	PCL/PS	X		Cab1		2	2		9HB931507	TX
Xerox	VL B405	92854	0	X	X	PCL/PS	X		PFU1		2	2	Dirty	9HB357451	MN
Xerox	VL B605	274027	0	X	X	PCL/PS	X		Cab2		2	2		5XB055612	MN
Xerox	VL B7025	40724	0	X	X	PCL/PS	X	A-FN21	PFU4		2	2		5DA859777	TX
Xerox	VL B7025	83858	0	X		PCL/PS	X		PFU4		2	2		5DA840486	TX
Xerox	VL B7030	376873	0	X		PCL	X		PFU4		2	2		5DA856271	MN
Xerox	VL B7035	11551	0	X		PCL/PS	X	HFN-2	PFU4		2	2		5DA854175	MN
Xerox	VL B7035	19078	0	X		PCL/PS	X	HFN-2	PFU4		2	2		5DA855792	MN
Xerox	VL B7035	38135	0	X		PCL/PS	X	HFN2	PFU4		2	2		5DA854183	MN
Xerox	VL B7035	52027	0	X	X	pcl/ps	X	HFN-2	PFU4		2	2		5DA854103	MN
Xerox	VL B7035	72445	0	X	X	pcl/ps	X	HFN-2	PFU4		2	2		5DA854595	MN
Xerox	VL B7035	270062	0	X	X	PCL/PS	X	Internal	PFU4		2	2		5DA081091	MN
Xerox	VL C400	11550	7490			PCL/PS			PFU1		2	2		7HB041802	TX
Xerox	VL C400	18413	10238			PCL/PS			PFU1		2	2		7HB776540	MN
Xerox	VL C400	23010	16203			PCL/PS			PFU1		2	2		7HB041800	TX
Xerox	VL C400	46642	28113			PCL/PS			PFU1		2	2		7HB774865	MN
Xerox	VL C405	3160	1168	X		PCL/PS	X		PFU1		2	2		4HX982609	TX
Xerox	VL C405	6186	1722	X		PCL/PS	X		PFU2		2	2		4HX982626	TX
Xerox	VL C405	16199	6080	X	X	PCL/PS	X		PFU1		2	2		4HX564851	TX
Xerox	VL C405	29275	25323	X	X	PCL/PS	X		PFU1		2	2		4HX957732	TX
Xerox	VL C405	30734	23043	X	X	pcl/ps	X		PFU1		2	2		4HX801825	MN
Xerox	VL C405	34779	31059	X	X	PCL/PS	X		PFU1		2	2		4HX957835	TX
Xerox	VL C405	45787	41655	X	X	PCL/PS	X		PFU1		2	2		4HX957833	TX
Xerox	VL C405	47129	34745	X	X	PCL/PS	X		PFU1		2	2		4HX973146	MN
Xerox	VL C405	52841	34428	X	X	PCL/PS	X		PFU1		2	2		4HX957620	TX
Xerox	VL C405	65571	60425	X		PCL/PS	X		PFU1		2	2		4HX959110	TX
Xerox	VL C405	126325	109805	X	X	PCL/PS	X		PFU1		2	2		4HX957729	TX
Xerox	VL C405	126569	12107	X	X	PCL/PS	X		PFU1		2	2		4HX807556	MN
Xerox	VL C500	33783	18793	X		PCL/PS	X		PFU1		2	2		7RA600519	TX
Xerox	VL C505	54807	1643	X	X	PCL/PS	X		PFU1		2	2		3RB730892	MN
Xerox	VL C7025	43492	15383	X	X	PCL/PS	X		PFU1		2	2	No cabinet, machine is on a pallet	7TX355265N	MN
Xerox	VL C7025	57003	39806	X		PCL/PS	X		PFU4		2	2	Reorder magenta toner, reorder cyan toner	3UA284372	TX
Xerox	VL C7025	121084	15997	X	X	PCL	X		PFU4		2	2		3UA291864	MN
Xerox	VL C7030	8773	2775	X		PCL/PS	X		PFU4		2	2		3UA295063	TX
Xerox	VL C7030	38249	21301	X		PCL/PS	X	Internal	PFU4		2	2		3UA291345	MN
Xerox	VL C7030	106854	39290	X		PCL/PS	X	Internal	PFU4		2	2		3UA225749	MN
Xerox	VL C8000	28950	11710			PCL/PS			PFU2		2	2	Dirty	2YX043100	MN
Xerox	WC5330	49225	0	X		PCL/PS	X		PFU4		2	2		AE9874583	TX
Xerox	WC5945	138070	0	X	X	pcl/ps	X	BFO-1	PFU4		2	2		A2M635397	MN
Xerox	WC6515	3162	993	X	X	PCL/PS	X		PFU1		2	2		5AV103546	MN
Xerox	WC7835	773617	194472	X	X	PCL/PS	X		PFU4		2	2		MX0146925	MN
Xerox	WC7855i	268530	208467	X	X	PCL/PS	X	HFN-2	PFU4		2	2		MX4481342A	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480



Please Contact Your Sales Rep Today!!
866.848.4900

5/21/2025

Zebra	ZD421	0								2	2		D8J210200291	MN
Zebra	ZD421	0								2	2		D8J210200330	MN
Zebra	ZD421	0								2	2		D8J210200364	MN
Zebra	ZD421	0								2	2		D8J210200375	MN
Zebra	ZD421	0								2	2		D8J210200377	MN
Zebra	ZD421	0								2	2		D8J210200381	MN
Zebra	ZD421	0								2	2		D8J210200422	MN
Zebra	ZD421	0								2	2		D8J212002210	MN
Zebra	ZD421	0								2	2		D8J212002229	MN
Zebra	ZD421	0								2	2		D8J212002235	MN
Zebra	ZD421	0								2	2		D8J212002238	MN
Zebra	ZD421	0								2	2		D8J212002240	MN
Zebra	ZD421	0								2	2		D8J212002242	MN
Zebra	ZD421	0								2	2		D8J212002247	MN
Zebra	ZD421	0								2	2		D8J212002250	MN
Zebra	ZD421	0								2	2		D8J212002252	MN
Zebra	ZD421	0								2	2		D8J212002255	MN
Zebra	ZD421	0								2	2		D8J212002258	MN
Zebra	ZD421	0								2	2		D8J212002274	MN
Zebra	ZD421	0								2	2		D8J212002275	MN
Zebra	ZT411	0								2	2		99J203903661	MN
Zebra	ZT411	0								2	2		99J203903663	MN
Zebra	ZT411	0								2	2		99J210100026	MN
Zebra	ZT411	0								2	2		99J210100040	MN
Zebra	ZT411	0								2	2		99J210100054	MN
Zebra	ZT411	0								2	2		99J210204251	MN
Zebra	ZT411	0								2	2		99J210204256	MN
Zebra	ZT411	0								2	2		99J210204257	MN
Zebra	ZT411	0								2	2		99J210204259	MN
Zebra	ZT411	0								2	2		99J210204261	MN
Zebra	ZT411	0								2	2		99J210204262	MN
Zebra	ZT411	0								2	2		99J210204263	MN
Zebra	ZT411	0								2	2		99J210204267	MN
Zebra	ZT411	0								2	2		99J210204269	MN
Zebra	ZT411	0								2	2		99J210204271	MN
Zebra	ZT411	0								2	2		99J210500262	MN
Zebra	ZT411	0								2	2		99J210500266	MN
Zebra	ZT411	0								2	2		99J210500278	MN
Zebra	ZT411	0								2	2		99J210500279	MN
Zebra	ZT411	0								2	2		99J210500280	MN
Zebra	ZT411	0								2	2		99J210500283	MN
Zebra	ZT411	0								2	2		99J210500284	MN
Zebra	ZT411	0								2	2		99J211204696	MN
Zebra	ZT411	0								2	2		99N220801762	MN
Zebra	ZT411	0								2	2		99N220801766	MN
Zebra	ZT411	0								2	2		99N220900250	MN

EC=External Condition
IC=Internal Condition

Highlighting Key
Green=Located in Texas
Yellow=New this Week!

John A 320.732.7484
Rick B 320.732.7480